	Submit 1 Copy To Appropriate District Office	ffice state of New Mexico Intrict I – (575) 393-6161 Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 11 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103	
	District I – (575) 393-6161 1625 N French Dr., Hobbs, NM 88240			Revised August 1, 2011 WELL API NO.	
	<u>District II</u> – (575) 748-1283 HOBBS OC 811 S. First St. Artesia NM 88210			30-025-39945 /	
	Destruct III (505) 224 6179			5. Indicate Type of Lease STATE FEE	
	District IV – (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. VO-7641	
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name NLA State Unit	
	PROPOSALS.) 1. Type of Well: Oil Well				7
	2. Name of Operator OGX Resources, LLC			9. OGRID Number 217955	
	3. Address of Operator PO Box 2064 Midland, TX 79702			10. Pool name or Wildcat	
	4. Well Location			South Flying M Abo Pool	
		M : 480 feet from the South line and 530 feet from the West			line
	Section 18 Township 9S Range 33E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4404' GR					
	12. Check App	ropriate Box to Indicate Na	to Indicate Nature of Notice, Report or Other Data		
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
		LUG AND ABANDON 💆	REMEDIAL WORK		ING 🗌
	TEMPORARILY ABANDON				
	DOWNHOLE COMMINGLE	OLTIPLE COIVIPL	CASING/CEMENT	JOB []	
	OTHER:		OTUED.		r
	OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:				
	of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
	proposed completion or recompletion. 13-3/8" csg set at 368' - cmt circ. 9-5/8" csg set at 3,166' - cmt cir. 7" csg set at				
	8,146' cmt cir. TOC 3,700' 4-1/2" liner set at 7,760' - 12,298' Set CIBP @ 1,760' and cap */-50' of cement. WOC and Tag. (4/2 Liver Top # 7"Shoe) Cmt. from 5,017'- 5,117' (Glorieta @ 5,067')				
	Set CIBP @ 7,760' and	cap $\frac{w}{50}$ of cement.	cement. WOC and Tag. (41/2 Liver Top \$ 7"cha)		
	Gut Carr 2 5051 2 6051 (G. 2. 1				
Ocal	Cmt. from 3,595' - 3,6	95' (San Andres @ 3,6)	45) a plug at 3 16	(1) Tar 3/16	
2216	Cmt from 2,564' - 2,66	<u></u>			
5 —	Cmt from 2,372' - 2,472' (Yates @ 2,422') Cmt from 318 - 418. WOC and Tag (Shoe plug at 368')				
	Cmt 60' to surface.				
	Cut off wellhead and anchors. Install dry hole marker.				
	Spud Date:	Rig Release Da	The Oil Conse	ervation Division Must be notifi	ed
	Rig Release Day 24 hours prior to the beginning of plugging operations.				
	I hereby certify that the information above is true and complete to the heat of my linearly 11.11.5				
	hereby certify that the information above is true and complete to the best of my knowledge and belief.				
	SIGNATURE Ammo Matter TITLE Regulatory Clerk DATE 09/26/2011				
	Type or print name Donna Stratton E-mail address: donna@rkford.com PHONE: 432-682-0440				
	From State Use Only				
	APPROVED BY Jonnal TITLE STANT MAKE DATE 10-24-2011				
	Conditions of Approval (if any):	THE T	· 10 0 10 000	DATE 1010	<u> </u>

€,

