

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr, Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St, Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd, Aztec, NM 87410
District IV - (505) 476-3460
1220 S St Francis Dr, Santa Fe, NM 87505

HOBBS OGD

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OCT 24 2011

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

RECEIVED

91 7108 2133 3939 3782 5550

WELL API NO. 30-025-38878
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VA 2905
7. Lease Name or Unit Agreement Name Saunders 33 State
8. Well Number 1
9. OGRID Number 151323
10. Pool name or Wildcat Saunders, Permo Upper Penn
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,218' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Pride Energy Company	
3. Address of Operator P.O. Box 701950, Tulsa, OK 74170-1950	
4. Well Location Unit Letter L : 1980 feet from the South line and 660 feet from the West line Section 33 Township 14S Range 33E NMPM Lea County	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Called and gave 24-hour notice to NMOCD.
2. Filled the 17.5" conductor pipe with cement, per NMOCD rep.
3. Cut off conductor pipe below ground level and welded on plate and dry hole marker.
4. Restored location by cleaning and leveling.
(Maxey Brown with NMOCD witnessed the job.)

P/A'd 10/20/2011

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE John W. Pride TITLE President of Pride Oil & Gas Co., Inc. as General Partner of Pride Energy Co. DATE 10/21/11

Type or print name John W. Pride E-mail address: johnp@pride-energy.com PHONE: 918-524-9200

For State Use Only

APPROVED BY [Signature] TITLE Staff MGR DATE 10-25-2011

Conditions of Approval (if any):

jp4807.sk OCT 25 2011