Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103 May 27,/2004
District 1 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resour	WELL API NO.
District II 1301 W. Grand Ave. Artesia, NM 8900	BS OCOL CONSERVATION DIVISIO	N 30-025-05814
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE STATE
1000 RIO Brazos Rd., Aztec, NM 87410 District IV	2 4 2011 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr , Santa Fe, NM 87505		
SUNDRY NOT	CESVED REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO CATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		9. OGRID Number
Apache Corporation /		873
3. Address of Operator 303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705		10. Pool name or Wildcat Eunice Monument:G/SA
4. Well Location		Eunice Wonument O/SA
Unit Letter P : 33	30 feet from the S line and 988	feet from the E line
Section 34 Townsh		
	11. Elevation (Show whether DR, RKB, RT, C	GR, etc.)
Pit or Below-grade Tank Application 🗌 o		
Pit type Depth to Groundwa		Distance from nearest surface waterN/A
Pit Liner Thickness: mil		Construction Material
12. Check A	Appropriate Box to Indicate Nature of N	lotice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PANDA		
PULL OR ALTER CASING I MULTIPLE COMPL CASING/CEMENT JOB		
OTHER: drill out & add Plugs		
		tails, and give pertinent dates, including estimated date
of starting any proposed we or recompletion.	rk). SEE RULE 1103. For Multiple Completion	ons: Attach wellbore diagram of proposed completion
•	¹ / ₂ " CIBP @ 3630'. Mix mlf & circ hole w/8	from
10/12/11 MIRU. Tag existing 5	$\frac{1}{2}$ " CIBP (a) 3630'. Mix mlf & circ hole w/8	8 bbls. Spot 40 sxs form 3630'. Woc.
	Perf @ 2675'. Pressure tested to 2000 psi.	
From 2725'. Spot 40 s	sxs cmt from 2725'. Tag @ 2342'. Perf 1475	'. Sqz 60 sxs cmt. Woc.
	'. Perf @ 371'. Did not circ so contact OCD	Advised to sqz 60 sxs. Woc & perf
	displace to 100'. Woc & tag cmt plug @ 90'	
	f. Cut off well head. Install dry hole marke .chors & Cleven locati	
	Chois + Clean IVIA II	in,
I hereby certify that the information	above is true and complete to the best of my kn	owledge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or	closed according to NMOCD guidelines 🖾, a general p	ermit [] or an (attached) alternative OCD-approved plan [].
SIGNATURE	TITLE P & A Supervisor	(Basic Energy Services) DATE 10/18/11
		(Dasie Energy Services) DATE <u>10/18/11</u>
Type or print name: Gary Egglest	ton E-mail address:	Telephone No. 432-563-3355
<u>For state Use Only</u>		
APPROVED BY:	TITLE Jyay	DATE DATE 0-15-CO 11
Conditions of Approval (if any): Approved for plugging of well bore only.		
	Lightlity under bond	is retained pending receipt t Report of Well Plugging)
	which may be found -	at OCD Web Page under
	Forms, www.cmnrd.s	tate.nm.us/ocd.
		OCT 2 5 201.