## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE		L CONSERVATION DIVISION			Reviseu 3-21-2004			
DISTRICT I 1625 N French Dr , Hobbs, NM 88240	HOBBS OCD	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL AP	WELL API NO 30-025-36193			
DISTRICT II	OCT 28 2011	•		5 Indicate	e Type of Lease		_	
1301 W Grand Ave, Artesia, NM 88210	331 23 -				STATE X	FEE		
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	mpari ipri			6 State O	nl & Gas Lease No			
1000 Rio Brazos Rd, Aztec, NM 87410 RECEIVED  SUNDRY NOTICES AND REPORTS ON WELLS					Name or Unit Agreer	nent Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					North Hobbs (G/SA) Unit			
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals )					24			
1 Type of Well					o 549			
Oil Well X	Gas Well	Other		9. OGRID	No. 157004			
2 Name of Operator Occidental Permian Ltd.				9. OGRIL	No 157984			
3 Address of Operator					name or Wildcat	Hobbs (G/S	A)	
HCR 1 Box 90 Denver City,	ΓX 79323							
4 Well Location							_	
Unit Letter I 1802	Feet From The	South	815	Feet From The	East	_ Line		
Section 24	Township	18-S	Range	37-E	NMPM	Lea Cou	nty	
	11 Elevation (She 3656' GL	ow whether DF, R	KB, RT GR, etc )					
Pit or Below-grade Tank Application	or Closure							
Pit Type Depth of Gro			nearest fresh water wel	Distar	nce from nearest si	urface water		
Pit Liner Thickness mil			bbls; Construc					
	eck Appropriate Box ITENTION TO:	to Indicate N	ature of Notice, Repo	ort, or Other Data SUBSEQUEN		F.		
PERFORM REMEDIAL WORK	PLUG AND ABAN	IDON	REMEDIAL WORK		ALTERING	G CASING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILL	NG OPNS.	PLUG & A	ABANDONMENT		
PULL OR ALTER CASING	Multiple Completion	on	CASING TEST AND	CEMENT JOB				
OTHER. Plug back/Sqz perfs/Re	eturn to producer	X	OTHER					
13. Describe Proposed or Completed		to all nortinent of	lotails, and give norting	nt datas including	astimated data of	storting ony		
proposed work) SEE RULE 110	3. For Multiple Compl	etions: Attach	wellbore diagram of pro Notice of Intent filed (	posed completion	or recompletion.	starting any		
1. Kill well.	• •			N <sub>1</sub> H				
<ul><li>2. Plug back w/pea gravel to 4160'</li><li>3. RIH w/CICR and squeeze perfs</li></ul>		tions	,			• •,		
4. Drill out squeeze to PBTD @43		uons.				i di		
5. Run back in hole w/ESP and equ			n	2 1 1		, ,		
6. Return well to production.						**		
						مراسلامید - حرابلامید		
				7		*		
				*- •		· • •		
I hereby certify that the information above	is true and complete to th	ue heet of my know	yledge and helief. I furtha				·	
constructed or	is true and complete to th	ie best of my know	—		·			
closed according to NMOCD guideling	nes , a genera	ıl permit	or an (attached) al	ternative OCD-appr	roved			
SIGNATURE MIND	w a out	THE THE PERIOD OF THE PERIOD O	plan TITLE Adminis	strative Associate	L DAT	J E 10/27/201	11	
TYPE OR PRINT NAME Mendy A	Johnson E-	mail address:	mendy johnson@o	xy.com	TELEPHONE NO	806-592-62	280	
			menay joinsonase					
For State Use Only								
				of we	DA DA	TE 10-3.	1-70	