

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-33306
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Phillips, J.R.
8. Well Number 13
9. OGRID Number
10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Chevron USA Inc

3. Address of Operator
15 Smith Rd, Midland, TX 79705

4. Well Location
Unit Letter E : 1700 feet from the North line and 940 feet from the East line
Section 6 Township 20-S Range 37-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL E Sect 6 Twp 20S Rng 37E Pit type Steel Depth to Groundwater 87 Distance from nearest fresh water well Over 1000'
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
1700 feet from the North line and 940 feet from the East line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hrs prior to MI and RU.
2. RIH Tag CIBP @2990, Spot 25sx plug 2990-2800 (Eumont, 7 RVRS Queen) WOC Tag 2817.
3. Displace hole w/MLF, 9.5# Brine w/12.5 # gel P/BBL.
4. Spot 25sx, plug 2400-2200 (B-Salt).
5. Spot 30sx, plug 1200 -1000 (8 5/8 Shoe, T-Salt) WOC Tag 990.
6. Spot 30sx Plug 300-Surf (Surf) WOC Tag @ Surf.
7. Install dry hole marker 4-05-05

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Jimmy Bagley TITLE Consultant DATE 4/05/05

Type or print name Jimmy Bagley E-mail address: Telephone No. 432-561-8600

(This space for State use)

APPROVED BY Sheryl W. Wink TITLE OCD FIELD REPRESENTATIVE II/STAFF MANAGER DATE APR 11 2005
Conditions of approval, if any

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.