

Submit 1 Copy to Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

HOBBS OCD

OIL CONSERVATION DIVISION

NOV 18 2011

1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-31000
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-332
7. Lease Name or Unit Agreement Name SUNRAY -A-6822 LTD
8. Well Number 001
9. OGRID Number 006550
10. Pool name or Wildcat LANE; SAN ANDRES (37000)
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
DWIGHT A. TIPTON

3. Address of Operator  
c/o Oil Reports & Gas Services, Inc. 1008 W. BROADWAY, HOBBS, NM 88240

4. Well Location

Unit Letter O : 990 feet from the SOUTH line and 1980 feet from the EAST line  
Section 36 Township 09S Range 33E NMPM LEA County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

REQUEST TO TEMPORARILY ABANDON DUE TO THE CEASING OF PRODUCTION.

Condition of Approval: Notify OCD Hobbs  
office 24 hours prior to running MIT Test & Chart

Rule 19.15.25.14

Set CIBP, RBP or Packer within 100 feet of uppermost  
perfs. or open hole Pressure test to 500 psi for 30 minutes with  
a pressure drop of not greater than 10% over a  
30 minute period

Release Date:

The Oil Conservation Division

**MUST BE NOTIFIED 24 Hours**

**Prior to the beginning of operations**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Gaye Heard TITLE AGENT DATE 11/16/11

Type or print name GAYE HEARD E-mail address: gheard@oilreportsinc.com PHONE: 575-393-2727

For State Use Only

APPROVED BY: [Signature] TITLE STAFF MGR DATE 11-21-2011

Conditions of Approval (if any):

NOV 21 2011