

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

HOBBS OCD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

NOV 18 2011

RECEIVED

WELL API NO.

30-041-20946

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Lillie Belle

8. Well Number

1

9. OGRID Number

001092

10. Pool name or Wildcat

Wildcat: Fusselman

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other Dry Hole ☐

2. Name of Operator

Armstrong Energy Corporation

3. Address of Operator

P.O. Box 1973, Roswell, NM 88202-1973

4. Well Location

Unit Letter H : 2167' feet from the North line and 990 feet from the East line
Section 29 Township 5S Range 34E NMPM Roosevelt County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☒
CASING/CEMENT JOB ☐OTHER: ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11-01-11 - Set CIBP @ 7375', Dump 35' of cement on top of plug. Cut casing at 6300'.

11-02-11 - Spot 70 sx cmt plug @ 6335'

11-03-11 - Tagged plug @ 6200'. TIH to 4630', spot 100 sx plug, POH and LD 52 jts to 2456', spot 125 sx across 8-5/8" shoe joint.

11-04-11 - Tagged plug @ 2381', spotted 35 sx. TIH and tagged @ 2223'. POH to 1900', spotted 35 sx. POH to 450', spotted 35 sx. POH to 60', spotted 35 sx to Surface. POH, cut off well head, install Dry Hole Marker, cut off anchors. RD.

11-07-11 - Move frac tank off location, fill in cellar, cleaned location and smoothed surface. Spread out top soil.
Finished except for reseeding in the SpringApproved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emnrd.state.nm.us/oed.

Spud Date:

7-19-2011

Rig Release Date:

8-16-11

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Vice President

DATE

11-16-11

Type or print name

Bruce A. Stubbs

E-mail address:

bastubbs@armstrongenergycorp.com

PHONE:

575-625-2222

For State Use Only

APPROVED BY:

TITLE

STAFF MGR

DATE

11-21-2011

Conditions of Approval (if any):

NOV 21 2011