		-
	To Appropriate District Office State of New Mexico Energy, Minerals and Natural R	
District I 1625 N Frenc	h Dr., Hobbs, NM 88240 HOBBS OCD	WELL API NO.
District II	d Ave., Artesia, NM 88210 OIL CONSERVATION DIV	/ISION 30-41-20947
District III		Dr. 5. Indicate Type of Lease
1000 R10 Braz District IV	os Rd., Aztec, NM 874100V 1 8 2011 1220 South St. Francis I Santa Fe, NM 87505	STATE STATE
	incis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
	SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	E THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BAC RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS		Peggy Sue State 8. Well Number
1 Type of	Well: Oil Well 🖾 Gas Well 🗌 Other	
2. Name of		9. OGRID Number
	Armstrong Energy Corporation	1092
3. Address	of Operator	10. Pool name or Wildcat
4. Well Lo	P.O. Box 1973, Roswell, NM 88202-1973	Tannyhill; Fusselman, East
	•	ne and 330 feet from the East line
	ction 36 Township 05S Range	33E NMPM Roosevelt County
	11. Elevation (Show whether DR, RKB,	
		·
	12. Check Appropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE	OF INTENTION TO:	SEQUENT REPORT OF:
		DIAL WORK
TEMPORA	— — — — — — — — — — — — — — — — — — — —	IENCE DRILLING OPNS. 🗌 P AND A
DOWNHOL		
AT:		
OTHER:		
13. Describe	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att	nd give pertinent dates, including estimated date of starting any
13. Describe propose	e proposed or completed operations. (Clearly state all pertinent details, and	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion.
13. Describe propose	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion.
13. Describe propose 11-08-11	e proposed or completed operations. (Clearly state all pertinent details, ar d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation
13. Describe propose 11-08-11 11-09-11	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots.	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation
13. Describe propose 11-08-11 11-09-11	e proposed or completed operations. (Clearly state all pertinent details, ar d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid.
 13. Describe propose 11-08-11 11-09-11 11-10-11 	e proposed or completed operations. (Clearly state all pertinent details, ar d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4 ¹ / ₂ BPM @ 3000 psi, 26	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid.
 13. Describe propose 11-08-11 11-09-11 11-10-11 	e proposed or completed operations. (Clearly state all pertinent details, ar d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4 ¹ / ₂ BPM @ 3000 psi, 26	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid.
 13. Describe propose 11-08-11 11-09-11 11-10-11 	e proposed or completed operations. (Clearly state all pertinent details, ar d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4 ¹ / ₂ BPM @ 3000 psi, 26	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid.
13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi.	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid.
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: 	e proposed or completed operations. (Clearly state all pertinent details, ar d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi.	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi,
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: 	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi.	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi,
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: 	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi.	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi,
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: I hereby certis SIGNATURI 	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi. Rig Release Date:	hd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, My knowledge and belief. PRESIDENTDATE11/16/11
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: I hereby certis SIGNATURI 	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi. Rig Release Date:	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, py knowledge and belief. PRESIDENTDATE11/16/11
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: I hereby certis SIGNATURI 	e proposed or completed operations. (Clearly state all pertinent details, at d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi. Rig Release Date: ify that the information above is true and complete to the best of m E	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, hy knowledge and belief. PRESIDENTDATE11/16/11 nstrongenergycorp.comPHONE:(575) 625-2222
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: I hereby certi SIGNATURI Type or print For State Us APPROVED 	e proposed or completed operations. (Clearly state all pertinent details, and work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi. Rig Release Date: ify that the information above is true and complete to the best of m E	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, hy knowledge and belief. PRESIDENT DATE 11/16/11 nstrongenergycorp.com PHONE: (575) 625-2222
 13. Describe propose 11-08-11 11-09-11 11-10-11 11-12-11 Spud Date: I hereby certi SIGNATURI Type or print For State Us APPROVED 	e proposed or completed operations. (Clearly state all pertinent details, at d work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Att Circ hole w/ 2% KCL wtr and 500 gals 15% NEFE acid, 1 BPM RIH w/ perf guns, perf 7722'-7728', 4 JSPF, 24 shots. Spot 250 gals 15% NEFE acid, POH w/ 3 stands and reverse aci broke at 3700 psi, establish rate @ 2 BPM, 4230 psi, increased t Acidize w/ 2000 gals 15% NEFE acid, 4½ BPM @ 3000 psi, 26 surged balls off, displaced @ 5 BPM, 3000-4000 psi. Rig Release Date: ify that the information above is true and complete to the best of m E	nd give pertinent dates, including estimated date of starting any tach wellbore diagram of proposed completion or recompletion. I, 205 BBLS. d into tbg, set pkr @ 7649', pressure tbg. Formation o 2.6 BPM @ 4635 psi, displace acid. BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, BBLS to load tbg, balled out w/ 24 balls on, 4890 psi, hy knowledge and belief. PRESIDENTDATE11/16/11 nstrongenergycorp.comPHONE:(575) 625-2222

.