••	Submit Copy To Appropriate District State of New Mexico	Form C-103	
	Office <u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.	
	1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 OH. CONSERDIA TION DIVISION	30-025-11759	
	District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 HOBBS OCH CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr.	5. Indicate Type of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE Z	
	$\frac{\text{District IV} - (505) 476-3460}{1220 \text{ S. St. Francis Dr., Santa Fe, NNDEC 19 2011} Santa Fe, NNV 87505$	6. State Oil & Gas Lease No.	
Г	07505	7. Lease Name or Unit Agreement Name	
	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROFILE OF THE DEFINITION OF DEEPEN OF PLUG BACK TO A	SOUTH JUSTIS UNIT	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		
	1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number J -24 -	
	2. Name of Operator LEGACY RESERVES OPERATING LP	9. OGRID Number 240974	
ł	3. Address of Operator	10. Pool name or Wildcat	
	P.O. BOX 10848 MIDLAND, TX 79702	JUSTIS-BLINEBRY-TUBB-DRINKARD	
ľ	4. Well Location		
	Unit Letter <u>F</u> : <u>1980</u> feet from the <u>North</u> line and <u>1</u>		
	Section 25 Township 25S Range 37E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Lea County	
	3058' GL 3070' KB		
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
	NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:	
	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
	TEMPORARILY ABANDON	LING OPNS. P AND A	
		ЈОВ 🔲	
-	OTHER: Return to Production & Acidize 🛛 OTHER:		
	13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Com	give pertinent dates, including estimated date	
	proposed completion or recompletion.	ipletions: Attach wellbore diagram of	
	ESTIMATED START DATE: 1/15/12		
	MIRU pulling unit. Install BOP. RIH w/ 7" casing scraper to top perf. RIH w/ 7"	pkr and tbg to top perf. Pressure test csg	
to 500#. RIH w/ Bulldog tubing bailer and tbg and cleanout PBTD to 6030' (cmt top). Spot 2000 gal (47.7 bbls) 15% NEFE			
HCL across perfs. Swab back 100 bbl min total load to cleanup well. Acidize perfs 4978'-5926' w/ 2500 gal (59.5 bbls) of Acid/Solvent Mixture (90% of 15% NEFE HCL + 10% Mutual Solvent/Xylene) at 8 BPM and 3500 # max pressure. RIH			
w/ production equipment. Install 2 7/8" tbg, rod pump and FG/steel rodstring. Install and flange up wellhead.			
	Start well pumping. RDMO pulling unit.		
	Perfs: 4978-5926' PBTD: 6030' TD: 7000'		
		· · · · · · · · · · · · · · · · · · ·	
S	Spud Date: Rig Release Date:		
Ţ	handly and for that the information along is true and any lot of the total total		
1	hereby certify that the information above is true and complete to the best of my knowledge	and belief.	
S	IGNATURE Kertwimm	DATE_12/15/2011	
T	ype or print name Kent Williams E-mail address:	PHONE: <u>432-689-5200</u>	
	merrial drive Enclosed		
	APPROVED BY:	DATE DEC 1 9 2011	
Ľ	conditions of Approval (11 ally).		

DEC 1 9 2011

