

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

RECEIVED
DEC 19 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-10080
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No E-9089
7. Lease Name or Unit Agreement Name Penroc New Mexico BW State
8. Well Number 1
9. OGRID Number 245872
10. Pool name or Wildcat Tobac Penn Upper
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well. Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Judah Oil, LLC	
3. Address of Operator PO Box 568, Artesia, NM 88211	
4. Well Location Unit Letter K 1874 feet from the South line and 2086 feet from the West line Section 20 Township 8S Range 33E NMPM Chaves County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attachment

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James B. Campanella TITLE Member/Manager DATE 12/15/11

Type or print name James B. Campanella E-mail address: Judahoil@yahoo.com PHONE: (575)746-1280

For State Use Only

APPROVED BY: Mary Brown TITLE Compliance Officer DATE 12/20/2011

Conditions of Approval (if any)

NM BW State #1 Workover Report

11/28/11
10:00 AM MIRU Basic Well Service. NU 3K BOP. SION 4:00 PM

11/29/11
7:00 AM RU wireline. Tagged CIBP @ 5000'. Shot 4 holes @ 4900'. PU and RIH w/new 2-3/8 J-55 Tbg and 4-1/2 cement retainer. RU pump truck and pressure up to 1500#s. No circulation. POOH w/Tbg. SION 4:00 PM.

11/30/11
7:00 AM RIH w/ 4 1/2 AD-1 packer and Tbg to 4898'. RU Crain Acidizing. Spotted 400 gallon 15% HCL NEFE. Set packer @ 4765'. Pumped 5 bbls @ 1 bbl pm. Pressure @ 2400#s and broke. Rate 1.5 bpm @ 0 psi. Pumped 13 bbls and pressure back to 550#s. Pumped 8 bbls and pressure to 2536 SD 5 minutes, 2430. RD acid trucks. RU Par 5 Cementers. Spotted 25 sxs Class "C". Set packer. Squeezed 18 sx into perfs @ max pressure 2090#s. Released packer and pulled 6 stands. Set packer and pressure to 2090#s. Left SION 4:45 PM.

12/1/11
7:00 AM RIH and tagged plug @ 4692'. POOH w/Tbg and packer. RU wireline. RIH w/perf guns and shot 4375-90 w/25 PF. RIH w/guns to perf 4346-61. Tagged BS at 4358'. Tried to work through, couldn't get through. POOH w/guns and RD wireline. Will try to circulate around backside of 4 1/2" in the morning. SDON 12:00 PM.

12/2/11
7:00 AM RU Kill Truck. Pumped to 1100#s, didn't circulate. RIH w/3 jnts tailpipe, AD-1 packer, SN, 130 jnts. Circulated 20 bbls down backside. Started slight gas kick to pit. Laid down 1 joint. Set packer @ 4282'. Pressured up to 2700#s. Wouldn't circulate around 4 1/2" casing. Released pressure. Released packer. Circulate down casing. RIH w/4 jnts. Ran packer to 4412'. No tight spots. POOH w/16 jnts. SLOW 1:30 PM.

12/7/11
7:00 AM POOH w/Tbg. RU JSI Wireline. FL 800'. Perfed holes 4346 - 61, 4283-98 w/25 PF. RD JSI. RIH w/136 jnts of Tbg, AD-1 packer, SN and 3 MJ. Swabbing well. Set packer @ 4209'. Btm of MJs @ 4307'. Made 5 runs. Swabbed dry on 3rd run, 4th dry. Waited 1 hour, 5th run dry. No sign of hydrocarbons. SION 3:30 PM.

12/8/11
8:00 AM RIH w/swab. No fluid. POOH laid down Tbg. ND BOP. Flanged up well head. RDPU 12:00 PM Wait to P/A well.