Submit I Copy To Appropriate District Stat	te of New Mexico	Form C-103
Office	erals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		WELL API NO. 30-005-00875
		5. Indicate Type of Lease
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 DEC <b>2 2</b> $2011220$ S District IV – (505) 476-3460 Sar	South St. Francis Dr.	STATE X FEE
District IV - (505) 476-3460 DLC Sar 1220 S. St. Francis Dr., Santa Fe, NM	nta Fe, NM 87505	6. State Oil & Gas Lease No.
87505		303735
SUNDRY NOTICES AND REPOR (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	O DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name ROCK QUEEN UNIT
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well 🗌 Oth	er	8. Well Number 37
2. Name of Operator Celero Energy II, LP		9. OGRID Number 247128
3. Address of Operator <sub>400</sub> W. Illinois, Ste. 1601	a ann a suar a suar a suar an an ann an ann an an an an an an an a	10. Pool name or Wildcat
		CAPROCK QUEEN
4. Well Location		
	n the <u>N</u> line and <u>198</u>	
Section 26 Townsh	hip 13S Range 31E ow whether DR, RKB, RT, GR, etc.	NMPM County CHAVES
4417' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABAI		
TEMPORARILY ABANDON 🔲 CHANGE PLANS		
		т јов
		·
OTHER:	OTHER: Squeeze	csg leak
13. Describe proposed or completed operations. (0	Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19 proposed completion or recompletion.	-	
11/11 - 11/18/11 - RIH w/ 5-1/2" RBP & 5-1/2" pkr. Set RBP @ 3030-3039'. Pkr to 3000' & test RBP to 600# - 15 mins. Annulus leak - 1 BPM - 100#. Test w/ pkr & found leak between 2910-2943' & pin hole leak near surface. POH w/ pkr & dumped 2 sks sand		
on RBP. RIH w/ 4" 11# UFJ coated liner w/ 10 jts 2-3/8" $4.7$ # J-55 8rd EUE tbg & 85 jts 2-7/8" $6.5$ # J-55 8rd EUE + 8' of 2-7/8"		
subs. Tagged fill 3070'. Take off 8' of subs and attempt to wash down. Wash down to 3080' & could not get deeper. Cmt w/ ±50 sks C		
+ 2% CaCl2 - 14.8 ppg, 1.33 cf/sk, 6.3 gps. Mixed 15 bbls & pump down tbg string. Get back on tbg and displace w/ 17 bbls down to 3020' inside 2-3/8". Began losing return rate w/ 5 bbls cmt in annulus & after 10 bbls no returns. TOC left @ 3065' in 4". Final		
differential pressure was 200#. Set down liner on TD. RIH w/ 4-7/8" bit, six 3-1/2" DC & 2-7/8" WS. Tag cmt @ 2507' - soft down		
to 2724'. Drl down to 2755'. Lost some returns & bit fell out cmt. Wash down to TOL @ 2795'. Circ hole clean. Tag fill/TOC inside		
4" 11# liner @ 2992' (liner top @ 2795'). RIH w/ 5-1/2" 32A pkr on 2-7/8" 6.5# J-55 8rd EUE tbg and set @ 2543' (78 jts). Load annulus & pressure up to 200#. Establish rate @ 2 BPM - 200#. Mix 150 sks C w/ 2% CaCl2 @ 14.8 ppg, 1.32 cf/sk, 6.3 gps - (18		
	21M - 200#. MHX 150 SKS C W/ 2% C	
bbls) & sqz down tbg @ 2 BPM down to 100#. Disp	lace w/ 17 bbls (2 bbls below pkr) -	final pump pressure 800# - SD 500#
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure	final pump pressure 800# - SD 500#
bbls) & sqz down tbg @ 2 BPM down to 100#. Disp holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure	final pump pressure 800# - SD 500#
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure	final pump pressure 800# - SD 500#
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet	final pump pressure 800# - SD 500#
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor Spud Date:	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date:	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date:	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor Spud Date:	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date:	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor Spud Date:	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date:	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor Spud Date:	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date:	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz e and belief. 
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor Spud Date:	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date: omplete to the best of my knowledg 	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz e and belief. 
holding. Wait 15 mins - squeeze w/ 1/4 bbl - pressure w/ 1/4 bbl - pressure 1000#. Pressure holding. * Cor Spud Date: I hereby certify that the information above is true and co SIGNATURE Type or print name Lisa Hunt	lace w/ 17 bbls (2 bbls below pkr) - 1000#. Pressure holding. pressure ntinued on attached sheet Rig Release Date:	final pump pressure 800# - SD 500# 800# - SD 500# holding. Wait 15 mins - sqz e and belief. 

## Rock Queen Unit #37 - C103 Continued

<u>11/28/11</u> - Run CBL from 3059' up to 2730'. TOL @ 2793' & shoe @ 3080'. CBL could not get below 3069'. RIH w/ perf guns - 10' fill. POH. RIH w/ 3-3/8" rock bit on 10 jts 2-3/8" WS + 2-7/8" WS down to 3075' cleaning out liner. RIH w/ perf guns & shoot perfs from 3066' up to 3052' [28 holes - 2 SPF - 180° phasing]. RIH w/ 4" pkr on 10 jts 2-3/8" WS & 2-7/8" WS down to 2853' and set pkr. Press annulus to 300# & monitor. Acidize perfs w/ 2000 gals 7-1/2% HCL dropping 42 RCN balls BD @ 975#. Ave treat rate = 3 BPM. Ave press = 1350#. Max psi @ 3500#. Balled out once @ 3450#. Surged off balls and remainder acid flushed and overflushed w/ 48 bbls FW.

11/30/11 - Unset 4" pkr and RIH to knock off any RCNB's. Tag TD @ 3075'. POH w/ pkr on mixed string. RIH w/ 10 jts 2-3/8" & 85 jts 2-7/8" WS to reverse hole clean w/ 100 bbls 10# PW. POH. RIH w/ 2-3/8" X 1.562" 'R' landing nipple SS, 2-3/8" X 2' tbg sub NC, bottom sub chemical discharge NC, 5-1/2" X 2-7/8" AS-1-X pkr NC, volume tube NC, 2-7/8" full opening T-2 Seal Nipple SS, Dummy T-2 On/Off Tool [13.5'], 85 jts 2-7/8" 6.5# J-55 8rd EUE tbg. [2763.87']. Set 5-1/2" P pkr @ 2760.75' to 2768.99', landing nipple from 2768.99 to 2769.94', EOT @ 3058.39' with 7' 2-7/8" tbg above GL. Filled every 10 stands w/ 10# PW while running. Test csg after setting P pkr 400# solid. Left 400# on csg to seat pkr.

12/2 - 12/15/11 - RIH w/ 5-1/2" X 2-7/8" T-2 On/Off NC, Top Sub CO2 Inj SS, 2-3/8" X 10.1' Tbg Sub NC. RIH 85 jts 2-3/8" 4.7# J-55 8rd EUE IPC tbg w/ sealant thread dope, tag P pkr, space out. Pulled out 2 jts, ran in 24' subs (10' + 10'+ 4'), ran 84th jt of 2-3/8" IPC. Latched onto P pkr @ 2773.09, sit 9 pts down. RIH w/ new 2-3/8" jt and latched into pkr. EOT @ 3080'