BUR	DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT		HOBBS OCD JAN 0 5 2012				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well			8. Well Name and No. Penrose Federal No. 1				
2 Name of Operator John H. Hendrix Corporation		<u> </u>		9. API Well No. 30-025-10150			
			lude area code)		10 Field and Pool or Exploratory Area		
P. O. Box 3040 Midland, TX 79702-3040 432-684-663							
4 Location of Well (Footage, Sec., T.,R.,M, or Survey Description) UL F Sec 9, T22S, R37E (1980' FNL & 1980' FWL)					11 Country or Parish, State Lea County, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION TYPE OF AC					ON		
Notice of Intent	Acıdize	Deepen			ction (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat		-71	mation	Well Integrity Other DHC Blinebry,	
Subsequent Report	Casing Repair	Plug and			nplete orarily Abandon	Tubb, Drinkard zones	
Final Abandonment Notice	Convert to Injection	Plug Bac			r Disposal		
following completion of the involved operations If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) This is a request for approval to Down-Hole-Corningle (DHC) the following pools in the subject well: Blinebry Oil & Gas (6660), Tubb Oll & Gas (60240), and Drinkard Pool (19190). This DHC request has been submitted to the NMOCD on January 5, 2012. The supporting data sheet is attached to this Sundry Notice of Intent. The procedure below will be used to perform this action upon OCD and BLM approval of the DHC. Form 3160-5 Subsequent Report and Form 3160-4 Well Recompletion Report will be filed after approved work is completed. MIRU, POOH. GIH and perf Tubb zone @ 6003-6174' Acidize existing Blinebry perfs (5435-5890') and new Tubb perfs w/2500 gal 15% HCl. Swab back spent acid fluids. Swab test Blinebry/Tubb zones. GIH, clean out and wash off sand and retrieve RBP @ 6220'. TFF. CO to 7000'+. (Existing Drinkard Perfs @ 6278-7000') GIH w/ pkr and set @ 6200' and acidize Drinkard perfs w/ 1500 gal 15% HCl. Swab back spent acid fluids. Swab test Dinkard perfs w/ 1500 gal 15% HCl. GIH w/ bg, pump and rods. Return to production. Test DHC well: Blinebry, Tubb, Drinkard.							
14 I hereby certify that the foregoing is true and correct. Name (Printed/Typed)							
Carolyn Doran Haynes			Title Engineer				
Signature Ana Dama Date 01/05/2012							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by		·····	fule		eun cean	Date JAN 1 0 2012	
Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon					VN		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction							

