Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
Office Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240 OBBS OCD District II OIL CONSERVATION DIVISION	WELL API NO.
District II OIL CONSERVATION DIVISION	30-025-06323
1301 W. Grand Ave., Artesia, NM 88210 District III	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	STATE 🔀 FEE 🗌
OIL CONSERVATION DIVISION District III 1000 Rio Brazos Rd, Aztec, NM 87410 JAN 1220 S St. Francis Dr, Santa Fe, NM 87505 District IV 1220 S St. Francis Dr, Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name: EUNICE MONUMENT SOUTH UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
XTO ENERGY, INC. ATTN: PATTY URLAS	005380
3. Address of Operator	10. Pool name or Wildcat
200 N. LORAINE, SUITE 800, MIDLAND, TEXAS 79701	EUNICE MONUMENT; CRAYBURG/SAN ANDRES
4. Well Location	
Unit Letter P: 330 feet from the SOUTH line and	330 feet from the EAST line
Offit Letter feet from the fine and	reet from the 1221 fine
Section 32 Township 20s Range 37E	
11. Elevation (Show whether DR, RKB, RT, GR, et 3,532' - GL	c.)
Pit or Below-grade Tank Application or Closure 🗵	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well * Dis	tance from nearest surface water*
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Constructi	
12. Check Appropriate Box to Indicate, Nature of Notice,	Report, or Other Data
12. Check Appropriate Box to Indicate Nature of Notice,	•
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
	•
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	SEQUENT REPORT OF: ALTERING CASING
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING AULTURE CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plugging or well of the performance of the performance of the performance of the plugging)	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plugging or well of the performance of the performance of the performance of the plugging)	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING AULTURE CASING TEST AND CEMENT JOB	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT SCEED AND ABANDONED 01/09/12. We pertinent dates, including estimated date
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plumping of well Of Mile Toom Approved for plumping of well Plugging) OTHER: Liability under hand is retained pending Toom OTHER: WELL PLUG 13. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD;	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONED 01/09/12. PRES. TEST 5-1/2" CSG. TO 500# - OK;
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plumping of well confine to the property of Well Plugging) Liability under hand is retained pending recently be found at OCD Web Page under OTHER: WELL PLUG 13. Describe problems by found at OCD Web Page under OTHER: WELL PLUG of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG ON THE PLUG OF TAG CMT. PLUG ON THE PLUG ON TH	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONED 01/09/12. PREST 5-1/2" CSG. TO 500# - OK; UG @ 3,430'; PERF.5-1/2" CSG. @2,400';
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plumping of well Of Mile Toom Approved for plumping of well Plugging) OTHER: Liability under hand is retained pending Toom OTHER: WELL PLUG 13. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD;	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT SCED AND ABANDONED 01/09/12. Pre pertinent dates, including estimated date wellbore diagram of proposed completion PRES. TEST 5-1/2" CSG. TO 500# - OK; UG @ 3,430'; PERF.5-1/2" CSG. @2,400'; 25 SX.CMT. PLUG @ 2,450' (PER NMOOD).
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIFIE CASING TEST AND CEMENT JOB Approved for plugging of well plugging) Liability under hand is retained pending record. Approved for plugging of well plugging) Liability under hand is retained pending record. OTHER: WELL PLUE 13. Describe proposed work of Well Plugging. OTHER: WELL PLUE 13. Describe proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. O1/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG @ 1/08/12: TAG CMT. PLUG @ 2,245'; PERF.5-1/2" CSG.@ 1,300'; ATTEMPT TO PUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT.	SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT SCEED AND ABANDONED 01/09/12. PRES. TEST 5-1/2" CSG. TO 500# - OK; JUG @ 3,430'; PERF. 5-1/2" CSG. @2,400'; 25 SX.CMT. PLUG @ 2,450' (PER NMOCD). O EST. INJ.RATE - PRES. UP TO 1,000#; PLUG @ 1,238'; PERF. 5-1/2" CSG. @
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plugging of well OF MPI ETCOM Approved for plugging of well OF MPI ETCOM Approved for plugging of well OF MPI ETCOM Tability under hond is retained pending recommendations. (Clearly state all pertinent details, and give composed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISTING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG @ 1,000# X HELD; PUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 250'; ATTEMPT TO EST. INJ.RATE - PRES. UP TO 1,000#; PUMP A	ALTERING CASING ALTERING CASING PLUG AND ABANDONED 01/09/12. PRES. TEST 5-1/2" CSG. TO 500# - OK; UG @ 3,430'; PERF. 5-1/2" CSG. @2,400'; 25 SX.CMT. PLUG @ 2,450' (PER NMOCD). O EST. INJ.RATE - PRES. UP TO 1,000#; FLUG @ 1,238'; PERF. 5-1/2" CSG. @ 25 SX. CMT. PLUG @ 300' (PER NMOCD).
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING ALL TIPLE CASING TEST AND CEMENT JOB OTHER: Liability under hand is retained pender of Well Plugging) 13. Describe problem of Change placed work Page under of Starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CAIC.); TAG CMT. PLUG @ 1/08/12: TAG CMT. PLUG @ 2,245'; PERF.5-1/2" CSG.@ 1,300'; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,000# X HELD; PUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WCC X TAG CMT. PLUG @ 1,350'; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,200#; PUMP A 01/09/12: TAG CMT. PLUG @ 102'; PERF. X CIRC. TO SURF. A 55 SX. CMT.	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT DEED AND ABANDONED 01/09/12. Pre pertinent dates, including estimated date wellbore diagram of proposed completion PRES. TEST 5-1/2" CSG. TO 500# - OK; UG @ 3,430'; PERF.5-1/2" CSG.@2,400'; 25 SX.CMT. PLUG @ 2,450' (PER NMOCD). TO EST. INJ.RATE - PRES. UP TO 1,000#; FLUG @ 1,238'; PERF. 5-1/2" CSG. @ 25 SX. CMT. PLUG @ 300' (PER NMOCD). PLUG @ 100'-3'; DIG OUT X CUT OFF
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plugging of well OF MPI ETCOM Approved for plugging of well OF MPI ETCOM Approved for plugging of well OF MPI ETCOM Tability under hond is retained pending recommendations. (Clearly state all pertinent details, and give composed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISTING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG @ 1,000# X HELD; PUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WOC X TAG CMT. PLUMP A 250'; ATTEMPT TO EST. INJ.RATE - PRES. UP TO 1,000#; PUMP A	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT DEED AND ABANDONED 01/09/12. Pre pertinent dates, including estimated date wellbore diagram of proposed completion PRES. TEST 5-1/2" CSG. TO 500# - OK; UG @ 3,430'; PERF.5-1/2" CSG.@2,400'; 25 SX.CMT. PLUG @ 2,450' (PER NMOCD). TO EST. INJ.RATE - PRES. UP TO 1,000#; FLUG @ 1,238'; PERF. 5-1/2" CSG. @ 25 SX. CMT. PLUG @ 300' (PER NMOCD). PLUG @ 100'-3'; DIG OUT X CUT OFF
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING ALL TIPLE CASING TEST AND CEMENT JOB OTHER: Liability under hand is retained pender of Well Plugging) 13. Describe problem of Change placed work Page under of Starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CAIC.); TAG CMT. PLUG @ 1/08/12: TAG CMT. PLUG @ 2,245'; PERF.5-1/2" CSG.@ 1,300'; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,000# X HELD; PUMP A 25 SX. CMT. PLUG @ 1,350' (PER NMOCD); WCC X TAG CMT. PLUG @ 1,350'; ATTEMPT TO EST. INJ. RATE - PRES. UP TO 1,200#; PUMP A 01/09/12: TAG CMT. PLUG @ 102'; PERF. X CIRC. TO SURF. A 55 SX. CMT.	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT PLUG AND ABANDONMENT ABAND
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING HUNTING of well POMPT Flows Approved for rhunding of well Pompt Flows OTHER: CASING TEST AND CEMENT JOB OTHER: WELL PLUG 13. Describe problem of Busings of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. O1/07/12: TAG EXISITING 5-1/2" CIBP @ 3,630'; CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG @ 2,245'; PERF.5-1/2" CSG.@ 1,300'; ATTEMPT TO EST. INJ.RATE - PRES. UP TO 1,000# X HEID; PUMP A 01/08/12: TAG CMT. PLUG @ 2,245'; PERF.5-1/2" CSG.@ 1,300'; ATTEMPT TO EST. INJ.RATE - PRES. UP TO 1,200#; PUMP A 01/09/12: TAG CMT. PLUG @ 102'; PERF. X CIRC. TO SURF. A 55 SX. CMT. WELLHEAD 3' B.G.L.; WELD CN STEEL PLATE TO CSGS. X INSTALL I hereby certify that the information above is true and complete to the best of my knowled grade tank has been will be constructed or losed according to NMOCD guidelines X, a general permit SIGNATURE TITLE ACCORD	SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT SCED AND ABANDONED 01/09/12. PRES. TEST 5-1/2" CSG. TO 500# - OK; JUG @ 3,430'; PERF. 5-1/2" CSG. @2,400'; 25 SX.CMT. PLUG @ 2,450' (PER NMOCD). NO EST. INJ. RATE - PRES. UP TO 1,000#; PLUG @ 1,238'; PERF. 5-1/2" CSG. @ 25 SX. CMT. PLUG @ 300' (PER NMOCD). PLUG @ 100'-3'; DIG OUT X CUT OFF DRY HOLE MARKER. ge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan ENT DATE 01/09/12
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING CASING TEST AND CEMENT JOB OTHER: Liability under hond is retained pending received to the label in retained pending received to the property of Well Plugging) OTHER: Liability under hond is retained pending received to the	ALTERING CASING ALTERING CASIN
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approved for plugging of well COMP. Flows Approved for plugging of well Plugging) Liability under hand de retained pending to the found of second pending to the found of the found o	SEQUENT REPORT OF: ALTERING CASING NG OPNS. PLUG AND ABANDONMENT DEED AND ABANDONED 01/09/12. PRES. TEST 5-1/2" CSG. TO 500# - OK; UG @ 3,430'; PERF. 5-1/2" CSG. @2,400'; 25 SX. CMT. PLUG @ 2,450' (PER NMOCD). O EST. INJ. RATE - PRES. UP TO 1,000#; PLUG @ 1,238'; PERF. 5-1/2" CSG. @ 25 SX. CMT. PLUG @ 300' (PER NMOCD). PLUG @ 100'-3'; DIG OUT X CUT OFF DRY HOLE MARKER. ge and belief. I further certify that any pit or belowdor an (attached) alternative OCD-approved plan ENT DATE 01/09/12 DEYLER@MILAGRO-RES.COM Telephone No. (432) 687-3033
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING CASING CASING TEST AND CEMENT JOB Approved for rlumping of well Plugging) OTHER: Liability under hand is retained pending to the property of Well Plugging) OTHER: WELL PLUG 13. Describe proposed Work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. 01/07/12: TAG EXISITING 5-1/2" CIEP @ 3,630'; CIRC. WELL W/ FXA MUD; PUMP A 25 SX. CMT. PLUG @ 3,630'-3,430' (CALC.); TAG CMT. PLUG ATTEMPT TO EST. INJ.RATE - PRES. UP TO 1,000# X HEID; PUMP A 01/08/12: TAG CMT. PLUG @ 2,245'; PERF.5-1/2" CSG @ 1,300'; ATTEMPT TO EST. INJ.RATE - PRES. UP TO 1,200#; PUMP A 01/09/12: TAG CMT. PLUG @ 102'; PERF. X CIRC. TO SURF. A 55 SX. CMT. WELLHEAD 3' B.G.L.; WELD CN STEEL PLATE TO CSGS. X INSTALL I hereby certify that the information above is true and complete to the best of my knowled grade tank has been will be constructed or losed according to NMOCD guidelines X, a general permit SIGNATURE Type or print name DAVID A. EYLER	SEQUENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT REPORT OF: ABANDON ABAND