Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W Grand Ave., Artesia, NACORES OCD OIL CONSERVATION DIVISION	30-025-09108 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE STEE
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd , Aztec, NM 87410 <u>District IV</u> 1220 S St Francis Dr , Santa Fe, NM 87505 Santa Fe, NM 87505	B-2657
SUNDRY NOTICE AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State A-32
PROPOSALS.)	8. Well Number 2
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator	9. OGRID Number 217817
ConocoPhillips Company Attn: Donna Williams	9. OGRID Nullider 21/81/
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 51810, Midland, TX 79710	Jalmat-Tansill-Yates-7 Rivers-Gas
4. Well Location	
Unit Letter G: 1980 feet from the North line and 198	
Section 32 Township 22-S Range 36-E NMPM	Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface waterN/A	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	-
	RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENOTHER: OTHER:	11 JOB []
Official Contract of the Contr	
13 Describe proposed or completed operations. (Clearly state all pertinent details, and	give pertinent dates including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.	each wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36'	each wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'.	each wellbore diagram of proposed completion
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO	down to 500 psi, good.
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or wolf?	down to 500 psi, good.
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for pluggfur or well be Liability under bond (s retained of C-103 (Subsequent Report of	down to 500 psi, good. Ore only, pending receipt to Well Plugging)
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well be Liability under bond is retained of C-103 (Subsequent Report of which may be found at OCD W.	down to 500 psi, good. Ore only, pending receipt to Well Plugging) els Page under
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for pluggfur or well be Liability under bond (s retained of C-103 (Subsequent Report of	down to 500 psi, good. Ore only, pending receipt to Well Plugging) els Page under
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well be Liability under bond is retained of C-103 (Subsequent Report of which may be found at OCD W.	down to 500 psi, good. Ore only, pending receipt to Well Plugging) els Page under
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well be Liability under bond is retained of C-103 (Subsequent Report of which may be found at OCD W.	down to 500 psi, good. Ore only, pending receipt to Well Plugging) els Page under
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well? Liability under bond is retained of C-103 (Subsequent Report of which may be found at 0'Cl') we Forms, www.cmnrd.st teether.es	down to 500 psi, good. Ore only, pending receipt (Well Plugging) est Page under occd.
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well? Liability under bond is retained of C-103 (Subsequent Report of which may be found at OCD we forms, www.cmnrd.st Hoomeds.)	down to 500 psi, good. Ore only, pending receipt (Well Plugging) est Page under occd.
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. Approved for plugging or well Liability under bond is retained of C-103 (Subsequent Report of which may be found at o'C'D we Forms, www.cmnrd.st theatheats which may be found at o'C'D we Forms, www.cmnrd.st theatheats are the constructed or closed according to NMOCD guidelines \(\sqrt{N} \), a general permit \(\sqrt{N} \)	down to 500 psi, good. Ore only, pending receipt (Well Plugging) est Page under occd.
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well? Liability under bond is retained of C-103 (Subsequent Report of Which may be found at OCIO W Forms, www.cmnrd.st the times. Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \(\sigma, \text{ a general permit} \) SIGNATURE TITLE P&A Technician (Basic Type or print name: Greg Bryant E-mail address:	down to 500 psi, good. Tore only, pending receipt well Plugging) est Page under ocd. e and belief. I further certify that any pit or below-or an (attached) alternative OCD-approved plan
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. Approved for plugging or well? Liability under bond is retained of C-103 (Subsequent Report of which may be found at OCD We Forms, www.cmnrd.st the times.) I hereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \(\sigma, \text{ a general permit} \) SIGNATURE TITLE P & A Technician (Basic	down to 500 psi, good. Tore only. I pending receipt to Well Plugging) Sels Page under oed. The and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . Energy Services) DATE 11/1/11
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 10/18/11 Set CIBP @ 3130'. 10/19/11 RIH w/tbg & tag CIBP @ 3130'. Spot 25 sxs cmt. Pressure test csg 36' 10/20/11 Perf @ 1560'. Sqz 40 sxs woc & tag toc @ 1400'. 10/24/11 Tbg 380' circ cmt to surface w/45 sxs. RDMO Approved for plugging or well? Liability under bond is retained of C-103 (Subsequent Report of Which may be found at OCIO W Forms, www.cmnrd.st the times. Thereby certify that the information above is true and complete to the best of my knowledge grade tank has been/will be constructed or closed according to NMOCD guidelines \(\sigma, \text{ a general permit} \) SIGNATURE TITLE P&A Technician (Basic Type or print name: Greg Bryant E-mail address:	down to 500 psi, good. Tore only. I pending receipt to Well Plugging) Sels Page under oed. The and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . Energy Services) DATE 11/1/11

JAN 2 3 2012