, Submit 1 Copy To Appropriate District State of New	Mexico	Form C-103
Office District IEnergy, Minerals and Natural Resources 1625 N French Dr , Hobbs, NM 88240Energy, Minerals and Natural Resources 1625 N French Dr , Hobbs, NM 88240District II - (575) 748-1283 115 First St , Artesia, NM 88210 HOBBS OCOIL CONSERVATION DIVISION 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr. 1220 S st. Francis Dr , Santa Fe, NM 1220 S st. Francis Dr , Santa Fe, NM		Revised August 1, 2011
		WELL API NO
		5. Indicate Type of Lease
		STATE FEE
		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		L.E. GRIZZELL
1. Type of Well: Oil Well 🛛 Gas Well 🗌		8. Well Number 3
2. Name of Operator CHEVRON U.S.A. INC.		9. OGRID Number 4323
 Address of Operator SMITH ROAD, MIDLAND, TEXAS 79705 		10. Pool name or Wildcat BLINEBRY/TUBB
4. Well Location		
Unit Letter A: 750 feet from the NORTH line and 760 feet from the EAST line		
Section 8 Township 22-S Range 37-E NMPM County LEA		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB I		
OTHER: CONVERT TO ROD PUMP, CO, SCALE SQZ OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
CHEVRON U.S.A. INC. INTENDS TO CONVERT TO ROD PUMP, CLEAN OUT, & SCALE SQUEEZE THE SUBJECT WELL.		
DI EASE ENID ATTACHED, THE INTENDED BROCEDURE, WELLBORE DIACRAM, & C. 144 INFORMATION		
PLEASE FIND ATTACHED, THE INTENDED PROCEDURE, WELLBORE DIAGRAM, & C-144 INFORMATION.		
	Deter	
Spud Date: Rig Release	Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE MARS ON TITLE: REGULATORY SPECIALIST DATE: 01-11-2012		
Type or print name: DENISE PINKERTON E-mail address: leakejd@cvhevron.com PHONE: 432-687-7375		
APPROVED BY: Maher HErow Title (maliance Officer Date)/18/2012		
Conditions of Approval (if any):		

,

MAN 2 3 2012

L.E. Grizzell #3 (30-025-10100) Blinebry Oil & Gas and Tubb Oil & Gas T22S, R37E, Section 8 Job: <u>Convert to Rod Pump & Scale Squeeze</u>

Procedure:

This procedure is based on the most recent information regarding wellbore configuration and equipment that could be found in the Midland Office well files and computer databases as of 11/18/2011. Verify what is in the hole with the well file in the Eunice Field office. Discuss w/ WEO Engineer, Workover Rep, OS, ALS, and FS prior to rigging up on well regarding any hazards or unknown issues pertaining to the well.

**Well has been flowing so expect tubing pressure. Well currently has BOP installed on wellhead.

Set tank containing 200 bbls 8.6 PPG cut brine water containing 4 drums (220 gallons) Baker SCW-358 Scale Inhibitor.

- 1. MI & RU workover unit. Test BOP. (Pkr set at 5,451'). Verify that well does not have pressure or flow. If well has pressure, record tubing pressure and notify Remedial Engineer if well has casing pressures. Kill with 8.6 to 10 PPG cut brine fluid containing SCW-358 Scale Inhibitor.
 - Caliper elevators and tubular EACH DAY prior to handling tubing/tools. Note in JSA when and what items are callipered within the task step that includes that work.
- 2. Release pkr, PU & GIH w/ additional 2-7/8" 6.5# J-55 tbg. Set pkr @ 6,040'. Pump down 2-7/8" tbg with 50 bbl containing 8.6 PPG cut brine fluid containing SCW-358 Scale Inhibitor.
- 3. Release pkr, POOH standing back tbg to 5,730'. Set pkr @ 5,730'. Pump down 2-7/8" tbg with 50 bbl containing 8.6 PPG cut brine fluid containing SCW-358 Scale Inhibitor.
- 4. Release pkr, POOH standing back tbg to 5,645'. Set pkr @ 5,645'. Pump down 2-7/8" tbg with 50 bbl containing 8.6 PPG cut brine fluid containing SCW-358 Scale Inhibitor.
- 5. Release pkr, POOH standing back tbg to 5,470'. Set pkr @ 5,470'. Pump down 2-7/8" tbg with 50 bbl containing 8.6 PPG cut brine fluid containing SCW-358 Scale Inhibitor.
- 6. Release pkr, POOH stand back tbg and LD pkr.
- 7. RIH w/ 2-7/8" production tubing and hang off per ALS recommendation. NDBOP. NUWH. RIH w/ rods and pump per ALS. RD and release workover unit.
- 8. Turn well over to production. Report producing rates, flowing pressures and/or fluid levels.



