



New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

HOBBS OCD

John H. Bemis
Cabinet Secretary - Designee

JAN 31 2012

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

RECEIVED

Jami Bailey
Division Director
Oil Conservation Division



Response Required – Deadline Enclosed

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

31-Jan-12

SHERIDAN PRODUCTION COMPANY, LLC
9 GREENWAY PLAZA SUITE 1300
HOUSTON TX 77046-

LETTER OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

NORTH VACUUM ABO NORTH UNIT No.001

Active Injection - (All Types)

30-025-24302-00-00
L-1-17S-34E

Test Date:	1/30/2012	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/4/2012
Test Type:	Bradenhead Test	FAIL TYPE: Other External Failure	FAIL CAUSE:
Comments on MIT:	UNABLE TO CHECK OPERATOR NOT AVAILABLE *****OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*****		

NORTH VACUUM ABO NORTH UNIT No.001

Active Injection - (All Types)

30-025-24487-00-00
F-1-17S-34E

Test Date:	1/30/2012	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 5/4/2012
Test Type:	Bradenhead Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT:	*****WELL FAILED BHT *****UPON ARRIVAL OPERATOR PRESENTLY HAS WELL SHUT IN*****OIL SPILL AROUND WELL HEAD ***OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*****		

Oil Conservation Division
1625 N. French Drive • Hobbs, New Mexico 88240
Phone (575) 393-6161 • Fax (575) 393-0720 • www.emnrd.state.nm.us/OCD



JAN 31 2012

NORTH VACUUM ABO NORTH UNIT No.002**30-025-24645-00-00**

Active Injection - (All Types)

H-1-17S-34E

Test Date: 1/30/2012 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 5/4/2012
Test Type: Bradenhead Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: SALT WATER ON SURFACE WELL MUST BE SHUT IN IMMEDIATELY; OVER PRESSURE LIMIT
TUBING SHOWS 4000# APPROVED PRESSURE LIMIT IS 2610#. ***OPERATOR IN VIOLATION
OF NMOCD RULE 19.15.26.11 AND 19.15.26.10

NORTH VACUUM ABO NORTH UNIT No.001**30-025-25066-00-00**

Active Injection - (All Types)

B-2-17S-34E

Test Date: 1/30/2012 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 5/4/2012
Test Type: Bradenhead Test FAIL TYPE: Other External Failure FAIL CAUSE:
Comments on MIT: UNABLE TO CHECK OPERATOR NOT AVAILABLE *****OPERATOR IN VIOLATION OF
NMOCD RULE 19.15.26.11*****

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,



Hobbs OCD District Office
COMPLIANCE OFFICER

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	015H14150977	US POSTAGE
	\$0.45	
	01/31/12	
	Mailed From 88240	

Sheridan Prod. Co. LLC
9 Greenway Plaza
Ste. 1300
Houston, TX 77046