State of New Mexico

,

Form C-103

Energy, Minerals and Natural Resources Department

i.

Revised 5-27-2004	
FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I HOBBS OCD 1220 South St. Francis Dr. 1625 N French Dr., Hobbs, NM 88240 Santa Fe, NM 87505	WELL API NO 30-025-07509
	5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 8821JAN 30 2012	STATE FEE X
	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	7 Lease Name or Unit Agreement Name
SUNDRY NOMCES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	North Hobbs (G/SA) Unit Section 31
1 Type of Well	8 Well No 131
Oil Well X Gas Well Other 2. Name of Operator /	9. OGRID No 157984
Occidental Permian Ltd.	
3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323 4 Well Location	A second s
Unit Letter L 2310. Feet From The South 990 Feet From The West Line	
Section 31 Township 18-S Range 38-E NMPM Lea County	
11 Elevation (Show whether DF, RKB, RT GR, etc.)	
3651' DF	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
PERFORM REMEDIAL WORK PLUG AND ABANDON Set CIBP, RBP or Packer within 100 feet of uppermost	
TEMPORARILY ABANDON X CHANGE PLANS PLANS Perfs or open hole Pressure test to 500 psi for 30 minutes with	
PULL OR ALTER CASING Multiple Completion a pressure drop of <u>not greater</u> than 10% over a 30 minute period.	
OTHER Sto minute period.	
13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any	
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. Kill well 2. POOL and law down tuking and production againment	
 POOH and lay down tubing and production equipment. Clean out to 4050' 	
4 RIH w/CIBP set @3980'. Cap w/35' of cement Tag to confirm TOC.	
5. Test casing and chart for the NMOCD.	
6. Install TA wellhead Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart	
The Oil Conservation Division	
Top perf @4039'	
MUST BE NOTIFIED 24 Hours	
Prior to the beginning of operations	
constructed or	
closed according to NMOCD guidelines , a general permit or an (attached) alternative	e OCD-approved
Thendry A Ash and plan	
SIGNATURE TITLE Administrative	
TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy_johnson@oxy.com	TELEPHONE NO 806-592-6280
For State Use Only	
APPROVED BY TITLE THAT MG DATE -31-2012	
CONDITIONS OF APPROVAL IF ANY	
FEB 0 1 2012	
	V K