Form 3160-5 HOBBS OCD UNITED STATES (August 2007) 21 DEPARTMENT OF THE INT	fexico Oil Conservation Division, D	istrict l
Form 3160-5 HOBE UNITED STATES	1625 N. French Drive	- FORM APPROVED OMB No. 1004-0137
Form 3160-5 HOBIC (August 2007) JAN 3 0 2017 BUREAU OF LAND MANAC	TERIOR Hobbs, NM 88240	Expires: July 31, 2010
JAN S BUREAU OF LAND MANAC	GEMENT 5. Lease Ser	M-03927
SUNDRY NOTICES AND REPOR Do not Get this form for proposals to o abandoned well. Use Form 3160-3 (APD	drill or to re-enter an	Allottee or Tribe Name
		CA/Agreement, Name and/or No.
SUBMIT IN TRIPLICATE – Other ins	structions on page 2.	Queen Sand Unit
☐ Oil Well ☐ Gas We f	. 8. Well Nam	e and No.
2. Name of Operator	- Drickey 9. API Well	Queen Sand Unit #13
Celero Énergy II, LP	30-005	
		Pool or Exploratory Area
400 W. Illinois, Ste. 1601 Midland TX 79701		k; Queen ///////////////////////////////////
4. Location of Well (<i>Footage, Sec., T.,R, M., or Survey Description</i>) 1980' FSL & 1980' FEL UL: J, Sec 33, T13S, R31E	Chave	s NM
12. CHECK THE APPROPRIATE BOX(I	ES) TO INDICATE NATURE OF NOTICE, REPORT	OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Deepen Production (Start/R	
Alter Casing	Fracture Treat Reclamation	Well Integrity
Subsequent Report	New Construction Recomplete	· · ·
Final Abandonment Notice	Plug Back Water Disposal	
 following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 3. Run pkr to 2760', load annulus & pressure test. 	filed only after all requirements, including reclamation,	w interval, a Form 3160-4 must be filed once
 following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, Swab back load. POOH.	w interval, a Form 3160-4 must be filed once
 following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) POOH w/ injection equipment. RIH w/bit to TD @ 2809'. Run pkr to 2760', load annulus & pressure test. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL 	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, 	w interval, a Form 3160-4 must be filed once have been completed and the operator has ng The BLM Roswell Field Prior To The Scheduled (MIT). For Wells In Chaves Iring Office Hours Or After
 following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) POOH w/ injection equipment. RIH w/bit to TD @ 2809'. Run pkr to 2760', load annulus & pressure test. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL RIH w/ inj tbg & pkr. Load annulus & perform M APPROVED FOR <u>3</u> MONTH PERIOR ENDING <u>APR 2 5 2012</u> 14. 1 hereby certify that the foregoing is true and correct. Name (Printed/T)	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, Swab back load. POOH. MIT. MIT. Approval Subject To Calli Office At Least 24 Hours F Mechanical Integrity Test And Roosevelt County, Du Office Hours Call (575) 623	w interval, a Form 3160-4 must be filed once have been completed and the operator has ng The BLM Roswell Field Prior To The Scheduled (MIT). For Wells In Chaves Iring Office Hours Or After
 following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) POOH w/ injection equipment. RIH w/bit to TD @ 2809'. Run pkr to 2760', load annulus & pressure test. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL RIH w/ inj tbg & pkr. Load annulus & perform M 	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, Swab back load. POOH. MIT. MIT. Approval Subject To Calli Office At Least 24 Hours F Mechanical Integrity Test And Roosevelt County, Du Office Hours Call (575) 623	w interval, a Form 3160-4 must be filed once have been completed and the operator has ng The BLM Roswell Field Prior To The Scheduled (MIT). For Wells In Chaves Iring Office Hours Or After
 following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) POOH w/ injection equipment. RIH w/bit to TD @ 2809'. Run pkr to 2760', load annulus & pressure test. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL RIH w/ inj tbg & pkr. Load annulus & perform M APPROVED FOR <u>3</u> MONTH PERIOR ENDING <u>APR 2 5 2012</u> 14. 1 hereby certify that the foregoing is true and correct. Name (Printed/T)	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, Swab back load. POOH. MIT. MIT. Approval Subject To Calli Office At Least 24 Hours F Mechanical Integrity Test And Roosevelt County, Du Office Hours Call (575) 62 Syped)	w interval, a Form 3160-4 must be filed once have been completed and the operator has ng The BLM Roswell Field Prior To The Scheduled (MIT). For Wells In Chaves Iring Office Hours Or After
following completion of the involved operations. If the operation of testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 3. Run pkr to 2760', load annulus & pressure test. 4. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL 5. RIH w/ inj tbg & pkr. Load annulus & perform M APPROVED FOR 3_MONTH PERIOR ENDING APR 2 5 2012 14. 1 hereby certify that the foregoing is true and correct. Name (Printed/T) Lisa Hunt Signature Signature Lisa Mathematical Abandonment Notices must be f determined that the site is ready for final inspection.)	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, Swab back load. POOH. MIT. MIT. MIT. Approval Subject To Calli Office At Least 24 Hours F Mechanical Integrity Test And Roosevelt County, Du Office Hours Call (575) 62 Syped) Title Regulatory Analyst	w interval, a Form 3160-4 must be filed once have been completed and the operator has Prior To The Scheduled (MIT). For Wells In Chaves Iring Office Hours Or After 7-0205.
following completion of the involved operations. If the operation of testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 3. Run pkr to 2760', load annulus & pressure test. 4. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL 5. RIH w/ inj tbg & pkr. Load annulus & perform M APPROVED FOR <u>3</u> MONTH PERIOR ENDING <u>APR 2 5 2012</u> 14. 1 hereby certify that the foregoing is true and correct. Name (<i>Printed/T</i>) Lisa Hunt Signature Approved by (S/ DAVID R. GLASSS Conditions of approval, if any, are attached. Approval of this notice does not	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, 	w interval, a Form 3160-4 must be filed once have been completed and the operator has Prior To The Scheduled (MIT). For Wells In Chaves iring Office Hours Or After 7-0205.
following completion of the involved operations. If the operation of testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 3. Run pkr to 2760', load annulus & pressure test. 4. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL 5. RIH w/ inj tbg & pkr. Load annulus & perform M APPROVED FOR <u>3</u> MONTH PERIOL ENDING <u>APR 2 5 2012</u> 14. 1 hereby certify that the foregoing is true and correct. Name (<i>Printed/T</i>) Lisa Hunt Signature Signature Approved by Conditions of approval, if any, are attached. Approval of this notice does not that the applicant holds legal or contracted entry is thereon.	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, 	w interval, a Form 3160-4 must be filed once have been completed and the operator has prior To The Scheduled (MIT). For Wells In Chaves iring Office Hours Or After 7-0205. R Date JAN 2 5 2012 DOFFICE
following completion of the involved operations. If the operation of testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 3. Run pkr to 2760', load annulus & pressure test. 4. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL 5. RIH w/ inj tbg & pkr. Load annulus & perform M APPROVED FOR 3_MONTH PERIOD ENDING APR 2 5 2012 14. 1 hereby certify that the foregoing is true and correct. Name (<i>Printed/T</i>) Lisa Hunt Signature AUMANAL STATE AND ADD R. GLASSS Conditions of approval, if any, are attached. Approval of this notice does not that the applicant holds legal or contracte tube to those rights in the publicat.	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, 	w interval, a Form 3160-4 must be filed once have been completed and the operator has prior To The Scheduled (MIT). For Wells In Chaves iring Office Hours Or After 7-0205. R Date JAN 2 5 2012 DOFFICE
following completion of the involved operations. If the operation r testing has been completed. Final Abandonment Notices must be f determined that the site is ready for final inspection.) 1. POOH w/ injection equipment. 2. RIH w/bit to TD @ 2809'. 3. Run pkr to 2760', load annulus & pressure test. 4. Acidize w/ 1500 gals inhibited 7.5% NEFE HCL 5. RIH w/ inj tbg & pkr. Load annulus & perform M ENDING <u>APR 2 5 2012</u> 14. 1 hereby certify that the foregoing is true and correct. Name (<i>Printed/T</i>) Lisa Hunt Signature <u>June</u> <u>Hund</u> Signature <u>June</u> <u>Hund</u> Signature <u>June</u> <u>Solution</u> <u>Conditions of approval, if any, are attached</u> . Approval of this notice does no that the applicant holds legal or contracting the reon. <u>June</u> <u>The perform</u> Title 18 U.S.C. Section 1001 and Title 43 U S C. Section 1212, make it a critical section of the foregoing and the foregoing and the reon. <u>The perform</u> Title 18 U.S.C. Section 1001 and Title 43 U S C. Section 1212, make it a critical section of the foregoing and the foregoing and the reon. <u>The perform</u> Title 18 U.S.C. Section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and Title 43 U S C. Section 1212, make it a critical section 1001 and title 43 U S C. Section 1	results in a multiple completion or recompletion in a ne filed only after all requirements, including reclamation, 	w interval, a Form 3160-4 must be filed once have been completed and the operator has prior To The Scheduled (MIT). For Wells In Chaves iring Office Hours Or After 7-0205. R Date JAN 2 5 2012 DOFFICE

CELEDA ENEDAV

1

CELERO ENERGY				
	rock key Queen Sand Unit ves	DATE: BY: WELL: STATE:	Dec. 14, 2011 MWM 13 New Mexico (Federal)	
COUNTY: Cha Location: 1980' FSL & 1980 SPUD: 3/55 COMP: 3/55 CURRENT STATUS: Injec Original Well Name: Gover	ves ' FEL, Sec 33J, T13S, R31ECM tor	STATE: KB = GL = API =	New Mexico (Federal) 4199' 30-005-00895 ce	
PBTD - 2809' TD - 2809'	5-1/2" 14# @ 2788' w/300 sx <u>Top of Queen @ 2793':</u> Queen Open Hole: 2793' - 2809' (3-55	5)		