

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OCD** State of New Mexico  
Energy, Minerals and Natural Resources  
FEB 01 2012  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
**RECEIVED**

Form C-103  
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-36013
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator David H. Arrington Oil & Gas Inc		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 2071 Midland, TX 79702		7. Lease Name or Unit Agreement Name Green Eyed Squealy Worm
4. Well Location Unit Letter I : 1974 feet from the South line and 1129 feet from the East line Section 26 Township 15S Range 34E NMPM County Lea		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4055 GL		9. OGRID Number 5898
		10. Pool name or Wildcat Eidson; Morrow. North (Gas)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Arrington plans to move in ASAP.  
Rig up and kill well.  
Isolate holes @ +/- 11461-11490', establish injection rate.  
Squeeze holes.  
Drill out cement retainer and CIBP.  
Install artificial lift equipment and put well on production.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Debbie Whiting*

TITLE Engineer Tech

DATE 02/01/2012

Type or print name Debbie Whiting

E-mail address: debbie.whiting@arringtonoil.com PHONE: (432)682-6685

For State Use Only

APPROVED BY:

*[Signature]*

TITLE

DATE

FEB 02 2012

Conditions of Approval (if any):

FEB 02 2012