Submit I Copy To Appropriate District State of New Mexico				
	Form C-103			
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources	Revised August 1, 2011			
1625 N. French Dr. Hobbs NM 88240	WELL API NO.			
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr	30-025-09637			
	 5. Indicate Type of Lease STATE FEE ⊠ 6. State Oil & Gas Lease No. 306443 			
$\frac{1000 \text{ Rio Brazos Rd., Aztec, NM 87410}}{\text{District IV} - (505) 476-3460} \text{ JAN } 2 \text{ 6 2012} $ Santa Fe, NM 87505				
1220 S St Francis Dr., Santa Fe, NM 87505				
SUNDRY CETTES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	Cooper Jal Unit			
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 127			
2. Name of Operator Resaca Operating Company	9. OGRID Number 263848			
3. Address of Operator	10. Pool name or Wildcat			
1331 Lamar Street, Suite 1450Houston, TX 77010	Jalmat; T-Y-7R/ Langlie Mattix; 7R-Q-G			
4. Well Location				
Unit Letter <u>H</u> : <u>1650</u> feet from the <u>North</u> line and <u>9</u>	990 feet from the <u>East</u> line			
Section 24 Township 24S Range 36				
11. Elevation (Show whether DR, RKB, RT, GR, etc.	2.) (¹ / ₂ , ¹ / ₂)			
3312' KB	-			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE				
	CIBP, cleaned out to TD, DHC			
OTHER: OTHER: Drilled (13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	nd give pertinent dates, including estimated date			
 Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y.			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. l be placed on produced when DHC approved. 5 mcf, 68 water			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Cc proposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y.			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, Oil Conservation Division Conditions of approval : Approval for drilling/workover ONLY CANNOT produce Downhole Commingled until 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, OII Conservation Division Conditions of approval : Approval for drilling/workover ONL Y CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production from Downhole commingling			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, eleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, Oil Conservation Division Conditions of approval : Approval for drilling/workover ONLY CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production from Downhole commingling 11/16/2011.			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, OII Conservation Division Conditions of approval : Approval for drilling/workover ONL Y CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production from Downhole commingling 11/16/2011.			
 Describe proposed or completed operations. (Clearly state all pertinent details, at of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. MIRU Pulling Unit & Above Ground Steel Pit. POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. Drilled CIBP @ 3354' & drilled out to TD @ 3541'. POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay RIH w/ production string. RDMO Pulling Unit, cleaned location, eleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, Oil Conservation Division Conditions of approval : Approval for drilling/workover ONLY CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production from Downhole commingling 11/16/2011.			
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1.) MIRU Pulling Unit & Above Ground Steel Pit. 2.) POOH w/ production string; RIH w/ 4 ³/₄" Bit, tagged @ 3311'. 3.) Drilled CIBP @ 3354' & drilled out to TD @ 3541'. 4.) POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay 5.) RIH w/ production string. 6.) RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, Oil Conservation Division Conditions of approval : Approval for drilling/workover ONL Y CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. pud Date: 11/11/2011 Rig Release Date: 1 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production from Downhole commingling 11/16/2011. ge and belief. antDATE1/3/12			
 13. Describe proposed or completed operations. (Clearly state all pertinent details, ar of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Cc proposed completion or recompletion. 1.) MIRU Pulling Unit & Above Ground Steel Pit. 2.) POOH w/ production string; RIH w/ 4 ¾" Bit, tagged @ 3311". 3.) Drilled CIBP @ 3354' & drilled out to TD @ 3541". 4.) POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay 5.) RIH w/ production string. 6.) RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC 4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, Oil Conservation Division Conditions of approval : Approval for drilling/workover ONL Y CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. pud Date: 11/11/2011 Rig Release Date: 1 IGNATURE Melanie Reyes E-mail address: melanie.reyes@resacaexport State Use Only 	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobl office for approval before transporting production from Downhole commingling 11/16/2011. ge and belief. antDATE1/3/12 ploitation.com PHONE:(432) 580-8500			
 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 1.) MIRU Pulling Unit & Above Ground Steel Pit. 2.) POOH w/ production string; RIH w/ 4 ¼" Bit, tagged @ 3311". 3.) Drilled CIBP @ 3354' & drilled out to TD @ 3541'. 4.) POOH w/ tubing, laid down drill collars & Bit; hydrotested tubing to 7000#, okay 5.) RIH w/ production string. 6.) RDMO Pulling Unit, cleaned location, cleaned & disposed of pit fluids. Well will *C-107A submitted & approved (DHC-4503). Jalmat Test 11/6/11- 5 oil, 5 mcf, 59 water ; Langlie Mattix Test 12/26/11- 5 oil, Oil Conservation Division Conditions of approval : Approval for drilling/workover ONL Y CANNOT produce Downhole Commingled until DHC is approved in Santa Fe. pud Date: 11/11/2011 Rig Release Date: 1 	and give pertinent dates, including estimated date completions: Attach wellbore diagram of y. I be placed on produced when DHC approved. 5 mcf, 68 water Form C-104 is required for each zone after DHC is approved by OCD Santa Fe office Also form Form C-105 completion with all perfs and 24 hr production test Forms to be sent to OCD Hobi office for approval before transporting production from Downhole commingling 11/16/2011. ge and belief. ant DATE DATE 1/3/12 ploitation.com PHONE:			

CURRENT COMPLET	ION SCHEMATIC	LEASE NAME		Cooper Jal	Unit			WELL NO	127	
		STATUS			Oil			API# 30	-025-09637	
		LOCATION SPUD DATE		TD	- 24S, R - 36E, Lee County, Nev 3541	КВ	3,312'	DF		
		INT COMP DA	TE	06/01/54 PBTD	3537 GEOLOGICAL DATA	GL	3,304'	L		
Inface Csg Size 12 1/4			ELEC?	IRIC LOGS			CORES	DST'S or MUD LC	OGS	
Size 121/4 Size 85/8 in				7-54 Schlumberger)						
et@ 290 in Cmt 150 ft		GR-CCL (8-19-93 Halliburton) HYROCARBON BEARING ZONE DEPTH TOPS.								
Circ Yes))	Yates @ 301							
C@ surf 🔼										
C by circ		SURF 8	8 5/8" - 24:	#, J-55 set@ 290' Cmt'd w/15	CASING PROFILE					
				#, J-55 set@ 3460' Cmt'd w/2		surf by c	alc DV tool @"	1205' - pmp 100 s	xs -	
		LINER N	LINER None 5 1/2" - TOC@ 675' f/ surf by calc							
	TOC@ 675	CSG PERFS			CURRENT PERFORATIO	PEN HC	-	isolated below	CIBP @ 3354'	
	by calc			mat (Yates): 3019'-3021' 3026						
		-		", 3194'-3198' & 3218'-3229', 2 s f/ 3048'-3057', 3059'-3064', 3			3141'-3143' 319	2-3194' 3204-32	N8' 3211'-3213'	
				", Peri'd 7-Rivers f/ 3242'-3246		-5150,	3141-3143, 313	2-3134, 3204-32	00,0211-0210,	
				-						
		TUBING DET	AIL	11/16/2011	ROD DETAIL		11/16/2011			
		Length (ft)		Detail	Length (ft)		Detail			
		2875	92	2 7/8" 6 5#, J-55, 8rd EUE 1		1		olish rod w/ 7/8"	pin	
		3	1	5 1/2" x 2 7/8" TAC	0	1	1 1/4" x 1 1/2			
		158 32	5 1	2 7/8" 6 5#, J-55, 8rd EUE 1 2 7/8" Super Max Blast Joir	•	3 58	2', 4', 6' x 7/8 7/8" D steel r	3" grade D pony r rods	od	
	DV Tool @ 1205'	1	1	2 7/8" SN	975	39	3/4" D steel i			
		4	1	2 7/8" Perf Sub	600	24	1 1/2" sınker	bars		
		19 128	1 1	2 7/8" Desander 2 7/8" tubing with Bull Plug	20 MA 0	1	2 1/2" x 1 1/2 1 - 1/14" Stra	2" X 16'RWBC p ainer	ump	
		3220	,		3075 bt	m				
		WELL HISTORY	SUMMARY							
	TOC@ 2405'			pletion interval: 3460 - 3541 pd, 0 bwpd & 185 Mcfgpd (fi	•	c'd w/4,0)00 gals oil & 6,0	000#'s sand		
	E By Calc	15-Nov-58 (C/O from 3	535 - 3541' (6' of fill) Placed	well on rod pump After WO					
				ED TO WATER INJECTION: CIBP @ 3354'. Perf'd (Jalma					00	
				a frac G-3000 & 255,340#'s 12						
				w/ tbg, rods & pmp PWOP	After WO: 50 bopd, 36 bw	pd, & 4	2 Mcfgpd.			
			C/O fill 324 Tao fill @ 3	18 - 3389' 3312' Did not C/O well						
		19-Mar-97 7	Tag fill @ 3	3305' Did not C/O well						
	Yates @ 3018' 2 spf			3302' Did not C/O well imp & tst tbg to 500 psi OK A	cdz'd the w/500 gals acid &	swab ha	ck RIH w/nmn	& rods PWOP		
		16-Apr-02 F	Puli stuck p	pump Pulled tubing Ran back	in hole Placed on pump					
	3019'-21' 3026'-48'			ut bridge in Perfs @ 3146' and rods and pump Tagged at 32				ed 20 acid sticks		
	3048'-3057'			rods & pump Tagged at 3233'				Recovered 20' o	of	
	3059'-3064'			IH with tubing and set TAC with pitting, bottom 30 rods had se		ds PW	OP Laid down 8	3 - 7/8" & 18 - 3/4		
	3077'-3090'			bls of produced water with 10						
	3090'-94'			ods, pump & tbg RIH w/ tbg &		7/8" Not	ched Collar & tb	g bailer and clear	led	
	3094'-3096' 3105'-18'			 RIH with production tubing, p ods, pump & tubing Replaced 		H w/ ne	w 2 7/8" Super I	Max Blast Joint P	WOP	
	3114'-3130'	09-Nov-07 F		rods and pump RIH with rep	•					
	3130'-41' 3142'-3143'			a production string RIH with Pl ave mill -cleaned out to 3,3541						
	3142'-3143'			2'-3194', 3204'-3208', 3211'-321						
			N2 and 15	5,000# 16/30 mesh sand with 5	0% resing coated ISIP= 2430	# Flowe	d well - all gas, p	ressure depleted	Laid down	
	3183'-87' 3992'-3194'			string RIH with 4 3/4", cleaned well PWOP	l out from 3,127' to 3,354' with	n 4 3/4" r	nill RIH with proc	duction string PW	OP	
	3992'-3194' 3194'-98'			prod string RIH 4 3/4", tagged	at 3,311, D/O CIBP at 3,354'	Cleane	d out to 3,541'.	-lydrotest tubing in	hole to 7,000#	
'	3204'-3208'							-		
	3218'-29' 3211'-3213'									
	3231'-3239'									
	Ę									
roduction Csg	7-Rivers @ 3238									
Size 77/8 m Size 51/2 m	Top of Fill at 3266'									
et @ 3460 ft	CIBP @ 3354'									
Cmt 300										
Cırc No C@ 675 f/sum#	k									
C by calc										
	OH Interval									
	3460 - 3541' Iso below CIBP									
	ISO DEIOW CIBP									
		1								
3TD 3537 ft										
TD 3541 ft	43/4									
	4 3/4 Queen @ 3600'	PREPARED								