Subrit I Copy To Appropriate District Office State of New Mexico	Form C-103 Revised August 1, 2011					
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.					
District II - (575) 748-1283 EFB O BAPPONSERVATION DIVISION	30-025-11484					
$\frac{D_{\text{istrict III}} - (505) 334-6178}{1220 \text{ South St. Francis Dr.}}$	5. Indicate Type of Lease STATE FEE 🛛 🛩					
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 RECEIVED Santa Fe, NM 87505	6. State Oil & Gas Lease No.					
1220 S St. Francis Dr., Santa Fe, NM						
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	South Langlie Jal Unit					
1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other TA'd Injector	8. Well Number 8					
2. Name of Operator	9. OGRID Number 160825					
BC Operating, Inc. 3. Address of Operator	10. Pool name or Wildcat					
P.O. Box 50820 Midland, Texas 79710	Jalmat Tansil Yates Seven Rivers					
4. Well Location						
Unit Letter O : <u>3300</u> feet from the <u>South</u> line and						
Section 7 Township 25S Range 37E 11. Elevation (Show whether DR, RKB, RZ	NMPM County Lea					
3118' DF						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
	SUBSEQUENT REPORT OF:					
	-					
TEMPORARILY ABANDON CHANGE PLANS COMMENCE						
	·· - ··-·- D					
OTHER: Reactivate TA'd Injection Well 13. Describe proposed or completed operations. (Clearly state	ited date					
of starting any proposed work). SEE RULE 19.15.7.14 N Per Undergroun	nd Injection Control Program Manual					
	shall be set within or less than 100					
Proposed Procedure:	ermost injection perfs or open hole.					
Rig up pulling unit. ND wellhead and NU BOP	/					
Rig up reverse unit and clean well out to 3341' with bit and colla						
Make casing scraper run to end of casing. TOH with workstring						
TIH with re-dressed packer on $2-3/8$ " injection tubing. Circu injection packer at $+/-3,180$ '.	hate corrosion inhibited packer fluid. Set					
ND BOP and NU wellhead. Perform MIT. Rig down pulling un	it and return well to injection in the Oueen					
formation. Gather injection test information. Acidize as needed.						
Will notify OCD office 24 hours prior to running MIT & Chart.	Condition of Approval: notify					
	OCD Hobbs office 24 hours					
The Oil Conservation Division	prior of running MIT Test & Chart					
Spud ¹ Date MUST BE NOTIFIED 24 Hours Rig Release Date:						
Prior to the beginning of operations						
I hereby certify that the information above is true and complete to the best of my know	ledge and belief.					
SIGNATURE fam Sturms TITLE Regulatory Analys	DATE_02/01/2012					
Type or print name <u>Pam Stevens</u> E-mail address: <u>pstevens@bcoperating</u>	ng.com PHONE: <u>432-684-9696</u>					
For State Use Only						
APPROVED BY: TITLE STATE ME	DATE 2-6-2012					
Conditions of Approval (If any):	FEB 0 6 2012					

FEB 0 6 2012

South Langlie Jal Unit #8 3300' FSL & 2310' FEL, UL O Sec 7 T25S-R37E Lea County, New Mexico API# 30-025-11484

Injection Well Reactivation

Well Data

Tubing:	None					
Casing:	5-1/2", 15.5#,	, J-55 @ 3255'	with 400 sx			
TD:	3341'	PBTD:	3341'	Elevation:	3118' DF	?' KB

CIBP @ 3190' with 2 sx cmt on top

Queen Open Hole 3255' - 3341'

Procedure

- 1. Comply with all company and governmental safety regulations.
- 2. Rig up pulling unit. ND wellhead and NU BOP.
- 3. Rig up reverse unit and clean well out to 3341' with bit and collars. Drill out plug at 3190'. TOH with bit. Make casing scraper run to end of casing. TOH with workstring.
- 4. TIH with re-dressed packer on 2-3/8" injection tubing. Circulate corrosion inhibited packer fluid. Set injection packer at +/-3,180'.
- 5. ND BOP and NU wellhead. Perform MIT. Rig down pulling unit and return well to injection in the Queen formation. Gather injection test information. Acidize as needed.

Contacts

Gary Stevens	Workover Supervisor	432-894-7113
Jerry Livingston	Production Superintendent	432-664-3189
Jason Wacker	Operations Manager	432-684-9696

SLJU #8 WBD.xls

