TO THE REPORT OF THE PROPERTY OF THE	*	
Submit 3 Copies To Appropriate District Office HOBE	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 June 19, 2008
1625 N French Dr, Hobbs, NM 88240	•	WELL API NO.
District II 1301 W. Grand Ave ; Artésia, NM 8821 0	O112 Conservation division	30-025-28133 5. Indicate Type of Lease
District III 1 000 Rio Brazos Rd., Aztec, NM 8741 0	1220 South St. Francis Dr.	STATE 🛛 FEE 🗌
<u>District1V</u> 1220 S St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6 State Oil & Gas Lease No. · · · ·
87505	ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM, FOR PROPOSALS TO	O DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR, USE "APPLICATION PROPOSALS.)	_ /	State GS 16 8 Well Number
	ell Other	9. OGRID Number
2. Name of Operator Mack Energy	Corporation	9. OGRID Number 7 013837
3. Address of Operator		10. Pool Name or Wildcat
P.O. Box 960 Arte	sia, NM 88210	Vacuum Abo, North
4. Well Location Unit Letter P 660	feet from the South line and	660 feet from the East line
Section 16	Township 17S Range 34E	NMPM County Lea
	Elevation (Show whether DR, RKB, RT, GR etc.	
A STATE OF THE STA	4087' GR	The state of the s
PULL OR ALTER CASING : MUL	TIPLE COMPL CASING/CEME	RILLING OPNS P AND A NT JOB
PULL OR ALTER CASING MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed of of starting any proposed work). Soft recompletion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water pressage w/Maxey Brown-OCD. RIH to be with the complete of the com	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 33329' Pump 25sx Class C 3% CC. 'RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressure	RILLING OPNS P AND A NT JOB P AND A
PULL OR ALTER CASING MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed of starting any proposed work). Soft recompletion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water lessage w/Maxey Brown-OCD. RIH to be with the session of th	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 33329' Pump 25sx Class C 3% CC. 'RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressured.	RILLING OPNS P AND A NT JOB P AND A
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed or of starting any proposed work). Signature of starting any proposed or completed or of starting any proposed or completed or starting any proposed or will be starting and starting any proposed or starting any proposed or completed or of starting any proposed or completed or starting any proposed or completed or starting any proposed or will be starting any proposed or completed or starting any proposed or completed or starting any proposed or completed or of starting any proposed or of starting any proposed or completed or of starting any proposed or	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 33329' Pump 25sx Class C 3% CC. 'RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressured.	RILLING OPNS P AND A NT JOB P AND A
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed or of starting any proposed work). Softer completion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water ressage w/Maxey Brown-OCD. RIH to /7/2012 RIH tag @ 3205'. Perf @ 2915' OCD ok spot 25sx plug @ 2968', WOC to lotify Maxey Brown-OCD ok spot plug./8/2012 RIH 1798' spot 35sx Class C 29 seg. Install Dry Hole Marker. roved for plugging of well bore only. fility under bond is retained pending receipt 103 (Subsequent Report of Well Plugging)	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 33329' Pump 25sx Class C 3% CC. 'RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressured.	RILLING OPNS P AND A NT JOB P AND A
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed of of starting any proposed work). Softer completion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water ressage w/Maxey Brown-OCD. RIH to provide the same with the s	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 3:3329' Pump 25sx Class C 3% CC. RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressure. % CC. WOC tag @ 1533'. Perf @ 60' circ. of the complete of the com	RILLING OPNS P AND A NT JOB P AND A
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed or of starting any proposed work). Softer completion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water ressage w/Maxey Brown OCD. RIH to ressage w/Maxey Brown OCD. RIH to ressage w/Maxey Brown OCD. RIH to ressage w/Maxey Brown OCD ok spot 25 xx plug @ 2968', WOC to restain the restained pending receipt will bore only.	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 33329' Pump 25sx Class C 3% CC. 'RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressured.	RILLING OPNS P AND A NT JOB P AND A INT JOB P
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed of of starting any proposed work). Softer completion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water lessage w/Maxey Brown-OCD. RIH to /7/2012 RIH tag @ 3205'. Perf @ 2915' CD ok spot 25sx plug @ 2968', WOC to fify Maxey Brown OCD ok spot plug. (8/2012 RIH 1798' spot 35sx Class C 29 sg. Install Dry Hole Marker. Toved for plugging of well bore only. (18) Install Dry Hole Marker. Toved for plugging of well bore only. (19) (Subsequent Report of Well Plugging) the may be found at OCD Web Page under las, www.cmnrd.state.nm.us/ocd.	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 3:3329' Pump 25sx Class C 3% CC. RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressure. % CC. WOC tag @ 1533'. Perf @ 60' circ. of the complete of the com	RILLING OPNS P AND A NT JOB P AND A
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed of of starting any proposed work). Signature of starting any proposed or completed of starting any proposed work). Signature of starting any proposed or completed of starting any proposed or completed or completed or starting any proposed or completed or completed or starting any proposed or completed or comple	OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A at cap. Shoot 4 squeeze holes @ 3300'. r gel. Set Pkr. @ 2997' pressured perfs @ 3:3329' Pump 25sx Class C 3% CC. RIH w/pkr. set @ 2486' pressured to 800# tag cement. @ 2731'. Perf @ 1750' pressure. % CC. WOC tag @ 1533'. Perf @ 60' circ. of the complete of the com	RILLING OPNS PAND A NT JOB Ind give pertinent dates, including estimated data attach, wellbore diagram of proposed completion and to 750# couldn't pump into. Called left couldn't pump into perfs. Notify Maxey Broad perfs to 650# couldn't pump into perfs. Seement to surface down 5 1/2" csg. Out 8 5/8
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed or of starting any proposed work). Signature of starting any proposed work of starting any proposed work of starting any proposed work. Signature of starting any proposed work of starting any proposed work of starting any proposed work. Signature of starting any proposed work of starting any proposed work of starting any proposed or complete or complete of starting any proposed or complete or complet	CASING/CEME OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A rt cap. Shoot 4 squeeze holes @ 3300'. It cap. Shoot 4 squeeze holes @ 3300'. It cap. Shoot 4 squeeze holes @ 3300'. It cap. Shoot 4 squeeze holes @ 300'. It cap. Shoot 4 sq	RILLING OPNS PAND A NT JOB Indigive pertinent dates, including estimated data attach, wellbore diagram of proposed completion and to to 750# couldn't pump into. Called left couldn't pump into perfs. Notify Maxey Broad perfs to 650# couldn't pump into perfs. Seement to surface down 5 1/2" csg. Out 8 5/8
PULL OR ALTER CASING: MULDOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed of of starting any proposed work). Soft recompletion. /3/2012 Set CIBP @ 4600' w/35' cement/6/2012 Circ. hole w/100 bbls salt water nessage w/Maxey Brown-OCD. RIH to 1/7/2012 RIH tag @ 3205'. Perf @ 2915' OCD ok spot 25sx plug @ 2968', WOC to 1/7/2012 RIH 1798' spot 35sx Class C 29/8/2012 RIH 1798' spot 35sx Class C 29/8/	CASING/CEME OTHER: perations. (Clearly state all pertinent details, a EE RULE 1103. For Multiple Completions: A rt cap. Shoot 4 squeeze holes @ 3300'. It cap. Shoot 4 squeeze holes @ 3300'. It cap. Shoot 4 squeeze holes @ 3300'. It cap. Shoot 4 squeeze holes @ 300'. It cap. Shoot 4 sq	RILLING OPNS PAND A NT JOB SINGLE PAND A NT JOB PAND A NT