HOBBS OCD OCD-HORI

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FEB 2 3 2012

FORM APPROVED OMB No. 1004-0137 Expires July 31, 2010

5. Lease Serial No. NMNM96239 6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS RECEIVED Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other swd Diamondtail 23 Fed SWD 2 2 Name of Operator Devon Energy Production Company, L.P. 9. API Well No. 30-025-33653 3a Address 10. Field and Pool or Exploratory Area 3b. Phone No. (include area code) SWD. 20 N Broadway, Oklahoma City, OK 73102-8260 Cherry Canyon 405-235-3611 4. Location of Well (Footage, Sec., T.,R, M, or Survey Description) 1980 FNL & 660 FEL SEC 23 T23S R32E 11 Country or Parish, State Lea, County, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acıdize Production (Start/Resume) Deepen Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Other MIT TEST Recomplete ✓ Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection ☐ Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection) 1) MIRU. 2) POOH w/ pkr & tbg. Set RBP @ 2500', circ wtr, spot sd on RBP. ND WH. Weld 2" patch on csg. 5) RIse RBP & set @ 5765'. Test csg to 1100 psi, ok. 6) Test csg to 1200 psi & chart for 30 min, ok. RIH w/ ArrowSet pkrT-2, On/Off Tool, 185 jts of 2 7/8" IPC tbg. CH w/ pkr fluid. Test csg to 500 psi for 30 min, ok. ND BOP. NU WH. Test csg to 700 psi, ok. RDMO. (Test charts attached). ACCEPTED FOR RECORD FEB 1 7 2012 /s/ JD Whitlock Jr BUREAU OF LAND MANAGEMENT 14 I hereby certify that the foregoing is true and correct. CARLSBAD FIELD OFFICE Name (Printed/Typed) Title Regulatory Specialist Signature 11/16/2011 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable tyle to those rights in the subject lease which would Office entitle the applicant to contact operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



