
State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-200-

FILE IN TRIPLICATE HOBBS OCD OIL	CONSERVATION DIVISION		Kevised 3-27-2004
DISTRICT I	1220 South St. Francis Dr.	WELL API NO	
1625 N French Dr. , Hobbs, NM 88240 FFB 2 9 2012	Santa Fe, NM 87505	30-025-12495	
DISTRICT II		5 Indicate Type of Lease	
1301 W Grand Ave, Artesia, NM 88210		STATE	FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410		6 State Oil & Gas Lease No	
SUNDRY NOTICES AND REP	ORTS ON WELLS	7. Lease Name or Unit Agreeme	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		Section 27	
l Type of Well Oil Well Gas Well	Other /Temporarily Abandonded	8 Well No 231	
2 Name of Operator	Temporarity Abandonded	9. OGRID No 157984	
Occidental Permian Ltd. 3 Address of Operator		10 Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		10 Foot name of windcat	Hoods (G/SA)
4. Well Location			
Unit Letter K 1350 Feet From The	South 1350 Fee	t From The West	Line
Section 27 Township	18-S Range 38-E	NMPM Yanamana	Lea County
11 Elevation (She 3630' GL	ow whether DF, RKB, RT GR, etc)		
Pit or Below-grade Tank Application or Closure		×aaaaaaaaaaaaaa	
Pit Type Depth of Ground Water		Distance from nearest sur	face water
	k: Volume bbls; Construction Ma		
I II Line Tinekiess iiii Below-Glade Falls	DDIS, CONSTRUCTION MA		
	to Indicate Nature of Notice, Report, or C		
NOTICE OF INTENTION TO:	,, i	SEQUENT REPORT OF	
PERFORM REMEDIAL WORK PLUG AND ABAN	DON REMEDIAL WORK	ALTERING	CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPI	NS. PLUG & AE	BANDONMENT
PULL OR ALTER CASING Multiple Complete	on CASING TEST AND CEMEN	IT JOB	
OTHER.	OTHER: Temporarily	Abandon well/TA Status F	Request X
13. Describe Proposed or Completed Operations (Clearly sta			arting any
proposed work) SEE RULE 1103. For Multiple Compl	etions: Attach wellbore diagram of proposed of	completion or recompletion.	
 RUPU & RU. Un-hang wellhead. POOH and lay down rods. 	The American of T	omporary	
3. ND wellhead. NU BOP.	Inis Approval of 1	emporary bires <u>1-31-20</u>	17
4 POOH and lay down tubing.		ALCO MARKETON AND A STATE OF THE STATE OF TH	
5. RIH w/bit and clean out to 4087'. POOH w/bit6. RIH w/CIBP set @4050'. RU wireline and dur		ine	
7. Circulate packer fluid and test casing to 600 PS		ag angrangi h in the Tolke et ann	
8. RIH w/tubing and tag top of cement at 4015'.	-		
9. ND BOP/NU TA wellhead.10 Test casing to 560 PSI for 30 minutes and chart	for the NMOCD. Mark Whitaker w/NMO	CD on site for test.	
11. RDPU & RU. Clean location. Well is TA'd			
	RUPU 1/23/2012 RDPU		
I hereby certify that the information above is true and complete to the constructed or	e best of my knowledge and belief I further certify	that any pit or below-grade tank ha	s been/will be
closed according to NMOCD guidelines , a genera		e OCD-approved	
SIGNATURE MUNICIPAL COLOR	plan TITLE Administrative	Associate DATE	2/27/2012
	mail address: mendy johnson@oxy.com	TELEPHONE NO	806-592-6280
For State Use Only			
APPROVED BY	TITLE STAFF	CARE DATE	3-1-2012
CONDITIONS OF APPROVAL IF AMY.	•		



Wellbore Diagram: NHSAU 231-27 Unknown 9.625 OD/ 36.00# Round Short 8.921 ID 8.764 Drift @(1718) 2916 3975 Unknown 7.000 OD/ 24.00# Round Short 6.336 ID 6.151 Drift @(4086) Plug - Cement @(4015) 4175 Wellbore Hole - Unknown Size and Depth (0-4375) Producing Interval-GBSA/231-27 (4086-4375)