

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

DISTRICT I
1625 N French Dr , Hobbs, NM 88240

DISTRICT II
1301 W Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
HOBBS OCD 1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 29 2012

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		WELL API NO 30-025-38071
1 Type of Well Oil Well ☒ Gas Well ☐ Other ☐		5 Indicate Type of Lease STATE ☒ FEE ☐
2 Name of Operator Occidental Permian Ltd.		6 State Oil & Gas Lease No
3 Address of Operator HCR 1 Box 90 Denver City, TX 79323		7 Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit Section 13
4 Well Location Unit Letter <u>M</u> <u>335</u> Feet From The <u>South</u> <u>120</u> Feet From The <u>West</u> Line Section <u>13</u> Township <u>18-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County		8 Well No <u>646</u>
11 Elevation (Show whether DF, RKB, RT GR, etc) 3681' GR		9 OGRID No <u>157984</u>
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10 Pool name or Wildcat <u>Hobbs (G/SA)</u>

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ Multiple Completion ☐
 OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: Clean out/Plug back/OAP/AT ☒

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1 RUPU & RU.
- 2 ND wellhead/NU BOP.
- 3 POOH w/rods and pump.
- 4 RIH w/bit & tag @4451' (PBDT). POOH w/bit.
- 5 RU wireline and perforate hole at 4220-4229'. RD wireline.
- 6 RIH w/RBP set @4275'. Dump 2 sack of sand on top of RBP. RIH w/PPI packer set @4169'.
- 7 RU acid truck & acid treat well w/1500 gal of 15% PAD acid w/1000# gelled rock salt block in two stages. Flush w/50 bbl fresh water. RD acid truck.
- 8 RU pump truck and pump scale squeeze w/100 bbl fresh water w/60 gal of EC6490A scale inhibitor. Flush w/100 bbl of 10# brine. RD pump truck.
- 9 POOH w/PPI packer and RBP.

see attached sheet for additional data*

I hereby certify that the information above is true and complete to the best of my knowledge and belief I further certify that any pit or below-grade tank has been/will be constructed or

closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A Johnson TITLE Administrative Associate DATE 02/27/2012
 TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy_johnson@oxy.com TELEPHONE NO 806-592-6280

For State Use Only

APPROVED BY [Signature] TITLE STAFF MGR DATE 3-1-2012

CONDITIONS OF APPROVAL IF ANY

MAR 01 2012

NHU 13-646 30-025-38071

10. RIH w/TAC set on 132 jts of 2-7/8" tbg. TAC set @4164'.
11. ND BOP/NU wellhead.
12. RDU & RU. Clean location and return well to production.

RUPU 1/23/2012

RDPU 1/31/2012

Wellbore Diagram : NHSAU 646-13

