

United States Department of the Interior

TAKE PRIDES INAMERICA

BUREAU OF LAND MANAGEMENT
Pecos District
Carlsbad Field Office
620 E. Greene
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm

IN REPLY REFER TO 3180 (P0220) NM-70970X

HOBBS OCD

Reference:

Designation of Successor Unit Operator Langlie Jal Unit Unitization Agreement No. NM-70970X Eddy County, New Mexico MAR 1 9 2012

RECEIVED

MAR. 1 3 2012

CERTIFIED—RETURN RECEIPT REQUESTED 7008 3230 0002 0987 6377

Resaca Operating Company 1331 Lamar Suite 1450 Houston, TX 77010

Gentlemen:

This office has received and reviewed your designation of successor unit operator in which your company has agreed to assume all rights, duties, and obligations as the unit operator of the Langlie Jal Unit Eddy County, New Mexico.

As your company as Resaca Operating Company has obtained a Nationwide 25,000.00 BLM Bond (NMB000624), a recommendation has been sent to BLM New Mexico State Office to require that Linn Operating, Inc. to post an additional individual Unit bond in the amount of \$150,000.00. The Authorized Officer condition of approval is based upon Resaca Operating Company final bonding to be in place within 60 days of the date of this letter.

Therefore, Resaca Operating Company is hereby approved as the unit operator for the Langlie Jal Unit as of this date and is effective April 1, 2011. In accordance with this approval, Resaca Operating Company is responsible for all operations and the reporting of all production from the unit. Well signs should also reflect Resaca Operating Company as the unit operator. Please inform all interested principles of such approval. An approved copy of this designation is enclosed.

In approving this designation, the Authorized Officer neither warrants nor certifies that the designated party has obtained all required approvals that would entitle it to conduct operations under the Langlie Jal Unit Agreement.

In addition to becoming the successor unit operator, this office requests a revised Exhibit B for the subject unit, as per 43 CFR 3186.1-2 model form, be suibmitted within 60 days from the receipt of this letter.

If you have any questions regarding this letter, please contact Edward G. Fernandez, Petroleum Engineer at the Division of Lands and Minerals at (575) 234-2220.

Sincerely,

Don Peterson Assistant Field Manager, Lands and Minerals

1 Enclosure

cc: ONRR, Denver NMOCD-Hobbs Hobbs I&E

NM (P0221)

NM (P0220), CFO

MAR 1 9 2012

RESIGNATION OF UNIT OPERATOR

RECEIVED

Langlie Jal Unit Area
County of Lea
State of New Mexico
Unit Agreement No. 14-08-0001-11587

Under and pursuant to the provisions of Section 7 of the Unit Agreement for the Development and Operation of the Langlie Jal Unit Area, Lea County, New Mexico, Ranger 40 Petroleum, LLC the designated Unit Operator under said Unit Agreement, does hereby resign as Unit Operator, effective upon the selection and approval of a Successor Unit Operator.

Executed with effect as aforesaid the 17th day of August, 2011.

Name: Leslie A. Sherman

Title: Chief Operating Officer

ACKNOWLEDGEMENTS

STATE OF FLORIDA)
) SS.
COUNTY OF COLLIER)

The foregoing instrument was acknowledged before me this 17th day of August, 2011, by Leslie A. Sherman, Chief Operating Officer of Ranger 40 Petroleum, LLC, a Delaware limited liability company, on behalf of said company.

Notary Public – State of Florida

REGINA MEROLLA
MY COMMISSION # DD930752
EXPIRES October 05, 2013
FloridaNotaryService com.

DESIGNATION OF SUCCESSOR UNIT OPERATOR LANGLIE JAL UNIT AREA COUNTY OF LEA, STATE OF NEW MEXICO

HOBBS OCD

MAR **1 9** 2012

NO. 14-08-0001-11587

RECEIVED

THIS INDENTURE, dated as of the 1st of February, 2012, effective the 1st day of April, 2011, by and between Resaca Operating Company, whose address is 1331 Lamar, Suite 1450 Houston, Texas 77010, hereinafter designated as "First Party", the Owners of the Unitized Working Interests, Resaca Exploitation, Inc. whose address is 1331 Lamar Suite 1450 Houston, Texas 77010, hereinafter designated as "Second Party".

WITNESSETH:

WHEREAS, under the provision of the Act of February 25, 1920, 41 Stat. 437, 30 U.S.C. Secs. 181, et seq., as amended by the Act of August 8, 1946, 60 Stat. 950, the Secretary of the Interior, on the 4th day of January, 1971, approved a Unit Agreement for the Langlie Jal Unit Area, and

WHEREAS, Ranger 40 Petroleum has resigned as Unit Operator and the designation of another Unit Operator is now required pursuant to the terms thereof; and

WHEREAS, the First Party has been and hereby is designated by the Second Party as Unit Operator, and said First Party desires to assume all the rights, duties and obligations of Unit Operator under the said unit agreement.

NOW THEREFORE, in consideration of the premises hereinbefore set forth and the promises hereinafter stated, the First Party hereby covenants and agrees to fulfill the duties and assume the obligations of Unit Operator under and pursuant to all the terms of the unit agreement, and the Second Party covenants and agrees that, effective upon approval of this indenture by the Authorized Office of the State of New Mexico, First Party shall be granted the exclusive right and privilege of exercising any and all rights and privileges as Unit Operator, pursuant to the terms and conditions of said unit agreement; said unit agreement being hereby incorporated herein by reference and made a part hereof as fully and effectively as though said unit agreement were expressly set forth in this instrument.

This instrument may be executed in multiple counterparts, none of which need to be executed by all parties hereto, but this instrument shall be binding on all parties who execute same.

IN WITNESS WHEREOF, the parties hereto have executed this instrument as of the date hereinabove set forth, effective the 1st day of April, 2011.

FIRST PARTY:

RESACA OPERATING COMPANY

NAME: TRACI J. GUTHRIE

TITLE: VICE PRESIDENT AND SECRETARY

SECOND PARTY:

BY:

RESACA EXPLOITATION, INC.

NAME: ROBERT PORTER

TITLE: VICE PRESIDENT OF ENGINEERING

	AUTHORIZATION:
	BY:
	NAME:TITLE:
	ACKNOWLEDGEMENTS
STATE OF TEXAS	§
COUNTY OF HARRIS	§
PATRICIA HEF MY COMMISSION August 17,	ON EXPIRES
COUNTY OF HARRIS	
The foregoing inst February, 2012 by Rober	strument was acknowledged before me on this day of ert Porter, Vice President and Secretary of Resaca Exploitation, n on behalf of said company.

•

EXHIBIT A

Well No.	Location	API No.
001	T24S, R37E, Sec, 31	30-025-11304 🗸
002	T24S, R37E, Sec. 31: NE/4 NE/4	30-025-24837 🗸
003	T24S, R37E, Sec. 32	30-025-11311
004	T24S, R37E, Sec. 32: NE/4 NW/4	30-025-24838
005	T24S, R37E, Sec. 32: NW/4 NE/4	30-025-11320
006	T24S, R37E, Sec. 32: NE/4 NE/4	30-025-11317
007	T24S, R37E, Sec. 32	30-025-11314
008 ~	T24S, R37E, Sec. 32: SW/4 NE/4	30-025-24839
009	T24S, R37E, Sec. 32: SE/4 NW/4	30-025-11310 /
011	T24S, R37E, Sec, 31	30-025-11293
012	T24S, R37E, Sec, 31	30-025-11303 🗸
013	T24S, R37E, Sec. 31: SE/4 NW/4	30-025-23865 🗸
014	T24S, R37E, Sec. 31: SW/4 NW/4	30-025-11296 🗸
016	T24S, R37E, Sec. 31: NE/4 SW/4	30-025-11299
017	T24S, R37E, Sec. 31: NW/4 SE/4	30-025-11301
018	T24S, R37E, Sec, 31	30-025-11298
019	T24S, R37E, Sec. 32: NW/4 SW/4	30-025-11323
020	T24S, R37E, Sec. 32: NE/4 SW/4	30-025-11313
021	T24S, R37E, Sec. 32: NW/4 SE/4	30-025-11315
022	T24S, R37E, Sec. 32: NE/4 SE/4	30-025-24478
023	T24S, R37E, Sec. 32: SE/4 SE/4	30-025-23866 人
024	T24S, R37E, Sec. 32: SW/4 SE/4	30-025-24479
025	T24S, R37E, Sec. 32: SE/4 SW/4	30-025-11307
026	T24S, R37E, Sec. 32: SW/4 SW/4	30-025-11322
027	T24S, R37E, Sec. 31: SE/4 SE/4	30-025-11297 /
028	T24S, R37E, Sec. 31: SW/4 SE/4	30-025-11302 /
029	T24S, R37E, Sec. 31: SE/4 SW/4	30-025-23867 /
031	T25S, R37E, Sec. 6: NW/4 NW/4	30-025-11475 🗸
032	T25S, R37E, Sec. 6: NE/4 NW/4	30-025-11481 /
033	T25S, R37E, Sec. 6: NW/4 NE/4	30-025-11480
034	T25S, R37E, Sec. 6: NE/4 NE/4	30-025-24889 /

		- ·	
	035	T25S, R37E, Sec. 5: NW/4 NW/4	30-025-11455
	036	T25S, R37E, Sec. 5: NE/4 NW/4	30-025-11452
	037	T25S, R37E, Sec. 5: NW/4 NE/4	30-025-11456 /
	038	T25S, R37E, Sec. 5: NE/4 NE/4	30-025-24484 /
	039	T25S, R37E, Sec. 4: NW/4 NW/4	30-025-11442
	040	T25S, R37E, Sec. 4: NE/4 NW/4	30-025-11436 /
	041	T25S, R37E, Sec. 4: NW/4 NE/4	30-025-11437
	042	T25S, R37E, Sec. 4: SW/4 NE/4	30-025-11438
	043	T25S, R37E, Sec. 4: SE/4 NW/4	30-025-23882
	044	T25S, R37E, Sec. 4: SW/4 NW/4	30-025-11443 J
	045	T25S, R37E, Sec. 5: SE/4 NE/4	30-025-11461 🗸
	046	T25S, R37E, Sec. 5: SW/4 NE/4	30-025-11453
	047	T25S, R37E, Sec. 5: SE/4 NW/4	30-025-23883 🗸
	048	T25S, R37E, Sec. 5: SW/4 NW/4	30-025-11457
	049	T25S, R37E, Sec. 6: SE/4 NE/4	30-025-23868 /
•	050	T25S, R37E, Sec. 6: SW/4 NE/4	30-025-24890
•	053	T25S, R37E, Sec. 6	30-025-11469 /
	055	T25S, R37E, Sec. 6: NW/4 SE/4	30-025-11476
		T25S, R37E, Sec. 6: NE/4 SE/4	,
	056		30-025-11479
	057	T25S, R37E, Sec. 5: NW/4 SW/4	30-025-23884
	058	T25S, R37E, Sec. 5: NE/4 SW/4	30-025-11464)
	059	T25S, R37E, Sec. 5: NW/4 SE/4	30-025-11454
	060	T25S, R37E, Sec. 5: NE/4 SE/4	30-025-24879
	061	T25S, R37E, Sec. 4: NW/4 SW/4	30-025-11435
	063	T25S, R37E, Sec. 5: SE/4 SE/4	30-025-11451
	064	T25S, R37E, Sec. 5: SW/4 SE/4	30-025-11450
	065	T25S, R37E, Sec. 5: SE/4 SW/4	30-025-23885
	066	T25S, R37E, Sec. 5: SW/4 SW/4	30-025-11463
	067	T25S, R37E, Sec. 6	30-025-11472
	068	T25S, R37E, Sec. 6	30-025-11471
	069	T25S, R37E, Sec. 6	30-025-11470
	070	T25S, R37E, Sec. 6	30-025-24480
	071	T25S, R37E, Sec. 8: NW/4 NW/4	30-025-23869 0
		<u>IL</u>][

•

072 T25S, R37E, Sec. 8 30-025-11506 073 T25S, R37E, Sec. 8: NW/4 NE/4 30-025-11497 074 T25S, R37E, Sec. 8: NE/4 NE/4 30-025-11496 075 T25S, R37E, Sec. 9: NW/4 NW/4 30-025-11510 076 T25S, R37E, Sec. 9: SW/4 NW/4 30-025-11510 077 T25S, R37E, Sec. 8: SE/4 NE/4 30-025-11498 078 T25S, R37E, Sec. 8: SW/4 NE/4 30-025-11499 079 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-11499 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-23870 081 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 084 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11512 085 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11634 086 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11630 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11643 090 T25S, R37E, Sec. 17: N	
074 T25S, R37E, Sec. 8: NE/4 NE/4 30-025-11496 075 T25S, R37E, Sec. 9: NW/4 NW/4 30-025-11510 076 T25S, R37E, Sec. 9: SW/4 NW/4 30-025-11510 077 T25S, R37E, Sec. 8: SE/4 NE/4 30-025-24881 078 T25S, R37E, Sec. 8: SE/4 NE/4 30-025-11498 079 T25S, R37E, Sec. 8: SW/4 NE/4 30-025-11499 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-23870 081 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11512 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11693 086 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
075 T25S, R37E, Sec. 9: NW/4 NW/4 30-025-11510 076 T25S, R37E, Sec. 9: SW/4 NW/4 30-025-11510 077 T25S, R37E, Sec. 8: SE/4 NE/4 30-025-11498 078 T25S, R37E, Sec. 8: SW/4 NE/4 30-025-11499 079 T25S, R37E, Sec. 8: SE/4 NW/4 30-025-21870 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11500 086 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
076 T25S, R37E, Sec. 9: SW/4 NW/4 30-025-24881 077 T25S, R37E, Sec. 8: SE/4 NE/4 30-025-11498 078 T25S, R37E, Sec. 8: SW/4 NE/4 30-025-11499 079 T25S, R37E, Sec. 8: SE/4 NW/4 30-025-23870 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11500 086 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
077 T25S, R37E, Sec. 8: SE/4 NE/4 30-025-11498 078 T25S, R37E, Sec. 8: SW/4 NE/4 30-025-11499 079 T25S, R37E, Sec. 8: SE/4 NW/4 30-025-23870 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
078 T25S, R37E, Sec. 8: SW/4 NE/4 30-025-11499 079 T25S, R37E, Sec. 8: SE/4 NW/4 30-025-23870 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
079 T25S, R37E, Sec. 8: SE/4 NW/4 30-025-23870 080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
080 T25S, R37E, Sec. 8: SW/4 NW/4 30-025-24849 081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
081 T25S, R37E, Sec. 8: NW/4 SE/4 30-025-11501 082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
082 T25S, R37E, Sec. 8: NE/4 SE/4 30-025-11495 083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
083 T25S, R37E, Sec. 9: NW/4 SW/4 30-025-11513 084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
084 T25S, R37E, Sec. 9: SW/4 SW/4 30-025-11512 085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
085 T25S, R37E, Sec. 8: SE/4 SE/4 30-025-11493 086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
086 T25S, R37E, Sec. 8: SW/4 SE/4 30-025-11500 087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
087 T25S, R37E, Sec. 17: NW/4 NE/4 30-025-11634 088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
088 T25S, R37E, Sec. 17: NE/4 NE/4 30-025-11644 089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
089 T25S, R37E, Sec. 17: SE/4 NE/4 30-025-11630 090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
090 T25S, R37E, Sec. 17: SW/4 NE/4 30-025-11643 091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
091 T25S, R37E, Sec. 17: NW/4 SE/4 30-025-24891	
092 T25S, R37E, Sec. 17: NE/4 SE/4 30-025-11636	
093 T25S, R37E, Sec. 17: SE/4 SE/4 30-025-11633	
095 T24S, R37E, Sec. 32: SW/4 SW/4 30-025-27840	
096 T24S, R37E, Sec. 32 30-025-27841	
097 T24S, R37E, Sec. 32: SE/4 SE/4 30-025-27842	
098 T24S, R37E, Sec. 32: NE/4 SE/4 30-025-27843	
099 T24S, R37E, Sec. 32: NE/4 SW/4 30-025-27844	
100 T24S, R37E, Sec. 32: NW/4 SW/4 30-025-27845	
101 T24S, R37E, Sec. 32: NW/4 SW/4 30-025-28404	•
102 T24S, R37E, Sec. 32: NE/4 SW/4 30-025-28405	,
103 T24S, R37E, Sec. 31: SE/4 SE/4 30-025-28406	,
104 T24S, R37E, Sec. 32 30-025-28407	1
105 T25S, R37E, Sec. 4: NW/4 NW/4 30-025-28454	,

T24S, R37E, Sec. 32: NE/4 NE/4	30-025-28963
T25S, R37E, Sec. 4: NE/4 NW/4	30-025-29044
T25S, R37E, Sec. 5: NE/4 SE/4	30-025 - \$9447 2
T25S, R37E, Sec. 5: NE/4 SE/4	30-025-39448 2
T25S, R37E, Sec. 5: NW/4 SE/4	30-025-29449
T25S, R37E, Sec. 5: SW/4 SE/4	30-025-29450
T25S, R37E, Sec. 8	30-025-29408
T25S, R37E, Sec. 5: SW/4 NE/4	30-025-30 6 71 %
T25S, R37E, Sec. 5: NW/4 NE/4	30-025-30883
T24S, R37E, Sec. 31	30-025-35577
T25S, R37E, Sec. 17	30-025-35642
T25S, R37E, Sec. 17	30-025-35626
T25S, R37E, Sec. 8	30-025-35681 49
T25S, R37E, Sec. 5	30-025-35681
T25S, R37E, Sec. 5	30-025-35749
	T25S, R37E, Sec. 4: NE/4 NW/4 T25S, R37E, Sec. 5: NE/4 SE/4 T25S, R37E, Sec. 5: NE/4 SE/4 T25S, R37E, Sec. 5: NW/4 SE/4 T25S, R37E, Sec. 5: SW/4 SE/4 T25S, R37E, Sec. 8 T25S, R37E, Sec. 5: SW/4 NE/4 T25S, R37E, Sec. 5: NW/4 NE/4 T25S, R37E, Sec. 31 T25S, R37E, Sec. 17 T25S, R37E, Sec. 17 T25S, R37E, Sec. 17 T25S, R37E, Sec. 5

EXHIBIT B

EFFECTIVE APRIL 1, 2011

TO UNIT OPERATING AGREEMENT LANGLIE-JAL UNIT LEA COUNTY, NEW MEXICO

Schedule of Unit Participation of Working Interest Owners

Working Interest Owner	Unit Participation
Resaca Exploitation, Inc.	100.00%
Total	100.00%

EXHIBIT B

EFFECTIVE APRIL 2, 2011

TO UNIT OPERATING AGREEMENT LANGLIE-JAL UNIT LEA COUNTY, NEW MEXICO

Schedule of Unit Participation of Working Interest Owners

Working Interest Owner	Unit Participation
Resaca Exploitation, Inc.	73.00%
Success Real Estate Company, Ltd.	6.00%
IV Holdings, LLC	2.00%
South Plains Capital, LLC	3.00%
Rockport Resources Capital Corporation	1.00%
HRB Oil & Gas, Ltd.	10.00%
Naŭ Holdings, LLC	5.00%
Total	100.00%