Office District I	State of New Mexico	Form C-103
1606 N. Enamel Dr. 11-44- NR 4 000 40	Energy, Minerals and Natural Resour	rces May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-23457
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-2229
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Phillips E State
1. Type of Well: Oil Well	Gas Well Other Water Injection	8. Well Number 012
2. Name of Operator		9. OGRID Number
ConocoPhillips Company		217817
3. Address of Operator 4001 Penbrook St., Odessa TX, 79	0762-5017	10. Pool name or Wildcat Maljamar, GB/SA
4. Well Location		Waijaniai, Ob/SK
	. OOOL Cod Coo day Coo day Po	1 0001 6 (6 (1 37)
Unit Letter M		and 990' feet from the West line
Section 10	Township 17S Range 3. 11. Elevation (Show whether DR, RKB, RT,	3E NMPM County Lea
	4184' RKB; 4172' GL	GR, etc.)
Pit or Below-grade Tank Application		the field of the state of the s
Pit type Depth to Grounds	waterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mi		bbls; Construction Material
12 Check	Appropriate Box to Indicate Nature of N	······································
12. Check	Appropriate Box to indicate Nature of I	votice, Report of Other Data
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		AL WORK
TEMPORARILY ABANDON		NCE DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/	CEMENT JOB
OTHER:	CT OTHER:	Repair Tubing Leak
	pleted operations. (Clearly state all pertinent de	etails, and give pertinent dates, including estimated date
	1) OPP DITTE 1100 P ACRES OF THE	turne, turn Brit Privations amount, minimum B communica auto
of starting any proposed w	ork). SEE RULE 1103. For Multiple Completi	ions: Attach wellbore diagram of proposed completion
or recompletion.	ork). SEE RULE 1103. For Multiple Complet.	ions: Attach wellbore diagram of proposed completion
	ork). SEE RULE 1103. For Multiple Complet	ions: Attach wellbore diagram of proposed completion
or recompletion.		
or recompletion. 04/11/2005 Arrived on location, ho	ld safety meeting. RU Pool Co. DD unit, found	well with 1200 psi on tubing & casing. Wait on
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure.	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pac	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure.	ld safety meeting. RU Pool Co. DD unit, found	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to corr ld safety meeting. RU tubing testers. RIH W/tu	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing. rosion. SDFN.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to corrold safety meeting. RU tubing testers. RIH W/to es. Replaced top jt of tubing with yellow band	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing. rosion. SDFN. bubing & new AD – Lepacker while pressure testing to IPC. RD pressure testing.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to ipc.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to ipc.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing. rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to ipc.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. For the packer is a set of the packer	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test	well with 1200 psi on tubing & casing? Wait on cker for 3 hours before being able to pull tubing. rosion. SDFN. bubing & new AD – 1 packer while pressure testing to IPC. RD pressure testing to IPC. RD pressure testing to IPC.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. For the packer is a set of the packer	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to ipc.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. For the packer is a set of the packer	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to ipc.
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed	ld safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test RDMO.	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to IPC. RD pressure testing to inspector (Johnny Robinson)
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed	Id safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct descriptions. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band to, NU wellhead & perform casing integrity test RDMO.	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to IPC. RD pressure testing to inspector (Johnny Robinson)
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed	Id safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct descriptions. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band to, NU wellhead & perform casing integrity test RDMO.	well with 1200 psi on tubing & casing. Wait on cker for 3 hours before being able to pull tubing rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testing to IPC. RD pressure testing to inspector (Johnny Robinson)
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed	Id safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct descriptions. RU tubing testers. RIH W/tt es. Replaced top jt of tubing with yellow band to, NU wellhead & perform casing integrity test RDMO.	well with 1200 psi on tubing & casing. Wait on ocker for 3 hours before being able to pull tubing. rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testers. ND BOP. Circulate packer to on annulus for NMOCD inspector (Johnny Robinson) rowledge and belief. I further certify that any pit or below-permit or an (attached) alternative OCD-approved plan .
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed	Ild safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/ttes. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test RDMO. The above is true and complete to the best of my king relosed according to NMOCD guidelines , a general part of the second secon	well with 1200 psi on tubing & casing. Wait on ocker for 3 hours before being able to pull tubing. rosion. SDFN. The property of the pressure testing to the pressure testing
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kenneth N. Ar	Ild safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/ttes. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test RDMO. The above is true and complete to the best of my king relosed according to NMOCD guidelines , a general part of the second secon	well with 1200 psi on tubing & casing. Wait on ocker for 3 hours before being able to pull tubing. rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testers. ND BOP. Circulate packer to on annulus for NMOCD inspector (Johnny Robinson) rowledge and belief. I further certify that any pit or below-permit or an (attached) alternative OCD-approved plan .
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kenneth N. As For State Use Only	Ild safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/ttes. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test RDMO. Tabove is true and complete to the best of my king relosed according to NMOCD guidelines , a general part of the performance of the perfo	well with 1200 psi on tubing & casing. Wait on ocker for 3 hours before being able to pull tubing. rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testers. ND BOP. Circulate packer to on annulus for NMOCD inspector (Johnny Robinson) rowledge and belief. I further certify that any pit or below-permit or an (attached) alternative OCD-approved plan . cialist DATE 04/18/2005 conocophillips.com Telephone No. 505.391.5569
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kenneth N. As For State Use Only	Ild safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/ttes. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test RDMO. Tabove is true and complete to the best of my king relosed according to NMOCD guidelines , a general part of the performance of the perfo	well with 1200 psi on tubing & casing. Wait on ocker for 3 hours before being able to pull tubing. rosion. SDFN. ubing & new AD — packer while pressure testing to IPC. RD pressure testers. ND BOP. Circulate packer to on annulus for NMOCD inspector (Johnny Robinson) rowledge and belief. I further certify that any pit or below-permit or an (attached) alternative OCD-approved plan . cialist DATE 04/18/2005 conocophillips.com Telephone No. 505.391.5569
or recompletion. 04/11/2005 Arrived on location, ho vacuum truck to bleed off pressure. POOH W/tubing & packer. Found 04/12/2005 Arrived on location, ho 5000 psi, did not find any more hol fluid in annulus. Set packer @ 424 to 500 psi for 30 min, tested OK. F. Chart enclosed I hereby certify that the information grade tank has been/will be constructed of SIGNATURE Type or print name Kenneth N. As For State Use Only	Ild safety meeting. RU Pool Co. DD unit, found NU BOP. Try to unseat packer, work with pactop jt of tubing with three holes in it due to correct ld safety meeting. RU tubing testers. RIH W/ttes. Replaced top jt of tubing with yellow band 10°, NU wellhead & perform casing integrity test RDMO. Tabove is true and complete to the best of my king relosed according to NMOCD guidelines , a general part of the performance of the perfo	well with 1200 psi on tubing & casing. Wait on ocker for 3 hours before being able to pull tubing. rosion. SDFN. The property of the pressure testing to the pressure testing

