Office	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	New Me	XICO		Form C-103
District I	Energy, Minerals a	and Natui	ral Resources	THE LANGE	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	7
District II 1301 W. Grand Ave., Artesia, NM 88210	301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-302 5. Indicate Type	
bistrict III 1220 South St. Francis Dr.			STATE	FEE 🖂	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM					
87505	ICEC AND DEDODTE ON	IWEIIC		7 Lagas Nama a	r Unit Agraement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				W. Dollarhide Q	r Unit Agreement Name / ueen Sand Unit
PROPOSALS.)	CATION FOR FERWIT (FORW	<i>n</i> C-101)1 C	K SOCII	8. Well Number	
1. Type of Well:				8. Well Number	
Oil Well Gas Well	Other Injection			113	
2. Name of Operator Chaparral Energy, LLC				9. OGRID Numb 004115	
3. Address of Operator				10. Pool name or Wildcat	
	ar Lake Blvd., Oklahoma	a City, O	K 73114	Dollarhide Quee	n
4. Well Location					
Unit Letter C:	feet from the	North_	line and2360_	feet from the	e West line
Section 31	Township 24	is i	Range 38E	NMPM I	Lea County
	11. Elevation (Show wh				
Alberta F. C. Charles and Alberta			·		100 miles
Pit or Below-grade Tank Application (Fo	r pit or below-grade tank closu	ires, a form	C-144 must be attached	<u>d)</u>	
Pit Location: ULSectTwp_	RngPit type	De	pth to Groundwater_	Distance from no	earest fresh water well
Distance from nearest surface water	Below-grade Tank Loca	ation UL	SectTwp	Rng;	
feet from theline and _	feet from the	_line			
12 Check	Appropriate Box to Inc	dicate N	ature of Notice	Report or Other	Data
	ITENTION TO:			SEQUENT RE	
NOTICE OF IN					
PERFORM REMEDIAL WORK			REMEDIAL WORK		ALTERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	_	REMEDIAL WOR	к <u> </u>	ALTERING CASING
				к <u> </u>	ALTERING CASING ☐ PLUG AND ☐
PERFORM REMEDIAL WORK	PLUG AND ABANDON	_	REMEDIAL WOR	LLING OPNS.	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON —	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WORK	LLING OPNS.	ALTERING CASING ☐ PLUG AND ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON —	PLUG AND ABANDON CHANGE PLANS MULTIPLE		CASING TEST AN CEMENT JOB	LLING OPNS.	ALTERING CASING ☐ PLUG AND ☐
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION		COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta	LLING OPNS. ND ain TA Status	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION oleted operations. (Clearly	state all p	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta	LLING OPNS. ND Inn TA Status If give pertinent date	ALTERING CASING PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION oleted operations. (Clearly	state all p	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta	LLING OPNS. ND Inn TA Status If give pertinent date	PLUG AND ABANDONMENT
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed we or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly ork). SEE RULE 1103. For	state all p	CASING TEST AN CEMENT JOB OTHER: Mainta	LLING OPNS. ND ain TA Status d give pertinent date tach wellbore diagr	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost of starting any proposed we	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly ork). SEE RULE 1103. For	state all p	CASING TEST AN CEMENT JOB OTHER: Mainta	LLING OPNS. ND ain TA Status d give pertinent date tach wellbore diagr	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly ork). SEE RULE 1103. For	state all por Multiple Ak 4/6/05,	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att	LLING OPNS. LLING OPNS. IND Inin TA Status I give pertinent date tach wellbore diagrate to 545# for 32 Le and belief. I furth	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly ork). SEE RULE 1103. For	state all por Multiple Ak 4/6/05,	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att	LLING OPNS. LLING OPNS. IND Inin TA Status I give pertinent date tach wellbore diagrate to 545# for 32 Le and belief. I furth	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compostarting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the complete of the closed according to NMOCD grant and closed acc	state all por Multiple Ak 4/6/05,	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att pressure up on case est of my knowledge , a general permit	LLING OPNS. LLING OPNS. IND Inin TA Status I give pertinent date tach wellbore diagrate to 545# for 32 Le and belief. I furth	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the complete of the closed according to NMOCD grant and closed acc	state all por Multiple Ak 4/6/05,	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att	LLING OPNS. LLING OPNS. IND Inin TA Status I give pertinent date tach wellbore diagrate to 545# for 32 Le and belief. I furth	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compof starting any proposed we or recompletion. ID 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or SIGNATURE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the complete of the closed according to NMOCD grant and closed acc	state all por Multiple k 4/6/05, see to the beguidelines	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att pressure up on case est of my knowledge a general permit Engineering Tech	LLING OPNS. ID In TA Status Id give pertinent date tach wellbore diagrates to 545# for 32 The and belief. I furth or an (attached) aftern	PLUG AND ABANDONMENT State
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Leigh Kuyke	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the second of the second	state all por Multiple k 4/6/05, see to the beguidelines	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att pressure up on case est of my knowledge a general permit Engineering Tech	LLING OPNS. ID In TA Status Id give pertinent date tach wellbore diagrates to 545# for 32 The and belief. I furth or an (attached) aftern	PLUG AND ABANDONMENT Bes, including estimated date am of proposed completion minutes. er certify that any pit or below-lative OCD-approved plan D. DATE 4/12/90
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Leigh Kuyke	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the second of the second	state all por Multiple k 4/6/05, see to the beguidelines	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att pressure up on case est of my knowledge a general permit Engineering Tech	LLING OPNS. ID In TA Status Id give pertinent date tach wellbore diagrates to 545# for 32 The and belief. I furth or an (attached) aftern	PLUG AND ABANDONMENT Bes, including estimated date am of proposed completion minutes. er certify that any pit or below-lative OCD-approved plan D. DATE 4/12/90
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or compost starting any proposed we or recompletion. ID 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed on SIGNATURE Type or print name Leigh Kuyke (This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the ser 3495'. RU pump truck above is true and complete closed according to NMOCD generally. And all . E-mail address:	state all por Multiple to the beguidelines	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att pressure up on case est of my knowledge , a general permit Engineering Tech schaparralenergy.	LLING OPNS. LLING OPNS. In TA Status In TA Status In give pertinent date tach wellbore diagrate to 545# for 32 E and belief. I further or an (attached) atternation of the community of the	PLUG AND ABANDONMENT Solution Solution
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed we or recompletion. ID 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Leigh Kuyke This space for State use)	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the ser 3495'. RU pump truck above is true and complete closed according to NMOCD generally. And all . E-mail address:	state all por Multiple to the beguidelines	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta pertinent details, and the Completions: Att pressure up on case est of my knowledge a general permit Engineering Tech	LLING OPNS. LLING OPNS. In TA Status In TA Status In give pertinent date tach wellbore diagrate to 545# for 32 E and belief. I further or an (attached) atternation of the community of the	PLUG AND ABANDONMENT Solution Solution
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Leigh Kuyke This space for State use) APPPROVED BY Conditions of approval, if any:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the ser 3495'. RU pump truck above is true and complete closed according to NMOCD general according to NMO	state all por Multiple k 4/6/05, et to the beguidelines [ITLE]	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta Dertinent details, and the Completions: Att pressure up on case est of my knowledge a general permit Engineering Tech Echaparralenergy.	LLING OPNS. LLING OPNS. In TA Status In TA Status In give pertinent date tach wellbore diagrate to 545# for 32 E and belief. I further or an (attached) atternation of the community of the	PLUG AND ABANDONMENT Solution Solution
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or composition of starting any proposed we or recompletion. TD 3950', perfs 3587'-3741', pack Thereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Leigh Kuyke This space for State use) APPPROVED BY Conditions of approval, if any:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detect operations. (Clearly ork). SEE RULE 1103. For the ser 3495'. RU pump truck above is true and complete closed according to NMOCD generally. And all . E-mail address:	state all por Multiple k 4/6/05, et to the beguidelines [ITLE]	REMEDIAL WORK COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Mainta Dertinent details, and the Completions: Att pressure up on case est of my knowledge a general permit Engineering Tech Echaparralenergy.	LLING OPNS. LLING OPNS. In TA Status In TA Status In give pertinent date tach wellbore diagrate to 545# for 32 E and belief. I further or an (attached) atternation of the community of the	PLUG AND ABANDONMENT Solution Solution

