Form 3160-5 (April 2004)	UNITED STATES OF THORRES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS	FORM APPROVED OMB No 1004-0137 Expires: March 31, 2007	
			5. Lease Serial No. NM 18306
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name	
	UBMIT IN TRIPLICATE- Other instru	uctions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil Well Gas Well C Other			8. Well Name and No. Back Basin #1
2. Name of Op	Endurance Resources, LLC.	/	9. API Well No. 30-025-27051
3a Address P.O. Box 14	166, Artesia, NM 88211	3b. Phone No. (include area code) 575.308.0722	10. Field and Pool, or Exploratory Area N. L.V.
	Well (Footage, Sec., T., R., M., or Survey Description) & 660' FEL Sec. 20 T23S-R34E		11. County or Parish, State Lea County, NM
	12. CHECK APPROPRIATE BOX(ES) TO	INDICATE NATURE OF NOTICE	REPORT, OR OTHER DATA
TUBE O	T2. CHECK APPROPRIATE BOX(ES) TO	TYPE OF ACTION	
Notice Subseq Final A 13. Descril	of Intent Acidize Acidize Alter Casing Casing Repair Change Plans Convert to Injection De Proposed or Completed Operation (clearly state all pert	Fracture Treat Reclamation New Construction Recomplete Plug and Abandon Temporarily Plug Back Water Disponent inent details, including estimated starting date Temporarily	Other Abandon of any proposed work and approximate duration thereof.
Attach followi testing determ	the Bond under which the work will be performed or proving completion of the involved operations. If the operation has been completed. Final Abandonment Notices shall be ined that the site is ready for final inspection.)	ride the Bond No. on file with BLWBIA. Re	tion in a new interval, a Form 3160-4 shall be filed once
Selec	ll 1500 S 3000# BOP on 9 5/8"csng. tive perforate Bone Springs Sand 10,400-10,600' with 2,000 gallons 7 1/2% NEFE perforations as necessary to establish production	SEE ATTACH	ED FOR OF APPROVAL
			10/2012
14. I her Nam	eby certify that the foregoing is true and correct e (<i>Printed/Typed</i>)	Title Geologist	
	Randall Harris		01/152017 PROVED
Signa		Date R FEDERAL OR STATE OFF	
/	THIS SPACE FO		
	•	i' Title	Date MIL WESLEY W. INGRAM PETROLEUM ENGINEER

BACK BASIN #1 30-025- 27051

CURRENT 2/08/2002

LOO' 20" CATT CIRC SIOS' 13 76 CATT CIRC

DU TOOL 7983 1200 5×5

+1,900 CIOP + 35' CMT 11939 T/WINDOW 11951 B/WINDON

T/Ware Frank 11,672

WHIPSPER

CIBP + 40' CMT 11960 - 11967 POR LINER HANCER

12310 95 1325 SXS

12600 CIBP+40'CMT 12620-12841 PERES

14150 5" LINER

Back Basin 1 30-025-27051 Endurance Resources, LLC April 11, 2012 Conditions of Approval

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location.
- 4. A minimum of a 3,000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 6. OPERATOR IS IN NON-COMPLIANCE AS A WELL SHALL NOT BE SHUT IN WITHOUT APPROVAL MORE THAN 30 DAYS. OPERATOR HAS NOT DONE WORK APPROVED IN 2010. NO PRODUCTION SINCE AUGUST 2006.
- 7. WELL IS NOT PLUGGED PROPERLY REQUIRED PLUG AT MORROW NOT SET, 9-5/8" CASING SHOE PLUG NOT SET, TOP OF LINER PLUG NOT SET (CIBP NOT ADEQUATE). THE OPERATOR DID NOT REQUEST APPROVAL TO SET EITHER THE CIBP SET AT 12,300' OR THE CIBP SET AT 11,958'. OPERATOR SCHEMATIC SHOWS THAT THERE IS A CIBP AT 12,600' AND 11,960', WHICH DOES NOT AGREE WITH DOCUMENTS SUBMITTED TO THE BLM. OPERATOR TO REVIEW RECORDS AND PROVIDE A CORRECTED WELL BORE SCHEMATIC.
- 8. OPERATOR STATED IN 2010 THAT THEY CANNOT DRILL OUT THE WHIPSTOCK AND PROPERLY PLUG THE WELL.
- 9. The operator shall tag the CIBP at 11,900' and place 25 sacks of Class H (16.4 ppg, 1.06 yield) cement on CIBP.
- 10. Operator shall set a plug across the top of the Wolfcamp formation. Plug shall be Class H (16.4 ppg 1.06 yield), 220' in length and tagged at 11,600' or shallower.
- 11. Operator has the option of pumping sufficient cement in step 9 to achieve a top of cement at 11,600' or shallower. Plug shall be tagged.
- 12. Operator shall submit a subsequent sundry within 30 days of completing work detailing work completed. Include current well bore schematic.
- 13. Operator shall submit a completion report for the recompletion within 30 days of completion.

- 14. Operator shall submit sundry within 5 days of production start stating well is on production and shall specify exact date.
- 15. Operator has 90 days to have the well back on production in paying quantities. A 72 hour independent well test required to confirm paying production.

WWI 041112