Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District 1</u> Energy, Minerals and Natural Resources	October 13, 2009 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II	30-025-05738
OII CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd , Aztec, NM 87410 Santa Fe NM 87505	STATE FEE
District IV	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM APR 1 6 2012 87505	B-1330-1
SUNDRY NORICES ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	N. d.M. (C/CA II 's DII 11
PROPOSALS.)	North Monument G/SA Unit Blk. 11 8. Well Number 1
1. Type of Well: Oil Well Gas Well Other Injection well.	
2. Name of Operator Apache Corp.	9. OGRID Number 000495
3. Address of Operator	10. Pool name or Wildcat
P O box Drawer D Monument NM 88265	Eunice Monument G/SA
4. Well Location	
Unit Letter A : 660 feet from the North line a	nd 660 feet from the
Eastline	
Section 29 Township 19S Range 33	TE NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, ar	ad give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	mpletions: Attach wellbore diagram of
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet.	mpletions: Attach wellbore diagram of er.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion.	er. i and it held ok.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole-with 3000 gallons 15% and pull of the hole with sonic hammer and acidize open hole-with 3000 gallons 15% and pull of the hole with sonic hammer and acidize open hole-with 3000 gallons 15% and pull of the hole with sonic hammer and acidize open hole-with 3000 gallons 15% and pull of the hole with sonic hammer and acidize open hole-with 3000 gallons 15% and pull of the hole with tubing and packet with 3000 gallons 15% and pull of the hole with tubing and packet with 3000 gallons 15% and pull of the hole with tubing and packet with 3000 gallons 15% and pull of the hole with 15% and	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 1401	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.)	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 1401	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.)	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.)	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.)	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.)	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. Resumed injection in this well. The cause of the failure was the Injection packer.	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.)	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. Resumed injection in this well. The cause of the failure was the Injection packer.	er. i and it held ok. out of the hole. out with tubing.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 if 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.) The cause of the failure was the Injection packer. Rig Release Date:	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. Resumed injection in this well. The cause of the failure was the Injection packer.	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 for 4/13/12 Pressure tested the well to 350 psi. held ok. *Resumed injection in this well.* The cause of the failure was the Injection packer. Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 for 4/13/12 Pressure tested the well to 350 psi. held ok. *Resumed injection in this well.* The cause of the failure was the Injection packer. Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid.
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 of 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.) The cause of the failure was the Injection packer. Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledged SIGNATURE TITLE Instrument Tech	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid. ge and belief. DATE 4-13-12
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 14/13/12 Pressure tested the well to 350 psi. held ok. Resumed injection in this well. The cause of the failure was the Injection packer. Rig Release Date: Title Instrument Tech Type or print name Jim Ellison E-mail address: JD.Ellison@ap	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid. ge and belief. DATE 4-13-12 acheccorp.com_ PHONE:
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packer 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 of 4/13/12 Pressure tested the well to 350 psi. held ok. (Resumed injection in this well.) The cause of the failure was the Injection packer. Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledged SIGNATURE TITLE Instrument Tech	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid. ge and belief. DATE 4-13-12 acheccorp.com_ PHONE:
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull of 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull of 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 14/13/12 Pressure tested the well to 350 psi. held ok. Resumed injection in this well. The cause of the failure was the Injection packer. Rig Release Date: Title Instrument Tech Type or print name Jim Ellison E-mail address: JD.Ellison@ap	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid. ge and belief. DATE 4-13-12 acheccorp.com_ PHONE:
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. 4/9/12 move in rig up and release the packer and pull out of the hole with tubing and packet 4/10/12 run in with a RBP set @ 3725' and circulate the hole clean. Pressure test to 500 ps Pull out of the hole with the RBP. Run in with a bit and tagged @ 3970'. No fill and pull 4/11/12 Run in with sonic hammer and acidize open hole with 3000 gallons 15% and pull 4/12/12 run in with a packer and 118 jts ipc tubing and set packer @ 3725'. Circulate 140 to 4/13/12 Pressure tested the well to 350 psi. held ok. Resumed injection in this well. The cause of the failure was the Injection packer. Rig Release Date: Title Instrument Tech Type or print name Jim Ellison E-mail address: JD.Ellison@ap For State Use Only	er. i and it held ok. out of the hole. out with tubing. obls. of packer fluid. ge and belief. DATE 4-13-12

