Submit 3 Copies To Appropriate Di Office	strict	State of N				Form C-103 May 27, 2004
District 1 1625 N. French Dr., Hobbs, NM 88 District 11		Energy, Minerals an OIL CONSERVA			WELL API NO. 30-025-06173	
District II 1301 W. Grand Ave., Artesia, No District III		1220 South S			5. Indicate Type of Lea STATE	se FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa FARB 1 8 2012 87505 Santa Fe, NM 87505					6. State Oil & Gas Leas 015823	
SUNDRY NOTISES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PSOFOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					7. Lease Name or Unit Eunice Monument Unit	
PROPOSALS.) 1. Type of Well: Oil Well 🗍 Gas Well 🛛 Other					8. Well Number 22	(
2. Name of Operator Burgundy Oil & Gas of New Mexico, Inc.					9. OGRID Number 00	/
3. Address of Operator 401 W. Texas, Suite 1003 Midland, TX 79701					10. Pool name or Wilde Eunice Monument; Gray	
4. Well Location Unit LetterK_:	198	0feet from the	South_1	ine and1980	feet from the	_Westline
Section 19		Township 20 South		nge 37 East	NMPM Le	a County
Pit or Below-grade Tank Applica		11. Elevation (Show whe 3537' KB Closure 🗌	ther DR, I	<i>KKB</i> , <i>K</i> 1, <i>GK</i> , <i>etc</i> .		
Pit typeDepth to (Groundwa	terDistance from nea	rest fresh w	vater wellDi	istance from nearest surface wa	ater
Pit Liner Thickness:	mil	Below-Grade Tank: Vol	lume	bbls; _ (Construction Material	
12. C	beck A	ppropriate Box to Inc	dicate N	lature of Notice	, Report or Other Dat	a
NOTICE	OF IN	FENTION TO:		SU	BSEQUENT REPOR	RT OF:
PERFORM REMEDIAL WO	DRK 🗌	PLUG AND ABANDON		REMEDIAL WO		
					— ·	/ -
	—	CHANGE PLANS			RILLING OPNS.	
TEMPORARILY ABANDON PULL OR ALTER CASING		CHANGE PLANS MULTIPLE COMPL		COMMENCE DE CASING/CEME	RILLING OPNS.	/
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMEI	RILLING OPNS. P AI	
PULL OR ALTER CASING OTHER: 13. Describe proposed of	Dr comple	MULTIPLE COMPL eted operations. (Clearly	state all j	CASING/CEMEI OTHER: pertinent details, a	RILLING OPNS.	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200'	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'.	state all p or Multip	CASING/CEMER OTHER: pertinent details, a le Completions: A	RILLING OPNS. P AI	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200' @ 250' u	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'.	state all p or Multip	CASING/CEMER OTHER: pertinent details, a le Completions: A	RILLING OPNS. P AI	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200' @ 250' u	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'.	state all p or Multip	CASING/CEMER OTHER: pertinent details, a le Completions: A	RILLING OPNS. P AI	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200' @ 250' u	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ¹ / ₂ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	v state all j 'or Multip IBP set @ '4'.	CASING/CEMEI OTHER: pertinent details, a le Completions: A 3645'.	RILLING OPNS. P AI NT JOB D nd give pertinent dates, in Attach wellbore diagram of	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200' @ 250' u	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	Tor Multip For Multip IBP set @ 4'.	CASING/CEMEN OTHER: pertinent details, a le Completions: A 3645'.	RILLING OPNS. P AI NT JOB nd give pertinent dates, in Attach wellbore diagram of Attach wellbore diagram of Plugging)	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200' @ 250' u	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	Tor Multip For Multip IBP set @ 4'.	CASING/CEMEI OTHER: pertinent details, a le Completions: A 3645'.	RILLING OPNS. P AI NT JOB nd give pertinent dates, in Attach wellbore diagram of Attach wellbore diagram of Plugging)	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx 	Dr comple osed wor ended, Ta @ 2500' @ 1200' @ 250' u	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	Tor Multip For Multip IBP set @ 4'.	CASING/CEMEI OTHER: pertinent details, a le Completions: A 3645'. 3645'.	RILLING OPNS. P AI NT JOB nd give pertinent dates, in Attach wellbore diagram of Attach wellbore diagram of Plugging)	ND A
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx Install dry hole mark Install dry hole mark 	Dr comple osed wor ended, Ta @ 2500' @ 250' u @ 250' u er	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	r state all p for Multip ior Multip IBP set @ 4'. proved for p bility under C-103 (Subs ich may be f rms, www.cm	CASING/CEMEN OTHER: pertinent details, a le Completions: A 3645'. 3645'.	RILLING OPNS. P AI NT JOB nd give pertinent dates, ind Attach wellbore diagram of Attach wellbore diagram of Attach wellbore diagram of Plugging) re under	ND A Solution Solution
 PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/23/12 Plug # 4- Spot 60sx Install dry hole mark 	Dr comple osed wor ended, Ta @ 2500' @ 250' u @ 250' u er	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	r state all p for Multip ior Multip IBP set @ 4'. proved for p bility under C-103 (Subs ich may be f rms, www.cm	CASING/CEMEN OTHER: pertinent details, a le Completions: A 3645'. 3645'.	RILLING OPNS. P AI NT JOB nd give pertinent dates, ind Attach wellbore diagram of Attach wellbore diagram of Attach wellbore diagram of Plugging) re under	ND A
PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/22/12 Plug # 4- Spot 60sx Install dry hole mark I hereby certify that the infor grade tank has been/will be construction SIGNATURE Type or print name	Dr comple osed wor ended, Ta @ 2500' @ 250' u @ 250' u er	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ CI , Calculated TOC @ 225 , Tagged @ 963'. up to surface.	proved for p bility under C-103 (Subs ich may be f rms, www.cm	CASING/CEMEI OTHER: pertinent details, a le Completions: A 3645'. 3645'. 3645'. bond is retained pendi equent Report of Well found at OCD Web Pag anrd.state.nm.us/ocd.	RILLING OPNS. P AI NT JOB Image: P AI Ind give pertinent dates, indicates, indindited, indindited, indicates, indicates, indicates, ind	ND A \square \square cluding estimated date f proposed completion ify that any pit or below- OCD-approved plan \square . TE $\underline{4/8/12}$
PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any proport recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/22/12 Plug # 4- Spot 60sx Install dry hole mark I hereby certify that the information grade tank has been/will be constructed to start the start of	Dr comple osed wor ended, Ta @ 2500' @ 250' u @ 250' u er	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface. Ap Lia of C whi For	r state all j for Multip IBP set @ 4'. proved for p bility under C-103 (Subs ich may be f rms, www.cm e to the be guidelines [TITLE	CASING/CEMEI OTHER: pertinent details, a le Completions: A 3645'. 3645'. 3645'. bond is retained pendi equent Report of Well found at OCD Web Pag anrd.state.nm.us/ocd.	RILLING OPNS. P AI NT JOB Image: P Ai Ind give pertinent dates, ind Image: P Ai Attach wellbore diagram of Attach wellbore diagram of Attach wellbore diagram of P Ai Ing receipt Plugging) ge and belief. I further cert or an (attached) alternative for DA	ND A \square \square cluding estimated date f proposed completion ify that any pit or below- OCD-approved plan \square . TE $\underline{4/8/12}$
PULL OR ALTER CASING OTHER: 13. Describe proposed of starting any propor recompletion. 3/22/12 Plug # 1- RIH open 3/22/12 Plug # 2- Spot 25sx 3/22/12 Plug # 3- Spot 25sx 3/22/12 Plug # 4- Spot 60sx Install dry hole mark I hereby certify that the infor grade tank has been/will be construction SIGNATURE Type or print name	mation a ucted or c	MULTIPLE COMPL eted operations. (Clearly k). SEE RULE 1103. F ag TOC @ 3482', 5 ½ Cl , Calculated TOC @ 225 , Tagged @ 963'. up to surface. Ap Lia of C whi For	proved for p bility under C-103 (Subs fch may be f guidelines [FITLE	CASING/CEMEI OTHER: pertinent details, a le Completions: A 3645'. 3645'. 3645'. bond is retained pendi equent Report of Well found at OCD Web Pag anrd.state.nm.us/ocd.	RILLING OPNS. P AI NT JOB Image: P AI Ind give pertinent dates, ind Image: P AI Attach wellbore diagram of Image: P AI Attach wellbore diagram of Image: P AI Ind give pertinent dates, ind Image: P AI Attach wellbore diagram of Image: P AI Ind give pertinent dates, ind Image: P AI Attach wellbore diagram of Image: P AI Ind give pertinent dates, ind Image: P AI Ind give pertine dates, ind Image: P AI	ND A \square \square cluding estimated date f proposed completion ify that any pit or below- OCD-approved plan \square . TE $\underline{4/8/12}$