Office Enorgy Minor	of New Mexico rals and Natural Resources	Form C-103 Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 RECEIVEDSE	ERVATION DIVISION	<u>30-025-39355</u>
District III $-(505) 334-6178$ 1220 Sc	with St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 APR 1 1 2012 Santa	a Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO I DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name MCA Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Your Content of Well		8. Well Number 486
2. Name of Operator ConocoPhillips Company		9. OGRID Number 217817
3. Address of Operator _{3300 N} "A" St		10. Pool name or Wildcat
Midland, TX 79705		Malgamar; Grayburg-San Andres
4. Well Location		
	the South line and 560	
Section. 28 Township		NMPM County LEA
3996 KB	w whether DR, RKB, RT, GR, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANE TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE	DON C REMEDIAL WOR	ILLING OPNS.
OTHER: Isolate water leak & repair	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Job proposal is to be done in two parts. 1. RU wire line truck and TIH with plug and set in 1.875 XN X 1.791 nipple. RU pump truck to tubing and pressure test tubing to 550 psi, if tubing fails, close valve on tubing, RU pump truck to casing and pressure test packer/casing. Report findings to Production Specialist. If packer/casing test passed & tubing test failed, Leave plug in X nipple. Notify NMOCD of pending job before rigging up on well. RU WSU, NDWH, NUBOP, unlatch from on/off tool and scan tubing COOH, replace tubing as needed. R&R top of on/off tool, TIH pressure test tubing GIH. If packer/casing test fails, retrieve plug, TOOH with tubing and packer, scan tubing COOH, MI work string and tally, TIH with bit, scrapper and tubing to TPBD. Clean out any fill. TOOH with tubing, scrapper, and bit. TIH with packer/RBP, set RBP at 3000', pull up 1 jt set packer and pressure test RBP/packer to 550 psi for 30 mins, if RBP holds, RU pump truck to casing and pressure test casing/packer to 550 psi if casing fails, isolate leak. If casing/packer test passes, TIH retrieve RBP, TOOH with RBP, packer and tubing. Lay work string down. TIH with packer, on/off tool and injection tubing, pressure test tubing GIH, set packer @ +/- 3810', RU pump truck to casing and pressure test casing/packer if test passes, get off on/off tool, circulate packer fluid, and get back on on/off tool. NDBOP, NUWH, rig up pressure recorder and pressure test casing/packer to 550 psi for 30 mins, notify NMOCD of test, and give chart to Production Specialist. RD, clean up location.		
Spud Date:	tig Release Date:	
I hereby certify that the information above is true and com	plete to the best of my knowledg	e and belief.
SIGNAPURE Constants 1	TITLE Staff Regulatory Technicia	anDATÉ 04/11/2012
Type or print name <u>Rhonda Rogers</u> I For State Use Only		
	E-mail address: <u>rogerrs@conoco</u>	
APPROVED BY:	E-mail address: <u>rogerrs@conoco</u>	DATE

.

1

APR 1 9 2012