Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District 1 (575) 202 6161	nergy, Minerals and Natural Resources	Revised August 1, 2011
District II – (575) 593-6101 1625 N. French Dr., Hobbs, NM 88240 HOBBS C <u>District II – (575) 748-1283</u>		WELL API NO. 30-025-26785
811 S. First St., Artesia, NM 88210	DIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III (505) 334-6178 MAR 1 6 2 1000 Rio Brazos Rd., Aztec, NM 87410	2012 1220 South St. Francis Dr.	STATE STATE
<u>District IV</u> - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505 RECEIVE		· · · · · · · · · · · · · · · · · · ·
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DELPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name
PROPOSALS.) Gas Well 1. Type of Well: Oil Well Gas Well		8. Well Number 1
2. Name of Operator Endeavor Energy Resources, LP		9. OGRID Number 190595
3. Address of Operator 110 N. Marienfeld, Ste 200		10. Pool name or Wildcat
Midland, TX 79701.		SALADO DRAW; WOLFCAMP (GAS)
4. Well Location		
Unit Letter <u>G</u> : 1980 feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>EAST</u> line		
Section 17	Township 26S Range 33E	NMPM County LEA
11. E 3267	levation (Show whether DR, RKB, RT, GR. etc., 7.9	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A		
PULL OR ALTER CASING MUL	TIPLE COMPL	
13. Describe próposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC: For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
Sale gas up casing from 9/29/2011 - 10/12/2012		
Circulate well with 10.2 brine water x tubing free x drill out CIBP at 12050 ft. x Clean out to depth of 13075 ft. x ND BOP x Install production tree x Perforate tubing at 12780 ft. x Turn well to sales through tubing 10/18/2011.		
production tree x Perforate tubing at 12/80 ft. x 1 urn well to sales through tubing 10/18/2011.		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
and the fit	11/	
SIGNATURE	M TITLE Regulatory Analyst	DATE_03/13/2012
Type or print name Jan South	E-mail address: JSouth@eeronlin	e.com PHONE: (432)262-4014
For State Use Only		
APPROVED BY:	TITLE PERMOREHAN ENDER	DATE A PR 3 0 2012
Conditions of Approval (if any):		

APR 3 0 2012

.