Form 3160-5 (August 2007)

(Instructions on page 2)

## UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

MAY 0 9 2012 5. Lease Serial No.

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals RECEIVED					LC-032452-A		
					ian, Allottee or Tribe Na	me	
SUBMIT IN TRIPLICATE – Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well							
Oil Well Gas Well Other					8. Well Name and No.		
2. Name of Operator					Skelly Penrose A Unit #53		
Legacy Reserves Operating LP  3a. Address  3b. Phone No (include area code)					30-025-10698		
PO Box 10848, Midland, TX 79702 432-689-5200					10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M. for Survey Description)					ie Mattix;7RVR		
1980 FSL, 1980 FEL,					11. County or Parish, State		
Unit Letter J, Sec. 10, T-23-S, R-37-E  12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REI					Lea County, NM		
	PROPRIATE BOX(E	S) TO INDICATE			R OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION							
□v.e. er	Acidize	Deepen	Production (Start/Re	esume) 🔲 V	Vater Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat	Reclamantion	□ v	Vell Integrity		
Subsequent Report	Casing Repair	New Constructi			Other		
Final Abandonment Notice	Change Plans	Plug and Aband	on Temporarily Abando	on			
13. Describe Proposed or Completed (	Convert to Injection	Plug Back	Water Disposal	_			
03/29/12 Dug out cellar. NU 03/30/12 Replace wellhead a 04/02/12 NU BOP. POH w/ 04/03/12 RIH w/ tbg and no fluid. Spotted 50 sx cement @ 2525-2345. I 04/04/12 Tagged plug @ 23 to 1500 psi on casing. POH @ 1067'. Perf'd casing @ 20 Spotted 30 sx cement @ 250 04/05/12 Tagged plug @ 110 to surface. Rigged down 04/13/12 Moved in welder a	and new piece of cathg and packer. otched collar to 351 on top of plug @ 35 POH w/thg. 90'. POH. Set pack w/ packer. RIH w/ 10'. Set packer @ 36 -70POH. 0'. Perf'd casing @ n moved off.	osing,  0'. POH. RIH v  500-3100. POH  er @ 30'. Press  tbg to 1280'. Sp  4'. Pump in rate  60'. Pressured	to 1800'. WOC. Tagge ured up on plug 700 p otted 35 sx cement @ e of 1/2 bbl per minute up on casing. RIH ope	ed plug @ 3 si. Perf'd ca 1280-1070. e @ 1500 ps en ended ar	asing @ 1230'. P POH. WOC. Ta i. RIH open end and spotted 30 sx	ressured up agged plug led to 250'.	
04/13/12 Moved in welder and backhoe. Dug out cellar. Cut off well head. Welded on above ground Dry Hole Marker.  Back filled cellar. removed dead men. cleaned location and moved off.							
Accepted as to plugging of the well bore.  Liability under bond is retained until  Surface restoration is completed.				DI	RECLAMATION DUE 1040-1		
<ol> <li>I hereby certify that the foregoing is tr Name (Printed/Typed)</li> </ol>	rue and correct.)	1		·			
Berry Johnson	\ /		Title Operations	Superint	rendent		
	VI//			ACC	EDTEN EN	D DEMAR	
Signature Dlun	- mi		Date 04/24/2012	<u> </u>	LLILDIO	N NLOUN	
()	/ IHIS SPACE	FOR FEDERA	L OR STATE OFFIC	E USE			
A					Date APR 2 6	2012	
Approved by Conditions of approval, if any, are attached	l. Approval of this notice doe	s not warrant or certify	Title		Date APR 26	2012	
the applicant holds legal or equiable fule to applicant to conduct operations thereby	o those wights in the subject.	ease which would entit	le the Office	ļ	Lam		
Title 18 U.S.C. Section 1001 and Title 43 U.S. States any false, fictitions or fraudulent states	J.S.C. Section 1212, make it	a crime for any person	knowingly and willfully to make	to any departine	apar adduchlourachthing	MANAGEMENT	