Submit 3 Copies To Appropriate District State of New Me	
Office State of New Me	
District I 1625 N. French Dr., Hobbs, NM 88240	ral Resources Revised March 25, 1999 WELL API NO.
District II	
1301 W. Grand Avenue, Artesia, NM 87210 OIL CONSERVATION	DIVISION 5 Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Fran	STATE STATE
District IV Santa Fe, INM 87	505 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	V-2522
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU	IG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	R SUCH FOX "A" STATE
PROPOSALS.) 1. Type of Well:	
Oil Well S Gas Well Other	
2. Name of Operator	8. Well No.
LAYTON ENTERPRISES, INC.	3
3. Address of Operator 3103 79th St.	9. Pool name or Wildcat
LUBBOCK, TEXAS 79423	Allison Penn
4. Well Location	
Unit Letter N : 660 feet from the South	line and 1980 fast from the West line
Unit Letter N : 660 feet from the South	line and <u>1980</u> feet from the <u>West</u> line
Section 2 Township 9S Rat	nge 36E NMPM County Lea
10. Elevation (Show whether DR	
11. Check Appropriate Box to Indicate Na	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🔲 PLUG AND ABANDON 🗔	REMEDIAL WORK
PULL OR ALTER CASING 🔲 MULTIPLE 🔲	CASING TEST AND
COMPLETION	CEMENT JOB
	CEMENT JOB There is a constraint of the constrai
OTHER:	OTHER: PLUG BACK
OTHER: 12. Describe proposed or completed operations. (Clearly state all per	OTHER: PLUG BACK
OTHER: 12. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 1103. For Multiple C	OTHER: PLUG BACK 🔀
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple Correcompilation. Pulled pumping equipment from the pumping equipment	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625'
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B	OTHER: PLUG BACK innent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9#
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5 ¹ / ₂ "
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casing casing @5100' in order to pull & re-run casing c	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5 ¹ / ₂ " g to cement across San Andres Zone.
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½"
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools.	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5 ¹ / ₂ " g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5 ¹ / ₂ " 100') Milled top down to 4416' - Ran
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment frow w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study.	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools.	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12./10/04 - 2./03.05	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment frow w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study.	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12./10/04 - 2./03.05	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12./10/04 - 2./03.05	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12./10/04 - 2./03.05	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: Image: the start of the start	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: 12. Describe proposed or completed operations. (Clearly state all performed starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12/10/04 - 2/03/05 Per DL	OTHER: PLUG BACK internet details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off est of my knowledge and belief. President DATE 476-7958 CLC3
OTHER: Image: Classical state of starting any proposed work). SEE RULE 1103. For Multiple C or recompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12./10/04 - 2/03/05 Per DL	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date completions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: Image: Construct of the starting any proposed work). SEE RULE 1103. For Multiple Construction of the starting any proposed work). SEE RULE 1103. For Multiple Construction. w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. (95200' w/5 sks casing (95100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. 12/10/04 - 2/03/05 Per DL Per DL Increase of the information above is true and complete to the b SIGNATURE Donald R. Layton	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off
OTHER: Image: Contract of the proposed of completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple Contrecompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. (25200' w/5 sks casing (25100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Contract of the pulled casing Contract of the pulled casing Contract of the pulled casing and recovered 4308' (pulled apa overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Contract of the pulled contract of the pulled casing and recovered 4308' (pulled apa overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Contract of the pulled casing Contrect of the pulled casing Contract of the pulled casing Contract o	OTHER: PLUG BACK
OTHER: Image: Contract of the proposed of completed operations. (Clearly state all performed of starting any proposed work). SEE RULE 1103. For Multiple Contrecompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. (25200' w/5 sks casing (25100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Contract of the pulled casing Contract of the pulled casing Contract of the pulled casing and recovered 4308' (pulled apa overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Contract of the pulled contract of the pulled casing and recovered 4308' (pulled apa overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Contract of the pulled casing Contrect of the pulled casing Contract of the pulled casing Contract o	OTHER: PLUG BACK internet details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5½" g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5½" 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off est of my knowledge and belief. President DATE 4 TO THE T
OTHER: Image: Complete the information above is true and complete to the best of starting any proposed work). SEE RULE 1103. For Multiple Contrecompilation. Pulled pumping equipment from w/5 sks cement on top (Approx 50') to cover B mud laden fluid. Set C.I.B.P. @5200' w/5 sks casing @5100' in order to pull & re-run casin Pulled casing and recovered 4308' (pulled apa overshot - jarred out 3 single joints (approx overshot - caught fish & jarred for four days tubing & tools. Well shut in for further study. Image: Complete to the best of the information above is true and complete to the best of the pulled complete to the best of the information above is true and complete to the best of the pulled complete to thetext of the pulled complete to the pulled co	OTHER: PLUG BACK inent details, and give pertinent dates, including estimated date ompletions: Attach wellbore diagram of proposed completion m well. Set C.I. Bridge Plug @9625' ough C perfs @9675 - 89'. Loaded hole w/9# cement. Ran chem-cutter & cut 5 ¹ / ₂ " g to cement across San Andres Zone. rt @ old casing bowl). Ran 8 1/8 x 5 ¹ / ₂ " 100') Milled top down to 4416' - Ran - unable to pull casing - Backed off while the pull casing - Backed off - unable to pull casing -

1

.

24	Allison	Upper	Penn
----	---------	-------	------