Form 3160-5 (September 2001)	New Mexico Oil Conservation Division, UNITED STATES 1625 N. French Drive DEPARTMENT OF THE INTERIOR Hobbs, NM 88249 BUREAU OF LAND MANAGEMENT			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				Lease Serial No.
				MNM078148
				ff Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side				f Unit or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Other				
2. Name of Operator				Well Name and No.
BTA Oil Producers				ench, 9004 JV-P, #2
3a. Address		3b. Phone No. (include area code)		API Well No.)-025-31118
104 S. Pecos; Midland, TX 79701		(432) 682-3753		Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T, R., M., or Survey Description) UL -I-, Sec. 24, T18S, R32E 1980' FSL & 510' FEL				orbin, Wolfcamp South County or Parish, State
				ea Co., NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION				
TIPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resu	ime) 🔲 Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair Change Plans		Recomplete	Other
Final Abandonment Notice	Convert to Injection	_	Temporarily Abandon Water Disposal	
Attach the Bond under which the following completion of the inv testing has been completed. Fin determined that the site is ready BTA proposes to recomplete this 1. MI & RU CU. RIH +/- 9500'. 2. Spot 200 gal 10% acetic acid a 3. RU WL. Run GR - CCL from 4. Dmp 40' cmt on CIBP at 1105 5. RIH w/tbg & pkr. Set pkr +/- 9 6. Breakdown perfs. Swab back 7. Frac as follows: A w/1,200 ga 8. Swab back load to evaluate. 9. If zone is commercial place on 10. If upper zone is commercial a 11. Place well on production. ENE	the work will be performed or provivolved operations. If the operation r nal Abandonment Notices shall be to for final inspection.) s well to the South Corbin (Bone at 9415'. POH w/ tbg. a 9500' to 4500'. Correlate. Perf 50'. RD WL 9200'. cload to evaluate. als 7 ½% HCl acid + 31,000 gals an production. If zone is marginal and RBP was set above lower zo PROVED FOR	de the Bond No. on file with Bl esults in a multiple completion of filed only after all requirements Spring) Field as follows: Second Bone Spring Sand at gel + 94,000 lbs sand. or non-productive, add'l pro ne, rel pkr and POH w/tbg & MONTH PERIOD	M/BIA. Required sub or recompletion in a ge including perfermation SUB ST ST ST ST ST ST ST ST ST ST ST ST ST	pposed work and approximate duration thereof ical depths of all pertinent markers and zones. sequent reports shall be filed within 30 days winterval, a Form 3160-4 shall be filed once a, have been completed, and the operator has APP 520VED APR 52 2005 3 - 9415' with 4" prem charges, 4 JSPF. GARY GOURLEY EVENUEUM ENGINEER ATTACHED.)
14. 1 hereby certify that the foregoin Name (PrintedlTyped)	ng is true and correct			
Pam Inskeep Title Regulatory Administrator				
Signature Pan Maker Date 02/14/2005				
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE USE	K25
Approved by (Signature)	an te a stand a second stand stand a second stand s	Name (Printed/Type	d)	Title
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				
	itle 43 U.S.C. Section 1212, make it ent statements or representations as t	a crime for any person knowing o any matter within its jurisdiction	ly and willfully to mak	te to any department or agency of the United
(Continued on next page)				

Attachment to 3160-5 BTA Oil Producers French, 9004 JV-P, #2 30-025-31118 February 14, 2005

Additional detail to Item 13:

Marginal:

- 1. Rel pkr & POH w/tbg & pkr.
- 2. GIH w/RBP. Set RBP @ +/- 8700'. Spot 2 Sx sand on RBP.
- Spot 250 gal 10% Acetic. POH. Perf w/4" prem charges @ 8414 8436'; 8476 8484'; 8486 8488'; 8577 8584'; 8621 8630' with 2 JSPF.

. ...

- 4. RIH w/tbg & pkr. Set pkr @ +/- 8350'.
- 5. Breakdown perfs. Swab back load to evaluate.
- 6. Frac as follows: A w/1200 gal 7 1/2% HCl + 31000 gal gel + 94000 lbs sand.
- 7. Swab back to evaluate.

Non-Productive: 1. Set CIBP @ 9300'. Cap w/40' cmt.

- Spot 250 gal 10% Acetic. POH. Perf w/4" prem charges @ 8414 8436'; 8476 8484'; 8486 8488'; 8577 8584'; 8621 8630' with 2 JSPF.
- 3. RIH w/tbg & pkr. Set pkr @ +/- 8350'.

The product of the second state of the state of

- 4. Breakdown perfs. Swab back load to evaluate.
- 5. Frac as follows: A w/1200 gal 7 1/2% HCl + 31000 gal gel + 94000 lbs sand.
- 6. Swab back to evaluate.