

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

APACHE CORPORATION

3a. Address

6120 S. YALE, STE. 1500 TULSA, OK 74136

3b. Phone No. (include area code)

918-491-4980

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

SEC 10-21S-37E

2375 FSL & 605 FEL

5. Lease Serial No.

NMNM2512 Fee

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

NMNM72602A

8. Well Name and No.

NEDU # 420

9. API Well No.

30-025-37028

10. Field and Pool, or Exploratory Area

EUNICE; BLI-TU-DR, NORTH

11. County or Parish, State

LEA

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other SPUD, SURF. CSG.,

TD, LOG, PROD. CASING

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Spud 3/17/05 SPUD 12 1/4" HOLE - DRILL & SURVEY FROM 40-876.

3/18/005- DRILL 876-964 SURVEY @ 936= 0.5 DRILL 964-1195 CIRCULATE FOR CSG DROP TOTCO - POH W/ BIT RIH 27 JTS. 1198.92' 8 5/8" 24# J55 ST&C CSG W/ 9
3/31/2005 CENTRALIZERS BJ CMT. SHOE @ 1195- FC @ 1147 W/ 375 SX 35.65 POZ W/ 6% GEL + 2% CACL + 1/4# CF = 126 BBLs. 12.7# SLURRY W/ 1.88 YIELD & 200
SX CLASS C + 2% CACL + 1/8# CF = 48 BBLs. 14.8# SLURRY W/ 1.35 YIELD - PLUG BUMPED & HELD - CIRC 162 SX CMT. TO PIT WOC CUT OFF CSG. -
WELD ON HEAD NU BOP EQUIP. TEST CSG. CHOKE MANIFOLD- BLIND RAMS - PIPE RAMS 1500# - ANNULAR 1000# CHANGE PUMP LINERS CHANGE PUMP LINERS RIH
W/ DRILL COLLARS SLIP & CUT 120' DRILLING LINE RIH W/ DRILL PIPE REPAIR #2 PUMP DRILL CMT. & EQUIP. D RILL 1195-1706 URVEY @ 1675= 0.75 DRILL 1706-2079
REPAIR GENERATOR DRILL 2079-2112 SURVEY @ 2079= 2.25 DRILL 2112-2296 SURVEY @ 2266= 2.75 DRILL 2296-2419 RIG UP SCIENTIFIC - RAN GYRO DRILL 2419-2500
CIRCULATE POH W/ BIT PICK UP DIRECTIONAL TOOLS RIH W/ BIT #3 & DIRECTIONAL TOOLS RIGGING UP SCIENTIFIC - SLIDE DRILL 2500-2520 DRILL 3947-3978 PULL 3
JTS. - REMOVE SCREEN - RIH DRILL 3978-4040 DRILL 5007-5097 SURVEY - MWD MAKE UP MWD TOOLS- START RIH RIH W/ BIT UNPLUG 2 DRILL COLLARS- FULL OF
RUST & SCALE RIH W/ BIT DRILL 5097-5164 DRILL 5164-5227 DRILL 6824-6914 SURVEY - MWD - CIRCULATE FOR LOGS CIRCULATE FOR LOGS START POH REPAIR IRON
ROUGHNECK POH W/ BIT - LAY DOWN MWD TOOLS HALLIBURTON RAN COMPENSATED SONIC LOG 6864-5150; DUAL LATEROLOG MICRO-SFL 6910-5150; DUAL
SPACED NEUTRON SPECTRAL DENSITY 6830-200 RIH 134 JTS. 5973.57' 5 1/2" 17# J55 LT&C CSG. + 1 JT. 14.34' 5 1/2" 17# L80 LT&C CSG W/ 23 CENTRALIZERS + 21 JTS.
935.60' 5 1/2" 17# L80 LT&C CSG. BJ CMT. SHOE @ 6914- FC @ 6867 W/ 700 SX 50:50 POZ W/ 10% GEL + 5% SALT + 1/8# CF = 304 BBLs. 11.8# SLURRY W/ 2.44 YIELD & 350
SX 50:50 POZ W/ 2% GEL + 5% SALT = 81 BBLs. 14.2# SLURRY W/ 1.29 YIELD - DISPLACE W/ 159 BBLs. 2% KCL WATER- CIRC 160 SX. CMT. TO PIT RIG DOWN BJ NO BOP -
SET SLIPS - CUT OFF CSG-

RELEASE RIG @ 6:00 AM 3-31-2005


14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

LANA WILLIAMS

Title DRILLING CLERK II

Signature



Date 4/12/2005

ACCEPTED FOR RECORD THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by


DAVID R. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)