

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised August 1, 2011

MAY 07 2012

RECEIVED

WELL API NO.	30-041-20924
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	LH 6324 0000
7. Lease Name or Unit Agreement Name	Mesa 26 State
8. Well Number	1
9. OGRID Number	220247
10. Pool name or Wildcat	Wildcat (Montoya)
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	4248 GL

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator	GeoSurveys, Inc.
3. Address of Operator	218 South Leggett Drive, Abilene, Texas 79605
4. Well Location	Unit Letter L : 1400 feet from the S line and 1100 feet from the W line Section 26 Township 2N Range 29E NMPM County Roosevelt
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4248 GL	

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of
C-103 (Subsequent Report of Well Plugging)
which may be found at OGD Web Page under
Forms, www.emnrd.state.nm.us/ogd

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTIFICATION TO:

SUBSEQUENT REPORT OF:

ABANDON ☐
☐
☐
☐

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER ☐

OTHER: ☐

13. Describe proposed or completed work (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 9.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4-19-12 Tag liner w/ gauge ring, set 5 1/2" CIBP @ 6882'.
4-23-12 Tag CIBP @ 6882'. Spot 25 sx 'C' 6880'-6822'. RU BOP.
4-24-12 Cut casing at 4835' and lay down casing.
4-25-12 Spot 40 sx 'C' w/ 2% cc @ 4885'. WOC. Tag @ 4716'. Spot 75 sx 'C' w/ 2% cc @ 2765'
4-26-12 Tag plug at 2470', perf at 1100'. Set packer @ 791', squeeze w/ 40 sx 'C' w/ 2%cc
WOC, tag @ 1005'. Perf at 430', set packer at 156', break circ. out annulus, pump 50 sx
'C' w/ 2%cc. WOC.
Tag plug @ 295', Perf at 60', set packer at 20'. Pump 35 sx 'C' to fill inside and out.
5-1-12 Dug out cellar, cut off head, Installed dry hole marker, cut off anchors,
cleaned location.

Gandy's expects to start hauling pits 5-14-12.

Spud Date.

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Calvin Donaghy TITLE President DATE 5-7-2012

Type or print name _____ E-mail address _____ PHONE: _____
For State Use Only

APPROVED BY: Donaghy TITLE Staff DATE 5-8-2012
Conditions of Approval (if any).

MAY 08 2012