w Mexico Oil Conservation Division, District 1 1625 N. French Drive

Hobbs, NM 88240 FORM APPROVED Form 3160-5 UNITED STATES OMB No. 1004-0137 (August 2007) HOBBS OCD DEPARTMENT OF THE INTERIOR Expires: July 31, 2010 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. NM-04385 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. RECEIVED 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. X Oil Well Gas Well Other Rock Queen Unit #33 2. Name of Operator 9. API Well No. Celero Energy II, LP 30-005-00890 10. Field and Pool or Exploratory Area 3a. Address 3b. Phone No. (include area code) 400 W. Illinois, Ste. 1601 Midland TX 79701 (432)686-1883 Caprock; Queen 4. Location of Well (Footage, Sec., T.R., M., oy Survey Description) Sec 27, Unit O, T13S, R31E 11. Country or Parish, State Chaves, NM 990' FSL & 1650' FEL 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off X Notice of Intent Fracture Treat Well Integrity Alter Casing Reclamation X Other Run MIT to Casing Repair New Construction Recomplete Subsequent Report extend TA Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal status 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones, Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Celero Energy II would like to run a MIT to extend the TA status for a 1 yr period. 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Lisa Hunt Title Regulatory Analyst Signature Date 03/16/2012 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by MAY 0 1 2012 PETROLEUM ENGINEER Conditions of approval, if any, are attached. roval of this notice does not warrant or certify that the applicant holds legal or equitable title to those y person knowingly and willfully to make to any department or agency of the United States any false, MIT Was Done On 04-10-2012 Subject To The Attached Standard Conditions Of Approval-

Temporary Abandonment Of Wells On Federal

Lands.

MAY n 9 2012

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)