
Submit 1 Copy To Appropriate District Office State of New Mexic	o Form C-103
Submit 1 Copy To Appropriate District Office District 1 – (575) 393-6161 1625 N French Dr., Hobbs, NM District II – (575) 748-1283 State of New Mexic Energy, Minerals and Natural	Resources Revised August 1, 2011 WELL API NO.
1625 N French Dr., Hobbs, NM	WELL API NO. 30-025 - 05846
811 S. First St., Artesia, NM 88210 20 20 20 11 CONSERVATION D	VISION 5 Indicate Type of Lease
1000 Big Berger Bd. Agree NM SWIO	STATE N FEE
District IV - (505) 476-3460 Santa Fe, NM 8750	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	B1581
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B	BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR S PROPOSALS)	
1. Type of Well: Oil Well Gas Well Other	8. Well Number 104
2. Name of Operator OXY USA WTP Limited Partnership	9. OGRID Number 192463
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 50250 Midland, TX 79710	Eumont Yates TR Qn
4. Well Location	
Unit Letter 1330 feet from the South	line and 1650 feet from the west line
Section 36 Township 195 Range	37E NMPM County Lea
11. Elevation (Show whether DR, RK	(B, RT, GR, etc.)
3559	
12. Check Appropriate Box to Indicate Natu	re of Notice, Report or Other Data
NOTICE OF INTENTION TO	OLIDOFOLIËNT DEDORT OF
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ AB	SUBSEQUENT REPORT OF: EMEDIAL WORK ALTERING CASING
<u> </u>	DMMENCE DRILLING OPNS. P AND A
	ASING/CEMENT JOB
DOWNHOLE COMMINGLE	
OTHER: MIT-TA Status & O	
OTHER: MILL IN STATUS RE LO	THFR:
OTHER: MIT-IA Status II O	THER:
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F	nent details, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pert	nent details, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F	nent details, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	ment details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. 	ment details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit # 104 30-025-05344 TD- 3525 PBTD- 3195 Perfs- 3550-35	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 poorarily Abandon Status Approval. This unit is
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit # 104 30-025-05344 TD- 3525 PBTD- 3195 Perfs- 3550-35	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 poorarily Abandon Status Approval. This unit is
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3255 Coorarily Abandon Status Approval. This unit is initiating the waterflood.
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	ment details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 corarily Abandon Status Approval. This unit is initiating the waterflood.
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	ment details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 corarily Abandon Status Approval. This unit is initiating the waterflood.
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 porarily Abandon Status Approval. This unit is initiating the waterflood. Vance. pressure test casing to 500# for 30 min.
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 porarily Abandon Status Approval. This unit is initiating the waterflood. vance. pressure test casing to 500# for 30 min. Condition of Approval: Notify OCD Hobbs
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 porarily Abandon Status Approval. This unit is initiating the waterflood. Vance. pressure test casing to 500# for 30 min.
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	nent details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 porarily Abandon Status Approval. This unit is initiating the waterflood. vance. pressure test casing to 500# for 30 min. Condition of Approval: Notify OCD Hobbs
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit # 104 30-025-05344 TD-3525 PBTD-355 Perfs-355-35 OXY USA WTP LP respectfully requests to extend the Tem currently being evaluated for possible infill drilling and re- 1. Notify NMOCD of casing integrity test 24hrs in advanced to the completion of the comp	condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	constraint details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 CIBP-3256 COORDINATE COORDINATE COORDINATE Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart Condition of Machine Mit Test & Chart
13. Describe proposed or completed operations. (Clearly state all pert of starting any proposed work). SEE RULE 19.15.7.14 NMAC. F proposed completion or recompletion. East Eumont Unit #	constraint details, and give pertinent dates, including estimated date for Multiple Completions: Attach wellbore diagram of CIBP-3256 CIBP-3256 COORDINATE COORDINATE COORDINATE Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart Condition of Machine Mit Test & Chart

OXY USA WTP LP East Eumont Unit #104 API No. 30-025-05846



CIBP @ 3750'