

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-32624
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name William Weir
8. Well Number 6
9. OGRID Number
10. Pool name or Wildcat Monument - ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Chevron USA Inc

3. Address of Operator
15 Smith Rd, Midland, TX 79705

4. Well Location
Unit Letter N : 425 feet from the South line and 1830 feet from the West line
Section 23 Township 19-S Range 36-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL N Sect 23 Twp 19S Rng 36E Pit type Steel Depth to Groundwater 45 Distance from nearest fresh water well Over 1000'
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;
425 feet from the South line and 1830 feet from the West line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 hours Prior to MI & RU.
2. Set 5 1/2 CIBP @ 7175 Spot 25sx plug 7175-7000 (Lateral-ABO) WOC Tag 6992.
3. Displace hole w/MLF 9.5 # Brine w/12.5# gel P/BBL.
4. Spot 25sx plug 4400-4200 (San Andres)
5. Spot 25sx plug 2900-2700 (Yates, B-Salt) WOC Tag 2709.
6. Spot 25sx plug 1400-1200 (9 5/8 Shoe, T-Salt) WOC Tag 1197
7. Spot 35sx plug 300-Surf (Surf) WOC Tag @ Surf.

8. Install Dry Hole Marker 4-21-05.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE Consultant DATE 4-21-05

Type or print name Timmy Bagley E-mail address: Telephone No. 432-561-8600

(This space for State use)

APPROVED BY [Signature] TITLE DISTRICT SUPERVISOR/GENERAL MANAGER DATE APR 28 2005
Conditions of approval, if any: Approved as to plugging of the Well Bore.
Liability under bond is retained until surface restoration is completed.