Submit 1 Copy To Appropriate District Office.	State of New Mexico	Form C-103
<u>District 1</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO.
1625 N French Dr, Hobbs, NM 88240 <u>District (I</u> – (575) 748-1283	© OH CONGERNATION DIVIGION	30-025-07679
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 R10 Brazos Rd , Aztec, NM 87410 District IV – (505) 476-3460 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1000 Rio Brazos Rd , Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S St Francis Dr , Santa Fe, NJUN 187505	Sunta re, run o rece	6. State Off & Gas Lease No.
SUNDRY NOTICE OF REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPERTY OF TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		South Hobbs (G/SA) Unit
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned		8. Well Number 68
2. Name of Operator		9. OGRID Number: 157984
Occidental Permian Ltd.		10 P. I. Will (0/04)
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		10. Pool name or Wildcat Hobbs (G/SA)
4. Well Location		
	feet from theNorth line and2310	
Section 10 Township 19S Range 38E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3623' KB		
12. Check Ap	propriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTI	ENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERI		
 -	CHANGE PLANS 🔲 COMMENCE DR	_
·	MULTIPLE COMPL CASING/CEMEN	T JOB
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
	ed operations. (Clearly state all pertinent details, an). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.	
 POOH with tbg and pkr. 		
2. TIH w/ bit and clean out to 4204'. TOH w/ bit.		
3. RIH w/ 4 ½" CIBP and set at 4154'. Cap with 35' of cmt.		
4. Circulate 10# MLF.		
5. Spot 30 sx of cmt from 2919-3019'. WOC. Tag.		
6. Spot 50 sx of cmt from 1548-1748'. WOC. Tag.		
	and circulate to surface. Top well-off as necess	sarv.
·	dry hole marker with labeling.	7
9. Clean up location, remove	anchors	
	The Oil Conservat	ion Division Must be notified
Smul Data	24 Hours prior to t	he beginning of plugging operations.
Spud Date:	Rig Release Date:	
<u> </u>		
I hereby certify that the information about	ove is true and complete to the best of my knowledg	e and belief.
\mathcal{N}_{\bullet} , \mathcal{N}_{\bullet} , \mathcal{N}_{\bullet} , \mathcal{N}_{\bullet} , \mathcal{N}_{\bullet}		
SIGNATURE PLANTY LA JOHN ASST. 6/15/2012		
Type or print name WENDY A JOHNSON E-mail address WENDY _ JOHNSON @ OXY, COM		
For State Use Only 806-592-6280		
APPROVED BY TITLE STAFF NGS DATE 27-2017		
Conditions of Approval (if any):		
		JUN 2.8 2012

Occidental Permian Ltd. SHU 68 30-025-07679 Lea Co, NM Perf at 300' sqz well and circulate to surface 13" 50# @220 Cement w/ 200 sx Cırculate Perf 7" at 1300' Sqz with 150 sx Circulate Perf 7" at 1660 Sqz with 300 sx (TOC 1338') 9 5/8" 36# @ 1659 Cmt w/ 375 sx 50 sx of cmt from 1548-1748' Perf 7" at 1820' Sqz with 500 sx (TOC 700') Perf 7" at 2050 Sqz with 750 sx (TOC 1856' 30 sx of cmt from 2919-3019' Perf 7" at 2952' Sqz with 750 sx (TOC 2084') 7" 22# @ 4070 Cmt w/ 350 sx · TOC 3150' CBL CIBP @ 4154' Cap with 35' of cmt Perforations 4204-4221' 4 1/2" 10 6# @ 4245 w/700 sx TOC 300' CBL