

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS
HOBBS OCD

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

JUL 03 2012

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

RECEIVED

SUBMIT IN TRIPLICATE

1. Type of Well

Oil Gas
☒ Well ☐ Well ☐ Other

2. Name of Operator

STRATA PRODUCTION COMPANY

3. Address and Telephone No.

P. O. Box 1030
Roswell, New Mexico 88202-1030 505-622-1127

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 2310' FEL
Section 15-22S-32E

5. Lease Designation and Serial No.

NM-27805

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Lechuza Federal #3

9. API Well No.

30-025-31753

10. Field and Pool, or Exploratory Area

Livingston Ridge Delaware East

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ OTHER

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Approved as to plugging of the well bore.
Liability under bond is retained until
completion of the work.

13. Description of Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/15/05: Tag CIBP at 7182'. Spot 15 sxs on top - 7040'. Spot 40 sxs at 4700 - 4320'. Tag.

12/19/05: Perforate at 1200'. Squeeze 120 sxs at 1200 - 868'. Tag. Perforate at 720'.

Squeeze 80 sxs at 720 - 493'. Tag.

12/20/05: Perforate at 60'. Squeeze 20 sxs to surface. Csg full. Install dry hole marker. Circulate 10# mud. Move out.

APPROVED

JAN 12 2006

GARY GOURLEY
PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Signed Kurt M. Bitt

Title Production Records

Date 12/23/05

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

MSSB/OCD 7/5/2012

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

* See Instruction on Reverse Side