

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

HOBBS OGD
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
JUL 11 2012

SUNDRY RECEIPTS AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-05868
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>Injection</u>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator <u>OXY USA WTP Limited Partnership</u>		6. State Oil & Gas Lease No. <u>B 2330</u>
3. Address of Operator P.O. Box 50250 Midland, TX 79710		7. Lease Name or Unit Agreement Name <u>East Eumout Unit</u>
4. Well Location Unit Letter <u>G</u> : <u>1998</u> feet from the <u>north</u> line and <u>1975</u> feet from the <u>east</u> line Section <u>2</u> Township <u>20S</u> Range <u>37E</u> NMPM County <u>Lea</u>		8. Well Number <u>112</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3601'</u>		9. OGRID Number <u>192463</u>
		10. Pool name or Wildcat <u>Eumout Yates TRQN</u>

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: CIBP - MIT - TA Status ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/2/12 MIRU PU, NDWH, Unset Pkr, NUBOP, POOH w/ tbg & pkr. RIH w/ 4-1/4" bit, 4-1/4" string mill to 3782'.
7/3/12 POOH w/ tbg, bit & mill. RIH w/ 5" CIBP & set @ 3750'. Plug would hold compression but would slide up hole, got off of plug @ 3730'. Loaded & tested CIBP, plug held, but formation will hold 900# and not bleed off. POOH.
7/5/12 RIH w/ 5" CIBP & tagged other CIBP @ 3730'. PUH to 3725 & set CIBP. Loaded & tested to 500 psi, Held OK. Displaced well w/ pkr fluid, POOH. ND BOP. NUWH.
7/6/12 Pressure to 580# for NMOCD MIT chart, held OK, RDPU.

This Approval of Temporary Abandonment Expires 7-6-2013

Spud Date:

Rig Release Date:


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Regulatory Advisor DATE 7/10/12

Type or print name _____ E-mail address: david_stewart@oxy.com PHONE: 432-685-5717


For State Use Only

APPROVED BY: [Signature] TITLE Dist. MGR DATE 7-12-2012
Conditions of Approval (if any):



OXY USA WTP LP - Current
East Eumont Unit #112
API No. 30-025-05868

12-1/4" hole @ 370'
8-5/8" csg @ 370'
w/ 300sx-TOC-Surf-Circ



7-7/8" hole @ 3900'
5-1/2" csg @ 3898'
w/ 800sx-TOC-2190-TS

CIBP @ 3730' - 3725'

PB-3893'

Perfs @ 3800-3860'

TD-3900'