

Submit I Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88201
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87401
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-27648 ✓
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-8077
7. Lease Name or Unit Agreement Name STATE 731 ✓
8. Well Number 3 ✓
9. OGRID Number 012444 ✓
10. Pool name or Wildcat Undesignated Jalmat/Yates/7 Rivers
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3558' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐

2. Name of Operator
PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING

3. Address of Operator
P.O. BOX 928, ANDREWS, TEXAS 79714-0928

4. Well Location
Unit Letter H : 1980 feet from the NORTH line and 330 feet from the EAST line
Section 26 Township 22S Range 35E NMPM LEA County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Temporary Abandoned ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIT Chart Attached

7-9-2012: Move in pulling Unit. LD all rods. POOH with tubing.

7-10-2012: Run CIBP and set at 3718'. Circulate hole with fresh water and packer fluid. Test plug and casing to 580#- good. POOH and LD all tubing. Load hole. RU chart and run 30 minute Pressure test. Beginning pressure 550#. Ending pressure 540#

WELL IS TEMPORARILY ABANDONED AS OF 07/10/2012

This Approval of Temporary
Abandonment Expires 7-10-2014

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. Dale Kelton TITLE PRESIDENT DATE July 11, 2012

Type or print name C. Dale Kelton E-mail address: providenceenergy@suddenlink.net PHONE: 432-661-1364

For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr DATE 7-16-2012
Conditions of Approval (if any):

JUL 18 2012

