

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

HOBBS OGD

OIL CONSERVATION DIVISION

JUL 20 2012  
20 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Form C-103

Revised August 1, 2011

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-28363
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Occidental Permian Ltd.		6. State Oil & Gas Lease No.
3. Address of Operator HCR 1 Box 90 Denver City, TX 79323		7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit Section 9
4. Well Location Unit Letter <u>G</u> : <u>2475</u> feet from the <u>North</u> line and <u>2425</u> feet from the <u>East</u> line Section <u>9</u> Township <u>19S</u> Range <u>38E</u> NMPM Lea County		8. Well Number <u>160</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3660.8 GL		9. OGRID Number: <u>157984</u>
		10. Pool name or Wildcat Hobbs (G/SA)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) POOH with prod equip.
- 2) Clean out to 4268
- 3) Perforate from 4131-38', 4145-52'.
- 4) Acid treat with 2770 gal.
- 5) RIH with prod equipment
- 6) Return well to production

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve Sneed TITLE Lift Specialist DATE 7/12/12

Type or print name Steve Sneed E-mail address: steve\_sncad@oxy.com PHONE: 806-592-6312

For State Use Only

APPROVED BY: [Signature] TITLE DBT DATE 7-23-2012  
Conditions of Approval (if any):

JUL 23 2012