Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103			
Office District I	Energy, Minerals and Natural Resources	October 13, 2009			
1625 N. French Dr., Hobbs, NM 88248 CCD		WELL API NO.			
District II	OIL CONSERVATION DIVISION	30-025-40335			
1301 W. Grand Ave., Artesia, NM 88210 District III		5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd, Aztec, NUR 4101 2017 District IV	1220 South St. Francis Dr.	STATE FEE			
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM					
87505	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS	East Caprock SWD				
	ON FOR PERMIT" (FORM C-101) FOR SUCH	Last Caprock 5 WD			
PROPOSALS.)	8. Well Number 5				
1. Type of Well: Oil Well Ga					
2. Name of Operator	9. OGRID Number				
PALADIN ENERGY	164070				
3. Address of Operator	10. Pool name or Wildcat				
10290 Monroe Drive, Suite 301, Dallas	Caprock:Devonian, East (8930)				
4. Well Location					
Unit Letter B : 930 feet from the North line and 2290 feet from the East line					
Section 14	Township 12S Range 32E	NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
·	4356' GR				

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:PERFORM REMEDIAL WORKPLUG AND ABANDONTEMPORARILY ABANDONCHANGE PLANSPULL OR ALTER CASINGMULTIPLE COMPLDOWNHOLE COMMINGLE	SUBSEQUENT REPORT OF:   REMEDIAL WORK ALTERING CASING   COMMENCE DRILLING OPNS. P AND A   CASING/CEMENT JOB A
OTHER:	OTHER: completion - SWD

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/25/2012 -5/18/2012

RU/ TIW w/ 4-3/4" bit, collars and workstring. Drill out cement from 5840' thru DV tool at 6500', continue to drill collar at 11,320' and out shoe at 11,364'. Circulated and cleanout 5-1/2" casing and open hole to 11,700', POOH with bit and work string. RU Wireline and run CBL and Compensated Neutron log. Set 4" liner form 11,288' to 11,520', cement with 25 sacks cmt. GIH with 3-1/2" plastic coated tubing and packer. Set packer at 11,443'. Acidize open hole with 3500 gallons of 15% HCL. Test casing to 520 psi for 30 minutes, held OK. Nipple Up Tree. Install surface facilities and flowline, commence SWD operations.

Test: 5/18/2012 - 5,000 BWPD.

Spud Date:	4/25/2012	Rig Release Date:	5/18/20112	
I hereby certify	that the information above is true ar	nd complete to the best of my	/ knowledge and belief.	
SIGNATURE	Dan Playone	V.P. Explor	ation & Production	6/4/2012 DATE
Type or print na		dpla E-mail address:	isance@paladinenergy.com	PHONE:
For State Use (	- 4/ //	TITLE DIST.	, V <del>QT</del>	DATZ-31-20/Z
Conditions of A	swDex309			JUL -3-1 2012

