All Gon		en 0					
	UNITED STATES		BS OCD	(ORM APPROVED DMB No. 1004-0137 pires. October 31, 2014		
SUNDRY N Do not use this f	IOTICES AND REPORTS form for proposals to dril Use Form 3160-3 (APD) f	ON WELLS	4 2012 NM 6. If N/A	NM67111 M67111	r Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. N/A			
1. Type of Well Oil Well Gas Well Other				8. Well Name and No. GERONIMO FEDERAL #10			
2. Name of Operator WAGNER OIL COMPANY				9. API-Well No: 30-025-31533			
3a. Address 500 COMMERCE, SUITE 600 FORT WORTH, TEXAS 76102	one No. (include area code 35-2222	ТО	10. Field and Pool or Exploratory Area TONTO, S. (YATES/7 RIVERS)				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660' FNL & 1575' FWL OF SECTION 31, T 19 S, R 33 E UNIT C				11. County or Parish, State LEA COUNTY, NEW MEXICO			
	K. THE APPROPRIATE BOX(ES)	TO INDICATE NATURE (OF NOTICE, R	EPORT OR OTHE	ER DATA		
TYPE OF SUBMISSION TYPE OF ACTI							
Notice of Intent	Acidize	Deepen Fracture Treat	Production Reclamation	(Start/Resume)	Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair	New Construction Plug and Abandon Plug Back	Recomplet Temporari Water Disp	y Abandon	Other Workove	r	
testing has been completed. Final <i>A</i> determined that the site is ready for Pull rods, tbg and pump Make bit and scraper run to 3140' +/ Perforate 5 1/2" csg at 3098' - 3104' RIH w/ 2 3/8" tbg and set anchor @ Swab test to evaluate Put well to production	- and 2936' - 2956'	SEE ATTA	CHED I			itor _{tu} as	
14. I hereby certify that the foregoing is tr	ue and correct. Name (Printed/Typed)			· · · · · · · · · · · · · · · · · · ·			
Sabrina Bonner	Title Regulatory	Title Regulatory Analyst					
Signature Sabur	a Barner	Date 05/02/2012	2	APP	ROVED		
	THIS SPACE FOR I	FEDERAL OR STA	TE OFFICE	USE			
Approved by Conditions of approval, if any, are attached that the applicant holds local or contable to entitle the applicant to conduct operators	which would Office		WESLEY PETROLE	1 0 2012 ate W. INGRAM UM ENGINEER			
Title 18 U.S.C. Section 1001 and Title 43 U fictitious or fraudulent statements or repres			willfully to mak	e to any department	or agency of the United S	tates any false,	

(Instructions on page 2)

.

.



Conditions of Approval

Wagner Oil Company Geronimo Federal - 10 API 30-025-31533 August 10, 2012

- 1. Notify Hobbs BLM 575-393-3612 a minimum of 24 hours prior to commencing workover procedures. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 2. Due to well's location in R-111-P potash and the lack of a salt protection string, operator shall perform a BLM PET witnessed (charted) casing integrity test by setting a plug within 100' of the top perforation and testing to 500 psi for 30 minutes. Pressure leakoff may require remediation before continuing the workover. Include a copy of the chart in the subsequent sundry for this workover.
- 3. Surface disturbance beyond the existing pad shall have prior approval.
- 4. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 5. Functional H_2S monitoring equipment shall be on location.

, ^{iz},

- 6. A minimum of 2000 (2M) BOPE is to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Submit a (Sundry Form 3160-5) subsequent report (daily reports) describing all wellbore activity and Mechanical Integrity Test. Include the date(s) of the well work, and the setting depths of equipment. Include current wellbore schematic.
- 9. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.
- 10. Operator shall perform a 72 hour well test using an independent tester to determine if the well can produce in paying quantities.

11. BLM has no record of the CIBP set above the Seven Rivers perforation. The BLM completion report showed all perforations open, but the report to NMOCD for transport approval showed only the Yates perforations. Submit documentation for BLM files.

PRS/WW1 081012

. ٩.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

٠.

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.