

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

HOBBS OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

AUG 16 2012

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-025-26891 ✓
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> FED
2. Name of Operator LINN OPERATING, INC.		6. State Oil & Gas Lease No.
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002		7. Lease Name or Unit Agreement Name SCHARB 4 ✓
4. Well Location Unit Letter _____ M; 660 feet from the _____ S line and _____ 660 feet from the _____ W line Section 04 Township 19S Range 35E NMPM LEA County		8. Well Number: 001 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,866'		9. OGRID Number 269324
		10. Pool name or Wildcat SHARB;BONE SPRING ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU plugging equipment. ND wellhead NU BOP.
- RIH with tbg set 5 1/2 CIBP and set @ 9500' / 25 sx cement on top. Circulate hole w/ 200 bbls mud laden fluid.
- POH to 7600'. Spot 25 sx cement plug @ 7600-7347.
- POH to 6520'. Spot 25 sx cement plug @ 6520-6267'. (across casing patch and dv tool) WOC & Tag
- POH to 4055'. Spot 25 sx cement plug @ 4055-3802'. (8 5/8 shoe) WOC & Tag.
- POH to 2400'. Spot 25 sx cement plug @ 2400-2147. (Base of Salt) WOC & Tag.
- POH w/ tbg. Perf @ 1450. Set packer and Sqz 75 sx and Displace to 1350. WOC & Tag
- POH w/ tbg. Perf @ 474'. Set packer and Sqz +/-100 sx to surface. WOC and Verify cement at surface.
- Rig down. Cut off wellhead and weld on Dry Hole Marker. Move off.

Spud Date:

Rig Release

The Oil Conservation Division Must be notified
24 hours prior to the beginning of plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Terry Callahan

TITLE: REGULATORY SPECIALIST III DATE AUGUST 14, 2012

Type or print name TERRY B. CALLAHAN

E-mail address: tcallahan@linnenergy.com

PHONE: 281-840-4272

For State Use Only

APPROVED BY:

Mary Brown

TITLE

Compliance Officer

DATE

8/20/2012

Conditions of Approval (if any):

AUG 20 2012

Proposed Wellbore Schematic

Well Name: SCHARB 4 #001
 Location: M-04-19S-35E 660 FSL 660 FWL
 Lea County, NM 32.68369 -103.46856
 API #: 30-025-26891
 Elevations: GROUND: 3866'
 KB: 3877'
 Depths (KB): PBDT 10574'
 TD 10706'

Date Prepared: 31-Oct-11 D. Gonzales
 Last Updated: 13-Aug-12 J Charbonneau
 Spud Date: 7/18/80
 RR Date:
 Spud Date to RR Date:
 Completion Start Date:
 Completion End Date: 13-Sep-80
 Completion Total Days:
 Co-ordinates:

