Submit 1 Copy To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natural Resources			October 13, 2009
1625 N. French Dr., Hobbs, NM 88240	acd	20.0	LL API NO. 025-10690	
District II District III District III District III District III District III 1220 South St. Francis Dr.		$\frac{11}{5}$ In $\frac{1}{5}$ In	5. Indicate Type of Lease	
District III 1220 South St. Francis Dr.		is Dr.		EE 🛛 🗸
1000 Rio Brazos Rd, Aztec, NM 87410 1 5 2012 District IV Santa Fe, NM 87505		05 6. S	State Oil & Gas Lease N	
1220 S. St. Francis Dr., Santa Fe, NM			307841	
87505 SUNDRY NORCO	AND REPORTS ON WELLS	7. 1	Lease Name or Unit Agr	eement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR TO DEEPEN OR PLUG	BACK TO A	74404 1 1411114 01 011114 1 1 1 1 1 1 1 1	
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		JIXI	ELLY PENROSE B UN	NIT/ V
1. Type of Well: Oil Well Gas Well Other		8. V	Well Number 060	
2. Name of Operator		9. 0	OGRID Number 01244	14
PROVIDENCE ENERGY SERVICES, INC. dba KELTON OPERATING				/
3. Address of Operator			10. Pool name or Wildcat	
P.O. BOX 928, ANDREWS, TEXAS 79714-0928		LAN	NGLIE MATTIX (3724	0)
4. Well Location				
Unit Letter <u>M</u> : 660 feet from the SOUTH line and 660 feet from the WEST line ✓				
Section 9 Township 23S Range 37E NMPM LEA County				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	3391' GR			
		237.1	0.1 7	
12. Check A	ppropriate Box to Indicate Nat	ure of Notice, Repo	ort or Other Data	
NOTICE OF INT	TENTION TO:	SUBSEO	UENT REPORT ()F∙
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐				
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB CASING/CEMENT JOB				
DOWNHOLE COMMINGLE				
				5 →2
OTHER: TO THE REturn Well To Active Production Status				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
proposed completion of recompletion.				
07/16/2012				
1. Moved in Pulling Unit. NU BOP. Run in hole with bit, collars and tubing. Tagged cement at 3634'. Test casing to 500# -				
good. Drilled out cement. Tag plug at 3469. Drill out plug. Clean hole out to 3663' and circulated hole clean. Pulled bit,				
tools and tubing out of hole.				
07/17/2012 2. Run 116 joints tubing. ND BOP. Flange up well head. Run pump, $102 - \frac{3}{4} + 39 - \frac{7}{8}$ rods. Hang well on.				
07/19/2012				
3. Install Panel and electrical lines.				
8/9/2012				
4. Install new flow line. Set pumping unit. Hook up electricity and turn well on. Pumping well to clean up and test.				
OCD Condition of Approval:				
After remedial work has been done Forms red				
 C-103 Subsequent Report with dates and the C-104 with transporter(s), perfs producing from 		:		
& 24 hour production test	, the sign of the depart		, ,	
	1			The state of
I hereby certify that the information a	bove is true and complete to the best	of my knowledge and	belief.	no Pit
	V. A. BORGU	> F2 1/F	D. 4 TO E . 4	. 10. 0010
SIGNATURE	TITLE PRESI	DEN I	DATE_Augu	ist 13, 2012
		•		
Type or print name <u>C. Dale Kelton</u>	E-mail address: prov	idenceenergv@suddenl	ink.net PHONE: 432	2-661-1364
For State Use Only				
The lattille Counting office of 20 30 10				
APPROVED BY:	MANN TITLE COMP	uduce Utticer	DATE DATE	-62-6012
Conditions of Approval (if any):	1			- 2010

AUG 2 2 2012

Kelton Operating Corporation - WELL DIAGRAM

